

Appendix C: Photographs



Photograph 1: Photograph looking north along the northbound lanes of U.S. Route 169 toward Northwest Barry Road overpass. The excavation in the median contains the damaged pipeline. (Source: Staff)



Photograph 2: Photograph of tapping and line stop fitting affixed to the pipeline on the west side of U.S. Route 169. (Source: Staff)



Photograph 3: Photograph of the damaged section of pipeline looking northeast. The red arrow (added by Staff) points to a repair clamp surrounding the damaged portion of the pipeline. (Source: Staff)



Photograph 4: Photograph of the damaged portion of the pipeline looking southeast. A repair clamp is surrounding the damaged portion of the pipeline. (Source: Staff)



Photograph 5: Photograph of the damage to the pipeline. (Source: Staff)



Photograph 6: Photograph of the damage to the pipeline. (Source: Staff)