

Order: TGPR 100000180136 1Y Annual Heat trace testing

1Y Annual Heat trace testing

Christian has Newtron coming out to test all heat trace, trouble shoot circuit 5 on top of the HRSG, and install permanent heat trace in all spots that are using extension cords. Duct burner skid, blowdown tank, under HRSG door 3ish, south side of HRSG on 2nd floor, and multiple locations on top of HRSG. Tom Jones will follow up and install insulation around these areas as well.

No date set for work, PO has been sent. CR 9/16/24

Newtron tested heat trace after installing new heat trace. No issues found. Circuit 5 tested OK. CR 10-31-24

Sys.Status: CLSD MANC NMAT PRC SETC RCOM

HeaderData Operations Components Costs Partner Objects Additional Data Loca

Person responsible

PlannerGrp: 020 / : 5165 LU Empire Thermal

Notifctn: 100000446553

Mn.wk.ctr: THERMAL / : 5165 Empire Thermal Riverton

Costs: 0.00

Person respons.:

PMActType: 615 Inspectio

SystCond.:

Address:

Dates

Bsc start: 04/30/2024 00:00

Priority: 30 Days

Basic fin.: 05/30/2024 00:00

Revision:

Reference object

Func. Loc.: GN-T-RIVR-PB03-HRSG

HRSG Enclosure, Structure, & Stack

Equipment: 21023791

Unit 12-2 Heat Trace Panel HTP-1000

Assembly:

Malfctn data Damage Notif. dates

Malf.Start: 09/16/2024 16:40:11

Breakdown

Save Cancel