

Order: TGCR 0000512445 REPAIR GAS TURBINE ENCLOSURE HEATERS

Gas Turbine- NE not working-Fan is Locked up. Looking into parts or replacement of heater. 10/17/2025 ROL
Gas Turbine Generator South- Fan has bad bearings Needs fan replaced. 10/17/2025 ROL
Gas Turbine Hydraulic oil-Unit operates properly 10/17/2025 ROL

In processo of ordering new heaters to replace the units in the generator and GT enclosures. 10/23/2025 ROL Replaced both heaters and returned them to service 11/15/2025 ROL

Sys.Status: CLSD GMPS JBFI NMAT PRC SETC RCOM

HeaderData Operations Components Costs Partner Objects Additional Data Location Planning Control Enhancement

Person responsible

PlannerGrp: 020 /: 5165 LU Empire Thermal
Mn.wk.ctr: THERMAL /: 5165 Empire Thermal Riverton
Notifctn: 100000923000
Costs: 0.00 USD
PMActType: 014 Repair
SystCond.:
Address:

Dates

Bsc start: 10/15/2025 16:03 Priority: 4 60 Days
Basic fin.: 01/14/2026 16:03 Revision:

Reference object

Func. Loc.: GN-T-RIVR-PB03-GC01-... Structures
Equipment: 21023168 Unit 12 Turbine Enclosure