

Order: TGCR 0000511101 REPAIR STEAM TURBINE BUILDING HEATERS

REPAIR STEAM TURBINE BUILDING HEATERS
This work order is a result of the NERC building heater check pm.
During inspection the following heaters were found not working at all or not working:
12BSA-UH-2025- Fan works but no heat.
12BSA-UH-1001- Not working.
12BSA-UH-1007- Not working.
12BSA-UH-1009- Not working.
Info for work order provided by R Lewis 10/12/2025

Sys.Status: CLSD GMPS JBFI NMAT PRC SETC RCOM

HeaderData Operations Components Costs Partner Objects Additional Data Location Planning Control Enhancement

Person responsible

PlannerGrp: 020 / 5165 LU Empire Thermal
Mn.wk.ctr: THERMAL / 5165 Empire Thermal Riverton
Person respons.:
Notifctn: 100000919975
Costs: 0.00 USD
PMActType: 014 Repair
SystCond.:
Address:

Dates

Bsc start: 10/14/2025 05:11 Priority: 3 30 Days
Basic fin.: 11/26/2025 05:11 Revision:

Reference object

Func. Loc.: GN-T-RIVR-PB03-ST01-... Structures
Equipment: 21025436 12 2 HVAC

Notification is completed -> can only be displayed View Details

Save Cancel