



Laclede ISRS Cast Iron Replacement



OPC ISRS Cast Iron Replacement



Laclede Exhibit No. 6
 Date 01-03-17 Reporter *F
 File No. GO-2016-0332
GO-2016-0333

FILED²

JAN 5 2017

Missouri Public Service Commission

* OPC Version does not account for the extra cost to connect caused by the fact that the original cast iron tends to be in the street, while the new plastic is being placed under the grassy side of the curb.

Cost



ISRS Recovery



Main Install vs. Replace

NINE WORK ORDERS IDENTIFIED BY OPC



In Feet	Effect on ISRS
43,833	↑
44,598	↓
8,817	↓