FILED May 11, 2016 Data Center Missouri Public Service Commission

Missouri Qas Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prol. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Accum, Dept	Depr Expense
380200-Services - Plastic & Copper	20401050360	003816	BWO SERVICE LINE LEAK RESPONSIVE	F0558	SLRP - Immediate response - company	Addition	Blanket WO	201509	86,708.75	7	0.00223333	1,355.54	2,323.79
380200-Services - Plastic & Copper	20401050360	003816	BWO SERVICE LINE LEAK RESPONSIVE	P0558	SLRP - immediate response - company	Addition	Blanket WO	201510	2,003.40	6	0.00223333	26.85	53.69
380200-Services - Plastic & Copper	20401050360	003816	BWO SERVICE LINE LEAK RESPONSIVE	F0558	SLRP - immediate response - company	Addition	Blanket WO	201511	(4,137.63)	5	0.00223333	(46.20)	(110.89)
380200-Services - Plastic & Copper	20401050360	003816	BWO SERVICE LINE LEAK RESPONSIVE	F0558	SLRP - Immediate response - company	Addition	Blanket WO	201512	(2,953.81)	4	0.00223333	(26.39)	[79.16]
380200-Services - Plastic & Copper	20401050372	003818	BWO SERVICE REPL BLOCK CONTRACTOR S	F0568	SLRP - block by block - contract	Addition	Blanket WO	201509	476,619.53	7	0.00223333	7,451.14	12,773.38
380200-Services - Plastic & Copper	20401050372	003818	BWO SERVICE REPL BLOCK CONTRACTOR S	F05G8	SLRP - block by block - contract	Addition	Blanket WO	201510	499,624.63		0.00223333	6,694.96	13,389.92
380200-Services - Plastic & Copper	20401050372	003818	BWO SERVICE REPL BLOCK CONTRACTOR S	F0568	SLRP - block by block - contract	Addition	Blanket WO	201511	302,009,45		0.00223333	3,372.43	8,093.84
380200-Services - Plastic & Copper	20401050372	003818	BWO SERVICE REPL BLOCK CONTRACTOR S	FOSG8	SLRP - block by block - contract	Addition	Blanket WO	201512	181,546.04		0.00223333	1,621.81	4,865.43
380200-Services - Plastic & Copper	20801050372	003819	BWO SERVICE LINE REPL BLOCK CONTRAC	F0552	SLRP - block by block - contract	Addition	Blanket WO	201509	12,844.81	,	0.00223333	200.81	344,24
380200-Services - Plastic & Copper	20801050372	003819	BWO SERVICE LINE REPL BLOCK CONTRAC	F0552	SLRP - block by block - contract	Addition	Blanket WO	201510	8,060.87		0.00223333	108.02	216.03
380200-Services - Plastic & Copper	20801050372	003819	BWO SERVICE LINE REPLIBLOCK CONTRAC	F0552	SLRP - block by block - contract	Addition	Blanket WO	201511	(531.73)		0.00223333	(5.94)	(14.25)
380200-Services - Plastic & Copper	20801050372	003819	BWO SERVICE LINE REPL BLOCK CONTRAC	F0552	SLRP - block by block - contract	Addition	Blanket WO	201512	(211.66)		0.00223333	(1.89)	(5.67)
380200-Services - Plastic & Copper	20801050361	003823	BWO SERVICE LINE REPL MODIFIED BLOC	F0522	SLRP - modified black by black - co	Addition	Blanket WO	201509	(267.19)		0.00223333	(4.18)	(7.16)
382000 Meter Installations-MGE	20901050363	003825	BWO SLRP MTR/REG REPL COMPANY	F0516	SLRP - meter & regulator replacemen	Addition	Blanket WO	201509	1,663.60		0.00203333	23.68	40.59
382000 Meter Installations-MGE	20901050363	003825	BWO SLRP MTR/REG REPL COMPANY	F0516	SLRP - meter & regulator replacemen	Addition	Blanket WO	201510	5,681,44		0.00203333	69.31	138.63
382000 Meter Installations-MGE	20901050363	003825	BWO SLRP MTR/REG REPL COMPANY	F0516	SLRP - meter & regulator replacemen	Addition	Blanket WO	201511	3,390.14		0.00203333	34.47	82.72
382000 Meter Installations-MGE	20901050363	003825	BWO SLRP MTR/REG REPL COMPANY	F0516	SLRP - meter & regulator replacemen	Addition	Blanket WO	201512	3,711.04		0.00203333	30.18	90.55
380200-Services - Plastic & Copper	20401050309	003927	BWO LINE LOCATES-REPL SERVICES ONLY	F0655	Service line locates	Addition	Blanket WO	201509	(0.22)		0.00223333		(0.01)
380200-Services - Plastic & Copper	20801050360	003929	BWO SERVICE LINE LEAK RESPONSIVE CO	F0520	SLRP - immediate response - company	Addition	Blanket WO	201509	(65,96)		0.00223333	(1.03)	(1.77)
382000 Meter Installations-MGE	20801050373	003930	BWO MTR/REG SET REPL CONTRACTOR-SLR	F0652	SLRP - meter & regulator replacemen	Addition	Blanket WO	201509	1,485.27	-	0.00203333	21.14	36.24
382000 Meter Installations-MGE	20801050373	003930	BWO MTR/REG SET REPL CONTRACTOR-SLR	F0652	SLRP - meter & regulator replacemen	Addition	Blanket WO	201510	2,135.64		0.00203333	2G.05	52.11
382000 Meter Installations-MGE	20801050373	003930	BWO MTR/REG SET REPL CONTRACTOR-SLR	F0652	SLRP - meter & regulator replacemen	Addition	Blanket WO	201511	(713.65)	- 4	0.00203333	(7.26)	(17.41)
382000 Meter Installations-MGE	20801050373	003930	BWO MTR/REG SET REPL CONTRACTOR-SLR	F0652	SLRP - meter & regulator replacemen	Addition	Blanket WO	201512	(44.65)		0.00203333	(0.36)	(1.09)
382000 Meter installations-MGE	20901050373	003931	BWO-Repl Mtr Sets (SLRP) - South	F0535	BWO Mtr/Reg Repl - SLRP ISRS (S)	Addition	Blanket WO	201509	25,739.18		0.00203333	366.35	628.04
382000 Meter Installations-MGE	20901050373	003931	BWO-Repl Mtr Sets (SLRP) - South	F0535	BWO Mtr/Reg Repi - SLRP ISRS (S)	Addition	Blanket WO	201510	8,494.40	- 1	0.00203333	103.63	207.26
382000 Meter Installations-MGE	20901050373	003931	BWO-Repl Mtr Sets (SLRP) - South	F0535	BWO Mtr/Reg Repl - SLRP ISRS (S)	Addition	Blanket WO	201511	7,336.83		0.00203333	74.59	179.02
382000 Meter Installations-MGE	20901050373	003931	BWO-Repl Mtr Sets (SLRP) - South	F0535	BWO Mtr/Reg Repl - SLRP ISRS (S)	Addition	Blanket WO	201512	10,405.67		0.00203333	84.63	253.90
380200-Services - Plastic & Copper	20401050361	003932	BWO SERVICES REPL MODIFIED BLOCK CO	F048G	SLRP - modified block by block - co	Addition	Blanket WO	201509	18,371.14		0.00223333	287.20	492.35
380200-Services - Plastic & Copper	20401050361	003932	BWO SERVICES REPL MODIFIED BLOCK CO	F0486	SLRP - modified block by block - co	Addition	Blanket WO	201510	7,149.34		0.00223333	95.80	191.60
380200-Services - Plastic & Copper	20401050361	003932	BWO SERVICES REPL MODIFIED BLOCK CO	F0486	SLRP - modified block by block - co	Addition	Blanket WO	201511	15,672.74	/ <u>_</u>	0.00223333	175.01	420.03
380200-Services - Plastic & Copper	20401050361	003932	BWO SERVICES REPL MODIFIED BLOCK CO	F0486	SLRP - modified block by block - co	Addition	Blanket WO	201512	11,319.90	- 1	0.00223333	101.12	303.37
380200-Services - Plastic & Copper	20801050367	003935	BWO MATERIAL SERV LINE REPL COMP	F0637	SLRP - materials - company crews	Addition	Blanket WO	201509	5,691.02		0.00223333	88.97	152.52
380200-Services - Plastic & Copper	20501050370	003937	BWO SERVICE LINE REPL CONTRACTOR	F057G	SLRP - immediate response - contrac	Addition	Blanket WO	201509	(3.64)		0.00223333	(0.06)	(0.10
380200-Services - Plastic & Copper	20501050372	003972	BWO SERVICE LINE REPL BLOCK CONTRAC	F0624	SLRP - block by block - contract	Addition	Blanket WO	201509	3,671.65	1	7 0.00223333	57.40	98.40
380200-Services - Plastic & Copper	20501050372	003972	BWO SERVICE LINE REPL BLOCK CONTRAC	F0624	SLRP - black by black - contract	Addition	Blanket WO	201510	94.65		0.00223333	1.27	2.54
380200-Services - Plastic & Copper	20501050372	003972	BWG SERVICE LINE REPL BLOCK CONTRAC	F0624	SLRP - block by block - contract	Addition	Blanket WO	201511	(3,957.00)		0.00223333	(44.19)	(106.05
380200-Services - Plastic & Copper	20501050372	003972	BWO SERVICE LINE REPL BLOCK CONTRAC	F0624	SLRP - block by block - contract	Addition	Blanket WO	201512	113.40		0.00223333	1.01	3.04
382000 Meter Installations-MGE	20401050373	003974	BWO-Repl Mtr Set (SLRP) - North	F0543	BWO Mtr/Reg Repl - SLRP ISRS (N)	Addition	Blanket WO	201509	95,286.61		0.00203333	1,356.25	2,324.99

Missouri Clas Energy - MCE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016.

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Proj. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Door Mo. Rate	Accum, Dept	Deer Expense
382000 Meter Installations-MGE	20401050373	003974	BWO-Repl Mtr Set (SLRP) - North	F0543	BWO Mitr/Reg Rept - SLRP ISRS (N)	Addition	Blanket WO	201510	114,443,57	6	0.00203333	1,396.21	2,792.4
382000 Meter Installations-MGE	20401050373	003974	BWO-Repl Mtr Set (SLRP) - North	F0543	BWO Mitr/Reg Repl - SLRP ISRS (N)	Addition	Blanket WO	201511	41,749.98	5	0.00203333	424,45	1,018.7
382000 Meter Installations-MGE	20401050373	003974	BWO-Repl Mtr Set (SLRP) - North	F0543	BWO Mtr/Reg Repl - SLRP ISRS (N)	Addition	Blanket WO	201512	10,846,49	4	0.00203333	88,22	264.6
380200-Services - Plactic & Copper	20501050361	003975	BWO SERVICE LINE REPL MODIFIED BLOC	F0494	SLRP - modified block by block - co	Addition	Blanket WO	201509	1.17	7	0.00223333	0.02	0.0
380200-Services - Plastic & Copper	20901050361	003976	SWO SERVICE LINE REPL MODIFIED BLOC	F0515	SLRP - modified block by block - co	Addition	Blanket WO	201509	(30.66)	7	0.00223333	(0.48)	(0.8
380200-Services - Plastic & Copper	20901050362	003979	BWO SERVICE LINE REPL BLOCK COMPANY	F0627	SLRP - block by block - company cre	Addition	Blanket WO	201509	14,49	7	0.00223533	0.23	0.3
380200-Services - Plastic & Copper	20901050372	004146	BWO SERVICE LINE REPL BLOCK CONTRAC	F0650	SLRP - block by block - contract	Addition	Blanket WO	201509	6,963.76	7	0.00223333	108.87	186.6
380200-Services - Plastic & Copper	20901050372	004146	BWO SERVICE LINE REPL BLOCK CONTRAC	F0650	SLRP - block by black - contract	Addition	Blenket WO	201510	37,933,22	6	0.00223333	508,30	1,016.6
380200-Services - Plastic & Copper	20901050372	004146	BWO SERVICE LINE REPL BLOCK CONTRAC	FOGSO	SLRP - block by block - contract	Addition	Blanket WO	201511	2,265.09	5	0.00223333	25.29	60.7
380200-Services - Plastić & Copper	20901050372	004146	BWO SERVICE LINE REPL BLOCK CONTRAC	F0650	SLRP - block by block - contract	Addition	Blanket WO	201512	1,874.81	4	0.00223333	16.75	50.24
380200-Services - Plastic & Copper	20501050377	004148	BWO MATERIAL SERV LINE REPL CONT	F0517	SLRP - materials - contract	Addition	Blanket WO	201509	693.68	7	0.00223333	10.84	18.5
380200-Services - Plastic & Copper	20401050370	004150	8WO SERVICE LINE REPL CONTRACTOR SL	F0559	SLRP - Immediate response - contrac	Addition	Blacket WO	201509	8,988.74	7	0.00223333	140,52	240.9
380200-Services - Plastic & Copper	20401050370	004150	BWO SERVICE LINE REPL CONTRACTOR SL	F0559	SLRP - Immediate response - contrac	Addition	Blanket WO	201511	(2,481.06)	5	0.00223333	(27.71)	(66.4
380200-Services - Plastic & Copper	20401050370	004150	BWO SERVICE LINE REPL CONTRACTOR SL	FGS59	SLRP - Immediate response - contrac	Addition	Blanket WO	201512	1,090,44	- 4	0.00223333	9.74	29.2
380200-Services - Plastic & Copper	20401050301	004152	BWO-Repl Svc w/ Pls (North Reg)	F0608	BWO Service Line Repl - ISRS (N)	Addition	Blanket WO	201509	219,111.83	- 7		3,425.44	5,872.1
380200-Services - Plastic & Copper	20401050303	004152	BWO-Repl Svc w/ Pls (North Reg)	F0608	BWO Service Line Repl - ISRS (N)	Addition	Blanket WO	201510	169,113.56	B		2,266.12	4,532.3
380200-Services - Plastic & Copper 380200-Services - Plastic & Copper	20401050301	004152	BWO-Repl Svc w/ Pls (North Reg) BWO-Repl Svc w/ Pls (North Reg)	F0608	BWO Service Line Repl - ISRS (N) BWO Service Line Repl - ISRS (N)	Addition	Blanket WO Blanket WO	201511	74,543.80 43,679.82	5		832.40 390.21	1,997.7
380200-Services - Plastic & Copper	20901050301	004153	BWO-Repl Svc w/ Pla (North Reg)	F0513	SWO Service Line Repl - ISRS (N)	Addition	Blanket WO	201512	39,G73,34	7		620.23	1,063.2
380200-Services - Plastic & Copper	20901050301	004153	BWO-Repi Svc w/ Pls (South Reg)	F0513	aWO Service Line Repl - ISRS (S)	Addition	Blanket WO	201510	86,684,93	6		1,161.58	2,323,
380200-Services - Plastic & Copper	20901050301	004153	BWO-Rep Svc w/ Pls (South Reg)	F0513	BWO Service Line Repl - ISRS (S)	Addition	Blanket WO	201511	71,033.92	5		793,21	1,903.7
380200-Services - Plastic & Copper	20901050301	004153	8WO-Repl Svc w/ Pls (South Reg)	F0513	BWO Service Line Repi - ISRS (S)	Addition	Blanket WO	201512	58,898,14	4	0.00223333	526.16	1,578,4
380200-Services - Plastic & Copper	20401050377	004279	BWO SERVICE LINE MATERIAL CONTRACTO	F0586	SURP - materials - contract	Addition	Blanket WO	201509	(8.00)	7	0.00223333	(0.13)	(0.5
380200-Services - Plastic & Copper	20401050377	004279	BWO SERVICE LINE MATERIAL CONTRACTO	FOSBG	SLRP - materials - contract	Addition	Blanket WO	201512	117.00	4	0.00223333	1.05	3.3
382000 Meter Installations-MGE	20401050363	004282	BWO REPL MTR/REG SETTING COMPANY SL	F0583	SLRP - meter & regulator replacemen	Addition	Blanket WO	201509	1,732.15	7	0.00203333	24.65	42.7
382000 Meter Installations-MOL	20401050363	004282	BWO REPL MTR/REG SETTING COMPANY SL	F0583	SLRP - meter & regulator replacemen	Addition	Blanket WO	201510	2,789.65	6	0.00203333	34,03	68.0
382000 Meter Installations-MGE	20401050363	004282	BWO REPLIMTR/REG SETTING COMPANY SL	F0583	SLRP - meter & regulator replacemen	Addition	Blanket WO	201511	4,583.70	5	0,00203333	46.60	111.0
382000 Meter Installations-MGE	20401050363	004282	BWO REPLIMTR/REG SETTING COMPANY SL	FOSRS	SURP - meter & regulator replacemen	Addition	Blanket WO	201512	2,888.71		0,00203333	23.49	70.4
380200-Services - Plastic & Copper	20901050377	004287	BWO MATERIAL SERV LINE REPL CONT	50607	SLRP - materials - contract	Addition	Blanket WO	201509	52,023,10	7		B13.29	1,394,2
380200-Services - Plastic & Copper	20901050377	004287	8WO MATERIAL SERV LINE REPL CONT	F0607	SLRP - materials - contract	Addition	Slanket WO	201510	5,498.95	6		73.69	147.5
											7		
380200-Services - Plastic & Copper	20901050377	004287	BWO MATERIAL SERV LINE REPL CONT	F0607	SLRP - materials - contract	Addition	Blanket WO	201511	157.70	-	0,00223333	1.76	4.3
380200-Services - Plastic & Copper	20901050377	004287	BWO MATERIAL SERV LINE REPL CONT	FQ607	SLRP - materials - contract	Addition	Blanket WO	201512	3,499,35	- 4	0,00223333	31.26	99,7
380700-Services - Plastic & Copper	20501050301	004288	BWO-REPLACE SERVICE	FQ541	Replace existing protected steel, p	Addition	Blanket WO	201509	6,028.23	7	0.00223333	94.24	161.5
380200-Services - Plestic & Copper	20501050301	004288	BWO-REPLACE SERVICE	F0541	Replace existing protected steel, p	Addition	Blanket WO	201511	(556.42)	5	0.00223333	(6,21)	(14.5
380200-Services - Plastic & Copper	20501050301	004288	BWO-REPLACE SERVICE	F0541	Replace existing protected steel, p	Addition	Blanket WO	201512	574.13	- 4	0.00223333	5,13	15.
380200-Services - Plastic & Copper	20801050362	004407	BWO SERVICE LINE REPL BLOCK COMPANY	F0594	SURP - block by block - company cre	Addition	Blenket WO	201509	8,665.57		0.00223333	135.47	232.0
380200-Services - Plastic & Copper	20601050362	004407	BWO SERVICE LINE REPL BLOCK COMPANY	F0594	SLRP - block by block - company cre	Addition	Blanket WO	201511	(603.81)		0.00223333	(6.74)	(16.:
380200-Services - Plastic & Copper	20801050362	004407	SWO SERVICE UNE REPL BLOCK COMPANY	F0594	SLRP - black by black - company cre	Addition	Blanket WO	201512	42.61		0.00223333	0.3п	1
380200-Services - Plastic & Copper	20801050370	004413	BWO SERVICE LINE REPL CONTRACTOR SL	F0518	SLRP - Immediate response - contrac	Addition	Blanket WO	201509	(4.12		1	(0.06)	-
380200-Services - Plastic & Copper	20901050370	004414	8WO SERVICE LINE REPL CONTRACT-SLRP	F0555	SLRP - immediate response - contrac	Addition	Blankes WO	201509	5,750.43			89,90	
380200-Services - Plastic & Copper	20901050370	004414	BWO SERVICE LINE REPL CONTRACT-SERP	F0555	SLRP - immediate response - contrac	Addition	Blanket WO	201510	20,233.86		0.00223333	273.13	542.
				-		1-100		-	-	-	100		
380200-Services - Plastic & Copper	20901050370	004414	BWO SERVICE LINE REPL CONTRACT-SLRP	F0555	SLRP - immediate response - contrac	Addition	Blanket WO	201511	55,930.49		0,00223333	624,56	
380200-Services - Plastic & Copper 380200-Services - Plastic & Copper	20901050370 21001050301	004414 004416	BWO SERVICE LINE REPL CONTRACT-SLRP BWO-REPLACE SERVICE	F0555	SLRP - immediate response - contrac Replace existing protected steel, p	Addition	Blanket WO	201512	8,754.30 (863.66		0.00223333	78.20	

Missouri Cea Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for Jenuary and February 2018

Utility Account	MOE Work Order No.	New Work Order No.	Work Order Description	Evadina Prol. No.	Funding Protect Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rete	Accum, Dent	Depr Expense
380200-Services - Plastic & Copper	21001050301	004416	BWO-REPLACE SERVICE	F05G1	Replace existing protected steel, p	Addition	Blanket WO	201510	182.25		0.00229333	2.44	4.88
380700-Services - Plastic & Copper	21001050301	00441G	BWO-REPLACE SERVICE	FD5G1	Replace existing protected steel, p	Addition	Blanket WO	201511	(47.87)		0.00223333	(0.53)	(1.28
380200-Services - Plastic & Copper	21001050301	004416	BWO-REPLACE SERVICE	F0561	Replace existing protected steel, p	Addition	Blanket WO	201512	462.84	4	0.00223333	4.13	12,40
380200-Services - Plastic & Copper	20801050371	004492	BWO SERVICE LINE REPL MODIFIED BLOC	F0619	SLRP - modified block by block - co	Addition	Blanket WO	201509	287.68	7	0.00223333	4.50	7.73
380200-Services - Plastic & Copper	20801050371	004492	BWO SERVICE LINE REPL MODIFIED BLOC	FDG19	SLRP - modified block by block - co	Addition	Blanket WO	201510	1,555.31		0.00223333	20.84	41.68
380200-Services - Plastic & Copper	20801050371	004492	BWO SERVICE LINE REPL MODIFIED BLOC	F0619	SLRP - modified block by block - co	Addition	Blanket WO	201511	(6,58)		0.00223333	(0.07)	(0.18
360200-Services - Plastic & Copper	20801050371	004492	BWO SERVICE LINE REPL MODIFIED BLOC	F0619	SLRP - modified block by block - co	Addition	Blanket WO	201512	(47.59)	- 4	0.00223333	[0.43)	(1,28
382000 Meter installations-MGE	20501050363	004498	BWO SLRP MYR/REG REPL COMPANY	F0596	SLRP - meter & regulator replacemen	Addition	Blanket WO	201509	76.04	- 7	0.00203333	1.08	1.86
382000 Meter Installations-MGE	20501050363	004498	BWO SLRP MTR/REG REPL COMPANY	F0596	SLRP - meter & regulator replacemen	Addition	Blanket WO	201510	338.50	ė	0.00203333	4.13	8.26
382000 Meter Installations-MGE	20501050363	004498	BWO SLIP MTR/REG REPL COMPANY	F0596	SLRP - meter & regulator replacemen	Addition	Blanket WO	201511	356,57		0.00203333	3.63	8,70
382000 Meter Installations-MGE	20501050363	004498	BWO SLIP MTR/REG REPL COMPANY	P0596	SLRP - meter & regulator replacement	Addition	Blanket WO	201512	199.22		0.00203333	1.62	4.86
380200-Services - Plastic & Copper	20501050367	004499	BWO MATERIAL SERV LINE REPL COMP	F0526	SLAP - materials - company crews	Addition	Blanket WO	201509	(0.44)		0.00223333	(0.01)	(0.01
380200-Services - Plastic & Copper	20801050301	004501	8WO-Repl Suc w/ Pls (SW Reg)	F0659	BWO Service Line Rept - ISRS (SW)	Addition	Blanket WO	201509	44,471.17		0.00223333	695,23	1,191.83
380200-Services - Plastic & Copper	20801050301	004501	BWO-Repl Svc w/ Pls (SW Reg)	F0659	BWO Service Line Repl - ISRS (SW)	Addition	Blanket WO	201510	G2,720.88	- 1	0,00223333	840,46	1,680,92
380200-Services - Plastic & Copper	20801050301	004501	8WO-Repl Svc w/ Pla (SW Reg)	F0659	BWO Service Line Repl - ISRS (SW)	Addition	Blanket WO	201511	76,101.35		0.00223333	849.80	7,039.51
380200-Services - Plastic & Copper	20801050301	004501	BWO-Repl Svc w/ Pis (SW Reg)	F0659	BWO Service Line Repl - ISRS (SW)	Addition	Blanket WO	201512	39,275.64			350.86	1,052.59
380200-Services - Plastic & Copper	20901050360	004598	BWG SERVICE LINE LEAK RESPONSIVE CO	F0484	SLRP - immediate response - company	Addition	Blanket WO	201509	(48.36)	F = -53	0.00223333	(0.75)	(1.30)
									1,2,2,0			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,,,,,,
380200-Services - Plastic & Copper	20401050371	004599	BWO SERVICE REPL MODIFIED BLOCK CON	F05G7	SLRP - modified black by black - ca	Addition	Blanket WO	201509	(162.83)		0.00223333	(2,55)	(4.36
380200-Services - Plastic & Copper	20501050371	004600	BWG SERVICE LINE REPL MODIFIED BLOC	F0669	SLRP - modified block by block - co	Addition	Blanket WO	201509	(147.61)		0.00223333	(2.31)	(3.96)
		THE TRANSPORT OF THE PARTY OF T		- Innertake									
380200-Services - Plastic & Copper	20501050371	004600	BWO SERVICE LINE REPL MODIFIED BLOC	F0669	SLRP - modified block by block - co	Addition	BlanketWO	201510	2,021.93		0,00223333	27.09	54,19
380200-Services - Plastic & Copper	20501050371	004600	BWO SERVICE LINE REPL MODIFIED BLOC	F0669	SLRP - modified block by block - co	Addition	Blanket WO	201512	5,437.93		0.00223333	60.72	145.74
				7 1					37,10				2-9111
380200-Services - Plastic & Copper	20501050371	004600	BWO SERVICE LINE REPL MODIFIED BLOC	F0669	SLRP - modified block by block - co	Addition	Blanket WO	201512	782.20		0.00223333	6.99	20,96
380200-Services - Plastic & Copper	21001050371	004601	BWO SERVICE LINE REPL MODIFIED BLOC	F0591	SLRP - modified block by block - co	Addition	Blanket WO	201509	(0.50)		0.00223333	(0.01)	(0.01)
382000 Meter Installations-MGE	20501050373	004602	8WO-Repl Mtr Set (SLRP) - SWest	50629	8WO Mtr/Reg Repl - SLRP ISRS (SW)	Addition	Blanket Wo	201509	1,387.35		0.00203333	19.75	33,85
382000 Meter Installations-MGE	20501050373	004602	BWO-Repl Mtr Set (SLRP) - SWest	F0629	BWO Mtr/Reg Repl - SERP ISRS (SW)	Addition	Blanket WO	201510	2,613.58		0.00203333	31.89	63,77
382000 Meter Installations-MGE	20501050373	004602	BWG-Repl Mtr Set (SLRP) - SWest	F0629	BWO Mtr/Reg Repl - SLRP ISRS (SW)	Addition	Blanket WO	201511	2,306.05		0.00203333	25.44	56.27
382000 Meter Installations-MGE	20501050373	004602	BWO-Repl Mtr Set (SLRP) - SWest	F0629	BWO Mtr/Reg Repl - SLRP ISRS (SW)	Addition	Blanket Wo	201512	665.55		0.00203333	5,41	16,24
380200-Services - Plastic & Cooper	20201050367	004609	BWG MATERIAL SERV LINE REPL COMP	F0G49	SLRP - materials - company crews	Addition	Blanket WO	201509	6,653.93		0.00223333	104.02	178.33
380200-Services - Plastic & Copper	20901050367	004609	BWG MATERIAL SERV LINE REPL COMP	F0649	SLRP - materials - company crews	Addition	Blanket WO	201510	7,230.07	1	0.00223333	25.88	199.77
380200-Services - Plastic & Copper	20901050367	004609	BWG MATERIAL SERV LINE REPL COMP	F0649	SLRP - materials - company crews	Addition	Blanket WO	201511	4,541.69		0.00223333	50.72	121.72
380200-Services - Plastic & Copper	20901050367	004609	BWO MATERIAL SERV LINE REPL COMP	F0649	SLRP - materials - company crews	Addition	Blanket WO	201512	(179.92)		4 0.00223333	(1.61)	(4.82
376300-Mains - Plattic	#N/A	007052	BWO Main installed Mice-North Reg	F0599	Main Replacement - ISRS (N)	Addition	Blanket WO	201510	180,392.52		0.00148333	1,605,49	3,210.98
376300-Mains - Plastic	#N/A	007052	BWO Main installed Mice-North Reg	F0599	Main Replacement - ISRS (N)	Addition	Slanket WO	201511	1,506.80		0.00148333	11.18	26,82
376300-Mains - Plastic	#N/A	007052	BWO Main Installed Mtce-North Reg	F0599	Main Replacement - ISRS (N)	Addition	Blanket WO	201512	745.37		4 0.00148333	4,42	13.27
37G300-Mains - Plastic	MN/A	007003	BWO Mains installed Mice -South Reg	F0604	Main Replacement - ISRS (S)	Addition	Blanket WO	201510	20,238.01		6 0.00148933	180,12	360.24
376300-Mains - Piastic	JIN/A	007053	BWO Mains installed Mtce-South Reg	F0604	Main Replacement - ISRS (S)	Addition	Blanket WO	201511	93.13		5 0.00148333	0.69	1.66
376300-Mains - Plastic	#N/A	007053	BWO Mains installed Mice-South Reg	F0604	Main Replacement - ISRS (S)	Addition	Blanket WO	201512	5,017.27		4 0.00148333	29.77	89.31
376300-Mains - Plastic	#N/A	007054	BWO Mains installed Mtce-Southwest	F0604	Main Replacement - ISRS (S)	Addition	Blanket WO	201510	7,119.41		6 0,00148333		126.73
376300-Mains - Plastic	#N/A	007054	8WO Mains Installed Mtcr-Southwest	FOGO4	Main Replacement - ISRS (5)	Addition	Blanket WO	201511	150.00				2.67
376300-Mains - Plastic	#N/A	007054	BWO Mains Installed Mice-Southwest	F0604	Main Replacement - ISRS (S)	Addition	Blanket WO	201512	239.18		4 0,00148333		4.26
380200-Services - Plastic & Copper	N/A	009217	8WO-Replace Svc w/ Steel (North)	80803	BWO Service Line Repi - ISRS (N)	Addition	Blanket WO	201509	861.58		7 0.00223333		23.09
380200-Services - Plastic & Copper	N/A	009217	BWO-Replace Svc w/ Steel (North)	BODOS	BWO Service Line Repl - ISRS (N)	Addition	Blanket WO	201510	7,069.77		6 0.00223333		189.47
376200-Mains - Cast Iron	20401050325	003969	ENCAPSULATION CAST IRON JOINTS	F0524	8WO Cl Joint Encapsulation ISRS (N)	Addition	Encapsulation	201509	140,688.53		7 0.00148333	1,460.B1	2,504.25
37G200-Mains - Cast Iron	20401050325	003069	ENCAPSULATION CAST IRON JOINTS	F0524	BWO Ci Joint Encapsulation ISRS (N)	Addition	Encapsulation	201510	156,356.03		8 0.00148333		2,783.13
376200-Mains - Cast Iron	20401050325	003969	ENCAPSULATION CAST IRON JOINTS	F0524	BWO Cl Joint Encapsulation ISRS (N)	Addition	Encapsulation	201511	148,996.63		5 0.00148333		
376200-Mains - Cast Iron	20401050325	003969	ENCAPSULATION CAST IRON JOINTS	F0524	BWO Ci Joint Encapsulation ISRS (N)	Addition	Encapsulation	201512	151,371.11		0.00148333	898.13	2,694.40
37G100-Mains - Steel	20401132881	003789	18th & Locust Repl Cl w 500'-4in PC	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	266.08		7 0.00148333	2.76	4,74
376100-Mains - Steel	20401132881	003789	18th & Locust Repl Cl w 500"-din PE	F0509	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	480.08		6 6.00148333	4.27	8,55
37G100-Mains - Steel	20401132881	003789	18th & Locust Replict w 500'-4in PE	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	172,78	=	5 0.00146333	1.28	3.08
37G100-Mains - Steel	20401132881	003789	18th & Locust Repl Cl w 500'-4in PE	FOS99	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	(95,118.85)		4 0.00148333	(564.37)	(1,693.11

Missouri Das Ehergy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2010

Jillity Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prof. No.	Funding Protect Description	FERC Activity	Category	Month	Addition Amount	Months	Dapr Mo. Rate	Accum. Dept	Depr Expense
76300-Mains - Plastie	20401132881	003789	18th & Locust Repl CI w 500-4in PE	F0509	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	95,099.06		0.00148333	564,25	1,692.76
76300-Mains - Plastic	20503143406	003808	3rd & Arch Repl PBS w 2795'-4;745'-	F0544	Replace bare steel main - safety re	Addition	tSRS-Other	201509	[19.95]	7	0.00148333	(0.21)	(0.36
176300-Mains - Plastic	20902133172	003874	Gregory Heights Real PBS main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(108.81)	7	0.00148333	(1.13)	(1.94
178000-Meas & Reg Station Equipment	20401132773	004003	Relocate DRS 258 Mayfair	FoGoo	Station Rebuild & Repl ISRS (N)	Addition	ISRS-Other	201509	(1,455.90)	7	0.00238333	(24.29)	[41.64
176100-4/Jains - Steel	20501139125	004064	Rept I/O Piping DRS 0182C	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	2,67	-	0.00148333	0.03	0.04
376300-Mains - Plastic	20501133125	004064	Repl I/O Piping ORS 0182¢	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	0.49		0.00148333	0,01	6.01
376300-Meine - Plastic	20501133207	204051	15th & Indiana Repi PBS/PCS w 590'-	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(29,22)	3391	0.00148333	(0.30)	(0.53
376100-Mains - Steel 378000-Meas & Reg Station Equipment	21204133050 20403133040	904126 004133	Glenaire Rectifier/Ground Bed Repi Rebuild DRS 356 New DRS 8757	F0503	Rectifier New/Rect ISRS (N) Station Rebuild & Rept ISRS (N)	Addition Addition	ISRS-Other	201509	(12,93)		7 0.001483333 7 0.00238333	(0.13)	(0.2:
376300-Mains - Plastic	20812143289	004198	Elm & Eagon Repl PBS w 1295'-4;505'	F0592		Addition	ISRS-Other	201509	(2.88) (0.31)		7 0.00148333	(0.03)	(0.0
376300-Mains - Plastic	20401133129	004221	63rd Repl Cl Main w 1607a*-PE main	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	24,18		7 0.00148333	0.25	5.4
376300-Mains - Plestic	20201143426	004248	24 Hwy & Allen Repi PBS w 120°-4in	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(5.05)	i	7 0.00148333	(0.05	(0.0
376100-Mains - Steel	20401133039	004271	AOR 2552 Chelses Repl Cl with 40'-G	F0599	Main Replacement - ISRS (N)	Addition	1585-Other	201509	(1.22)		7 0.00148333	(0.01	(0.0)

Missouri Gas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prof. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Depr.Mo. Rate	Accum. Onor	Depr Expense
376100-Mains - Steel	20903121888	004315	Brezendine Rectifier LOO43 and Grou	F0503	Rectifier New/Repl ISRS (N)	Addition	ISRS-Other	201509	(2.72)		7 0.00148333	(0.03)	(0.05
376300-Mains - Plastic	20317143417	004364	Davis St Repl P85 w 730'-2in PE mail	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(11.98)	ş maş	0.00148333	(0.12)	(0.21
376100-Wains - Steel	20902132967	004374	Railroad St Repi BS/CS w 1515'-2in;	F0504	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	23.43	-	7 0.00148333	0.24	0.42
376100-Mains - Steel	20902132967	004374	Reliroed St Repl BS/CS w 1515*-2in;	F0604	Main Replacement - ISIG (5)	Addition	ISRS-Other	201510	(400.00)		5 0.00148333	(9.56)	(7,12
376100-Mains - Steel	20201133049	004382	33rd & Vermont Rectifler/GroundBed	FOSO3	Rectifier New/Repl ISRS (N)	Addition	ISRS-Other	201509	4,65		7 0.00148333	0.05	0.08
376100-Mains - Steet	20201133137	004396	Farley Ave Repl PBS w 9325'-2;285'-	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	94.48		7 0.00148333	0.98	1,68
37G100-Mains - Steel	20301118253	004430	W0337 Rectifier Groundbed Replaceme	F0503	Rectifier New/Repl ISRS (N)	Addition	ISRS-Other	201509	5.19	-	7 0.00148333	0.05	0.05
376300-Mains - Plastic	20501133213	004458	12th & Joplin Ave Repi 985 w 1355'-	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	17,217.08		7 0.00148333	178.77	306.46
376300-Mains - Plastic	20501133213	D04458	12th & Joplin Ave Repl PBS w 1355'-	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201510	9,218.33		8 0,00148933	s 82,04	164-0

Missouri Cas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prol. No.	Eunding Protect Description	FERC Activity	Catagory	Month	Addition Amount	Months	Depr Mo, Rate	Accum. Deor	Depr Expense
376300-Maine - Ploxite	20501133213	004458	12th & Joplin Ave Repl PBS w 1355'-	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201511	6,654.12		0.00148333	49.35	118.44
376300-Mains - Plostic	20501133213	004458	12th & Jopin Ave Repl PBS w 1355'-	F0572	Main Replacement - ISRS (SW)	Addition	585-0 ther	201512	(478.89)	\ \ \	0.00148333	(2.84)	{8.53
376100-Mains - Steel	20815132957	004474	Replace Fuses on WO 132353 Thistie	FOSSIA	Replace steel & plastic main	Addition	ISRS-Other	201509	2.90		0.00148333	50.03	0.0
.37G100-Mains - Steel	20503132745	004559	7th & Minnesota Repl PBS w 2350°-4;	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(37.67	)	7 0.00148333	(0.39)	(0.6
376300-Mains - Plastic	20502143412	004588	Jefferson Repl PbS/PCS w 1080'-6;82	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(35.12	)	7 0.00148333	(0.36)	(0.63
376100-Mains - Storel	20201132490	004619	Lexington & Short Repl PBS w 220-2	F0604	Main Replacement - ISRS (\$)	Addition	ISRS-Other	201509	2.37		7 0.00148333	0.02	0.0
				17 7/10									The second secon
376300-Mains - Plastic	20201143450	004888	33rd & Vermont Repl PBS w 22300'-2;	F0504	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(436,56		7 0.00148333	(4.53	(2.7

Missouri Das Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Julia Account	MGE Work Order No.	New Work Order No.	Work Order Opportation	Funding Proj. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Qepr.Mo. Rate	Accum, Deer	Door Expense
176300-Məina - Plastic	20201143455	004882	40th & Highridge Repl PBS w 7870'-2	FOGO4	Main Replacement - ISRS (5)	Addition	ISRS-Other	701500	(103.02)		0.00148333	(1,07)	(1.83
176300-Mains - Plastic	20201143455	004889	40th & Highridge Repl PBs w 7870°-2	F0604	Main Replacement - JSRS (5)	Addition	ISRS-Other	201510	(321,09)		3 0.00148333	(2.86)	(5.7:
376300-Mains - Plastic	20312143471	004949	Folger Repl PBS w 3350'-Zin PE main	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(8.12)		0.00148393	(0.08	(0.14
376100-Mains - Steel	20401143477	004973	84th & Tracy Repl PBS w 24'-TF Stee	F0663	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(3,83)		7 0.00148333		111111111111111111111111111111111111111
376300-Mains - Plastic	20401143313	004986	Cast Iron Repi Proj Ph I SecosoGKC	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(26.05		7 0.00148333	(0.27	) (0.44
376300-Mains - Plaxilo	20802143485	005008	Morris & Mirtle Real PBS w 2885-PE	F0592	Neplace bare steel main - safety re	Addition	ISRS-Other	201509	(330,54	111111	7 0,00148333	3.44	) (s.85
376300-Mains - Piestic	20501143304	005012	13th & Delawaro Repl PBS w 49351-PE	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201512	456,940,97		4 0,0014833:	3 2,711.18	8,133,5
375300-Mains - Plastic	20301143476	005028	Market St Repl PBS w 1320'-Zin PE m	F0504	Main Replacement - ISRS (S)	Addition	ISRS-Other	261509	(14.42		7 0.00148533	(0.15	(0.20
376100-Mains - Steel	20925143475	005029	Rept bridle valve & 10 piping DRS 1	P060S	Replace steel & plastic main	Addition	ISRS-Other	201509	(244,47	1	7 0.00148333	3 (2.54	(4.3)

Missouri Gas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

tillity Account	MGE Work Order.	New Work Order No.	Work Other Description	Funding Prol. No.	Eunding Protect Description	FERC Activity	Category	Month	Addition Amount	Months	Dept Mo. Bate	Accum, Dept	Dent Expense
									1				
176300-Mains - Plastic	20201143501	005039	31st Overton Repl PBS/PCS w 3425-2	F0504	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(0.46)		0.00148333	764	(0.01
178000-Meas & Reg Station Equipment	20925143474	005042	Rebuild DRS 1 09-25 RD Mize	FOGOO	Station Rebuild & Repl (SRS (N)	Addition	ISRS-Other	201510	2.09		0.00238333	0.03	0.00
178000-Meas & Reg Station Equipment	20925143474	005042	Rebuild DRS 1.09-25 RD Mize	F0600	Station Rebuild & Repl ISRS (N)	Addition	ISRS-Other	201511	(0.03)		0.00238933		
378000-Meas & Reg Station Equipment	20925143474	005042	Rebuild DRS 1 09-25 RO Mize	FGGGO	Station Rebuild & Repl ISRS (N)	Addition	SRS-Other	201512	(11,332.23)		0.00238333	(108.03	(324.10
976300-Meins - P(astič	20902143513	005153	S9th & Kentucky Repl PCS/PBS w #85'	F0654	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	<u>(19.68)</u>		7 0.00148333	(0.20	) (0.3:
37G3OQ-Mains - Plastic	20201143520	005210	35th Ter & Pittman Repi PBS w 4120'	F0604	Main Replacement - ISRS (5)	Adaltion	ISRS-Other	201509	(252,00)				
376300-Mains - Plastic	20401143422	005250	Wabash & St John Repl Cl w 190'-4in	F0500	Replace cast fron main - CPI / prio	Addition	ISRS-Other	201509	(42,58)		7 p.00148333 7 p.00148333		F-95
376300-Mains - Plustic	20201143547	005273	35th & Evanston Tie exist PEroC-500	F0580	Replace steel & plastic main	Addition	ISRS-Other	201509	(51.02		7 0.00148333	(0.53	) (0.9)
376300-Mains - Plastic	20201143547	005273	35th & Evanston Tie exist PEtoC-500	F0580	Replace steel & plastic main	Addition	ISRS-Other	201510	(7.08		6 0,00148333	(0 <u>.0</u> 0	(0.1
376300-Mains - Plastic	20809143500	005274	Hadley & Rinker Repl PBS w 895'-2p	F0592	Replace bare steel main - safety re	Addition	ISRS-Other	201512	140,885.69		4 6,00148333	835,92	2,507.70

Missouri Gas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prol. No.	Funding Protect Description	FERC Activity	Category	Month	Addition Amount	Months	Dept Mo. Rate	Accum. Depr	Dept Expense
8763,00-Mains - Steel	20201143515	005291	Repi PBS main Blue Ridge blvd 31st	F0604	Main Reniacement - ISRS (S)	Addition	ISRS-Other	201509	(0.59)		0.00148333	(0.01)	(0.01
376300-Mains - Plastic	20201148515	005291	Repl P85 main Blue Ridge Blvd 31st	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(1,172.84)		0.00148333	(12.18)	(20.88
376300-Mains - Plastic	21271143517	005295	39th & N Spruce Repl P85 w 2400'-2	F0663	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(192.94)	,	0.00148333	(2.00)	(3,43)
37G300-Mains - Plastic	20902143584	005395	79th & Raytown Rd Repl PBS/PCS main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(759.11)		0.00148333	(7.88)	(23.51
376300-Mains - Plastic	20401143489	005432	43rd/47th Beilonteine Cl Repi Proj	F0509	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(1,290.57)		0.00148333	(13.40)	(22.97
376300-Mains - Plastic	20401143480	005433	1511 Brooklyn REPL CI w 101'-4IN PE	F0500	Replace cast Iron main - CPI / prio	Addition	ISRS-Other	201509	215,50	- 3	0.00148333	2.24	5.84
376100-Mains - Steel	20801143585	005451	11th & Broadway Repl PBS w 50'-2In	F0634	Replace bare steel main - sofety re	Addition	ISRS-Other	201509	(0.59)		0.00148333	(0.01)	(0.01
376300-Mains - Plastic	20504143350	005456	Repl Steel in Alba due to Leakage	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(953-31		7 0.00148333	(2.90)	(16.97
376300-Mains - Piastic	70504143350	005456	Repi Steel in Alba due to Leakege	F0544	Replace bare steel main - safety re	Addition	15RS-Other	201510	(218,682.40		6 0.00148333	(1,056.27	(2,112,54

Missouri Oas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Finding Prof. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo, Rate	Accum_Door	Deer Exgense
376300-Mains - Plestic	29504143350	005456	Replisteel in Alba due to Leakage	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201511	(141.87)		5 b.00148333	(1.05)	(2.53)
376300-Mains - Plastic 376300-Mains - Plastic	20504143350 21001143532	005456 005466	Repisted in Alba due to Leakage Spratt Ave Repi PBS w 454°-2(n PE	F0544 F0504	Replace bare steel main - safety re Replace bare steel main - safety re	Addition Addition	ISRS-Other ISRS-Other	201512 201509	897-23 8.61		4 0.00148333 7 0.00148333	5.32 0.09	
376300-Mains - Plastic	20503149605	005468	Murphy Repl PBS/PE w 1115-2;255-4	F0544	Replace hare steel main - safety re	Addition	ISRS-Other	201502	(96.38)		7 0,00148333	(1.00)	(1,72
376300-Meins - Plastic	20501143605	005468	Murphy Repl P85/PE w 1115*2;255'-4	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201510	(42.16)		5 0.00148333	(0.44)	(O.B8
376300-Mains - Plastic	20501143573	005490	Picher Ave Repl PBS w 125'-Gin CS;	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(96.95)		7 0.00148333	(1.01)	(1.73
376300-Mains - Plantic	20501143573	005490	Picher Ave Repl PBS w 125'-6in CS;	F0572	Main Repiacement - ISRS (SW)	Addition	isRS-Other	201510	(15,23	) 	0,00148333	[0.14]	(0.27
376300-Mains - Plastic	20324143614	005557	College Repl PBS LP main w IP 3865*	FD604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(136.19		7 0.0014#333	(1.42)	(2.42

Missouri Oss Energy - MOE 13RS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2015

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prol. No.	Funding Project Coscription	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Accum. Depr	Depr Expense
76300-Mains - Plestic	20324143614	005557	College Repi PBS LP main w IP 3865'	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201510	(56,88)		0.00148333	(0.51)	(1.01
76300-Mains - Plastic	21001143533	005592	4th & Sylvanie St Repl Bin Cl W 600	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(16.50)	7	0.00148333	(0.17)	(0.29
176300-Meins - Plastic	20401143586	005677	CI Repl due to graphitization	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(369,47)	,	0,00148333	(3.84)	(6,58
37 6300-Mains - Plactic	20401143569	005679	CI Repl Due to Graphitization	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(55.14)	7	0.00148333	(0.57)	(0,98
3761.00-Mains - Steel	20201133055	005735	Jones St Ret DRS 117 & I/O piping T	F0580	Replace steel & plastic moin	Addition	ISRS-Other	201509	(27.94)		0.00148333	(0.29)	(0.50
S76300-Mains - Plastic	20401143601	005773	803 Bales Ct Repl Cl w 40'-4in PC m	F0599	Moin Replacement - ISRS (N)	Addition	ISRS-Other	201509	(9.32)		0.00148333	(0.10)	(0,17
376300-Mains - Plastic	20324143615	005799	College Repl 2in PE w/1000*-sin PE	F0580	Replace steel & plastic main	Addition	ISRS-Other	201509	(41.32)		0.00148333	(0.43	(0.74
376300-Mains - Plastic	20324143615	005799	College Rept 2tn PC w/1000'-4in PE	F0580		Addition	ISRS-Other	201510	(7.33	1	5 0.00148333		
376300-Mains - Plastic 376300-Mains - Steel	20401143687 20401143682	005852 005854	2415 Walrond Repl Cl w 15'-6in PE m Kensington & E 112 Ter Reloc PB w 1	F0599 F0663	Main Replacement - ISRS (N) Replace bare steel main - safety re	Addition	ISRS-Other	201509	(3.35 (0.99		7 0.00148333 7 0.00148333		1 - 2 - 2
376300-Mains - Plastic	20403143602	005917	18th Ter Xepl CI/CS w 2945'-4;340'-	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(219.94		7 0.00148333	(2.28	(3.93
376300-Mains - Steel	20301143713	005951	Wajnut Grove Rectifier 0256 Reloca	F0503	Rectifier New/Rep) ISRS (N)	Addition	ISRS-Other	201509	(53.13	)	7 0.00148333	3 (0.55	(0.95
376100-Mains - Steel	20301143713	005951	Walnut Grove Rectifler 0256 Reloca	F0503	Rectifier New/Repi ISRS (N)	Addition	ISRS-Other	201510	(776.12		6 0.0014833	3 (6.91	(13.8:

Missouri Gas Energy - MOE ISRS Work Order Additions September 2015 - Occember 2015 with Estimates for January and February 2016

Jrillity Account	MGE Work Order Na	New Work Order No.	Work Order Description	Funding Prot. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Dept Mo. Rate	Accum. Deor	Depr Expense
						Y							
76100-Mains - Steet	20301143713	005951	Walnut Grove Rectifier 025G Reloca	F0503	Rectifier New/Robi ISRS (N)	Addition	ISRS-Other	201511	3.30	5	0.00148333	0.02	0.0
76100-Mains - Steel	20301143713	005951	Walnut Grove Rectifier 0256 Reloca	F0503	Rectifier New/Repl ISRS (N)	Addition	ISRS-Other	201512	25,78		0,00148333	0.14	0.4
7500-Mains - 3000	20301143713	003931	Wallut Older Reculier 5236 Roots	70303	NELSHET NEW POUR SAS (N)	Rability	ISRS-Other	201317	23,74		0.00142333	0.14	5.9
17G100-Mains - Steel	20401143709	005956	River Market Rectifier and Groundbe	F0G2G	Rectifier initial installations	Addition	ISRS-Other	201509	(51.99)	.7	0.00148333	(0.54)	(0.9
376100-Mains - Steel	20925143738	006030	Replace 12in PCS Main I-70	F0580	Replace steel & glastic main	Addition	ISRS-Other	201509	(270.38)	-	0.00148333	(2.81)	(4.8
376100-Mains - Steel	20925143738	006030	Replace 12in PCS Main 1-70	F0580	Replace steel & plastic main	Addition	ISRS-Other	201510	(43.20)		0.00148333	(0.38)	(0.7
376JCD-44ains - Plastic	20925143749	006080	Install Zin PE distribution main Je	F0580	Replace steel & plastic main	Addition	ISRS-Other	203509	(57.75)	7	0.00148333	(0.60)	(1.0
97G100-Mains - Stool	21001143745	000085	DSAGE RECTIFIER GROUND BED REPLACEM	F0503	Rectifier Naw/Repl ISRS (N)	Addition	ISRS-Other	201509	[54,69]		7 0.00148333	(0.57)	(0.5
376100-Mains - Steel	21207143744	006111	Northwyck Park Rectifler and Ground	F0621	Rectifier initial installation	Addition	SRS-Other	201509	(87.12		7 0.00148333	(0.90)	(1.5
876100-Mainz - Steel	20828143755	006113	Repl 1,25 and 2 in CS Main	F0598	Replace steel & plastic main	Addition	ISRS-Other	201509	(66.50)		7 0.00148333	(0.69)	(1.1
376100-Mains - Steel	20909143721	006126	Veille Road Rectifier Relocation	F0503	Rectifier New/Repl ISRS (N)	Addition	ISRS-Other	201509	(64.79)		7 0.00148333	(0.67	(1)
376300-Mains - Plastic	20506143761	006201	Stones Corner Main Relocation	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201500	(51.62		7 0.00148333	(0.54	(0.5

Missouri Cast Energy - NGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prol. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Dapr Mo. Rate	Accum. Depr	Depr Expense
376300-Mains - Plastic	20401143705	006351	AOR GIn CI Replacement with \$5ft-6i	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(90,771	,	0.00148333	(0,94)	(1,62
376300-Mains - Plastic	21001343596	006355	PBS Replacement	FD504	Replace bare steel main - sefety re	Addition	ISRS-Other	201509	(133.91)	7	-	(1.39)	(2.38)
376300-Mains - Plastic	21001143596	006355	PBS Replacement	F0504	Replace bare steel main - safety re	Addition	ISRS-Other	201510	(21.41)	6	9.00148333	(0.10)	(0.38)
376300-Mains - Plastic	20806143791	006356	Repl 288ft Pas with 295ft Zin Plast	F0634	Replace bare steel main - safety re	Addition	15RS-Other	201509	(68,80)	7	0.00148333	(0.71)	(1.72)
376300-Mains - Plastic	20501149720	006435	Lower 167ft of 2 in PE	F0575	Replace steel & plastic main	Addition	ISRS-Other	201509	(20.69)		0,00148333	(0.11)	(0.19)
376300-Mains - Plastic	20813143792	006473	Repl 391 th 85 86 th C≤ with 479 th 2	F0573	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(233.24)	7	0.00148333	(2.42)	(4.15)
376300-Maina - Plattic	20502143823	006512	Replace w/ 210ft of 4in Pt due to D	FOS75	Replace steel & plastic main	Addition	iSRS-Other	2015(9)	(492.44)		0.00148333	(5.11)	(8.77
376300-Mains - Plastic	20501143824	006513	Repl 22ft of 6tn PE due to 3rd Part	F0575	Replace steel & plastic main	Addition	ISRS-Other	201509	(4.43)		0.00148933	(0.03)	(0.08)
376300-Mains - Plostic	20324143651	006516	Replace PBS Main in Pilot Grove	F0504	Main Replacement - ISRS (S)	Addition	ISRS-Other	701509	(1,968.19		7 G.00148333	(26,44)	(35.03
376300-Mains - Plastic	20324143651	006516	Replace PBS Main in Pilot Grova	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201510	(334,99	,	0.00148333	(2.98)	(5.96
37G300-Mains - Plostic	20903143822	006551	Replace 4inch PCS/P85 main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(58.52		7 0.00148333	(0.61)	(1.04
376300-Mains - Plastic	21207143819	006552	Zin PE Main Relocation	F0636	Replace steel & plastic main	Addition	ISRS-Other	201509	10.61		7 0.00148333	(0.01)	(0.01
376300-Mains - Plestic	20201143853	006594	Replace 6in PBS 20th and Arlington	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	§12.11		7 0.00148333	(0.13)	) (0.22
376300-Meins - Plastic	20401143816	006597	CI Replacement w/ 2,430ft-4in PE	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(884.14		0.00148333	(9.18)	(15.74
376300-Mains - Plastic	20401143826	006603	3in PBS Main Replacement	F0613	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(99.57	)	7 0.00148333	(1.03	(1,77
376300-Mains - Plastic	20806143868	006654	Repl Zin PBS due to CP	F0573	Replace bare steel main - sufety re	Addition	ISRS-Other	201509	(154.03	1	7 0.00148333	(1.70	(2,92

Missouri Oas Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MOE Work Order	New Work Order No.	Work Order Description	Funding Prol. No.	Funding Project Description	FERG Activity	Category	Month	Addition Amount	Months	Dept Mo. Rate	Acouth, Debt	Dept Expense
										- Control		11766	
176300-Mains - Plastic	20401143775	006659	Cast Iron Replacement project WO-1	P0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(3,525.77)	7	0.00148333	(30.61)	(62.7
376300-Mains - Plastic	20401143773	006659	Cest Iron Replacement project WO-1	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	(325.13)		0.00148333	(1.93)	<b>†5,</b> 7
7,050	No. 100. No. 100.	55.005	and the state of t	1		Applied	toria attici	1	, Constitution of the Cons			,,,,,,,	1375
376300-Mains - Plactic	20501143695	006664	Repl with 875ft of 4in PE due to EP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(107.85)	7	0.00148333	(1.12)	(1,9
37G100-Meina - Steel	20501143696	006665	Repl 655ft of Gln PBS due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	9,661.58	2	0.00148333	100.32	171.9
376300-Moins - Plastic	20501143696	299900	Rept 656ft of Gin PBS due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(9,726.87)		0.00148333	(101.00)	(173.1-
37G100-Mains - Steel	20501143696	006665	Repl GSGft of Gin PBS due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201516	921.84		0.00148333	8.20	16,4
376300-Mains - Plantic	20501143696	006665	ReplicSGt of Gin PBS due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201510	3,594.63		0.00148333	31,99	63.9
376100-Mains - Steel	20301143696	006665	Replication of Gin Pas due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201511	(23.26)		5 0.00148333	(0.17)	(0.4
376300-Mains - Plastic	20501143696	206665	Repl 656th of Gin Pas due to CP	F0572	Main Replacement - ISRS (5W)	Addition	ISRS-Other	201511	(90.69)		0,00148333	(0.67)	{1.5
376100-Mains - Steel	20501143696	andecs	Replication of Gin PBS due to CP	F0572	Main Repistement - ISRS (SW)	Addition	ISRS-Other	201512	(23.40)		4 0.00148333	(0.14)	(0.4
376300-Mains - Plestic	20501143696	006665	Repl 656ft of Gin PBS due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201512	(21.18)		4 0.00148333	(0.54	(1.6
376300-Mains - Plastic	20801143783	999900	Repl 177ft 2in 85 with 180ft 2in Pl	F0573	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(17.53)		7 0.00148333	(0.18	(0.3
376300-Mains - Plastic	20801143783	006666	Repl 177ft 2in BS with 180ft 2in Pl	F0573	Replace bare steel main - safety re	Addition	ISRS-Other	201510	(118.81)		6 0.00148333	(1.06	(2.1

Missouri Gas Energy - MOE ISR3 Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Exadina Prot. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Accum. Dept	Depr Expense
376300-Mains - Plastic	20501145697	006667	Repl with 375ft of 2in PE due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(25.26)	7	0.00148333	(0.26)	(0.45)
376300-Mains - Plastic	20501243694	006668	Repl with S10ft of 4in PE due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(114.52)	7	0.00148333	(1.19)	(2.04)
176300-Mains - Plastic	20501143694	006668	Repl with 510ft of 4in PE due to CP	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201510	17,19		0,00148333	0.15	0,31
176300-Malos - Plastic	20806143672	006669	Repl 2in PCS due to CP Mein and	F0598	Replace steel & plastic main	Addition	ISRS-Other	201509	58.11	,	0.00148333	0.60	1,03
378000-Meas & Reg Station Equipment	20932143803	006670	Rebuild DRS 4 Medison and Forwood	F0606	Station rebuild & replacement	Addition	ISRS-Other	201511	26,953.85		0.00238333	321.20	770.58
378000-Mear & Reg Station Equipment	20932143803	006670	Rebuild DRS-4 Madison and Foxwood	F0606	Station rebuild & replacement	Addition	ISRS-Other	201512	(3,790.13)	4	0.00236333	(36.13)	(108.40)
376300-Mains - Plastic	20201143851	006671	Replace PBS Northern and 27th	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(1,107.83		7 0.00148533	(11.50)	(19.72)
376102-MGE-Mains Steel-Transmission	20925143795	006690	Hydrotest 12/n Transmission Main	FOSOZ	34-394-10G-PIPESAFE	Addition	ISRS-Other	201509	(432.73		7 0.00148333	[4,49]	(7.70
376500-Mains - Plastic	2050243908	006738	Replace with 975ft of 2in due to CP	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201512	33,260.50		4 D.00148333	201.50	604.50
37G300-Mains - Plastic	20501143900	OD6740	Repl with 2120ft of Jin PE due to C	20544	Replace bare steel main - safety re	Adultion	ISRS-Other	201510	96,179.05		e 0.00148333	855.99	1,711.98
376300-Meins - Plastic	20501143900	006740	Repi with 2120ft of 2in PE due to C	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201511	335,82		5 0.00148333	3 2,49	5.98
376300-Mains - Plastic	20501143900	006740	Repl with 212aft of Zin PE due to C	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201512	(13.04	)	4 0.00148333	(0.08	(0.23
376300-Mains - Piastic	20901143903	006762	Replace pas main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(77.8)	7)	7 0,00148333	(0.81	(1.39
376300-Mains - Plastic	20901143903	006762	Replace pbs main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201510	(10.21	.)	6 0.00148333	(0.09	(0.12

Missouri Cas Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for Jenuary and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prof. No.	Funding Protect Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Accum, Oppr	Depr Exponse
376300-Mains - Plastic	21001143860	006790	Replace 202ft of PBS with 202ft of	F0678	Replace bare steel main - safety re	Addition	IS8S-Other	201509	(125.42)	7	0.00148333	(1.30)	(2.23
376300-Mains - Plastic	21001143907	006800	Repl 60ft of 2in PE main with 2inP	F0580	Replace steel & plastic main	Addition	ISRS-Other	201509	2.19	7	0,00148333	5.02	0.04
37G100-Mains - Steel	20403143829	006836	CI Breek Repl w/1630ft of 4in PE an	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(75.40)	7	0.00148333	(0.78)	(1,34
376300-Mains - Plastic	20401143829	006836	CI Breek Repl w/1030ft of 4lh PE an	F0599	Main Replecement - ISRS (N)	Addition	ISRS-Other	201509	(342.28)	7	0.00148333	(3.55)	(6.09)
376100-Mains - Steel	20401143829	006836	CI Greak Repl w/1630ft of 4in PE an	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	(9.98)		0.00148333	[0.09]	(0.18
376300-Mains - Plattic	20401143829	006836	CL Break Repl w/1630ft of 4in PE an	F0S99	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	(45.40)	. 6	0.00148333	(0.40)	(0.81
376300-Mains - Plastic	70902143839	858900	Replace 4in PCS/PBS main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(316.13)	7	0.00148333	(3.28)	(5:63
376300-Mains - Plastic	20902143839	006838	Replace 4in PCS/PBS main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201510	(192.14)	6	0.00148333	(1.71)	(3.42
376300-Mains - Plastic	20902143856	006839	Replace 2in PBS main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(178.78)	7	0.00148333	(1.86)	(3.18
376100-Mains - Steel	20401143807	006844	2in PCS Replacement	F0665	Replace steel & plantic main	Addition	ISRS-Other	201509	(77.66)	7	0.00148333	(0.82)	(1.38
376300-Mains - Plastic	20201143934	006845	Replace 2 in PCS & 2 in PBS m	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(584.91)	7	0.00148333	(6.07)	(10.41
376300-Mains - Plastic	20902143857	006851	Replace 4In PBS & Zin PCS m	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(157.64)		0.00148333	(1,64)	(2.8)
376300-Mains - Plastic	20902143858	006855	Replace 2in PCS/PBS main	F0G04	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(101.60)		0.00148333	(1.05)	(1.81
376300-Mains - Plastic	20902143858	006855	Replace 2in PCS/PBS main	FD604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201510	(21.84		0.00148333	(0.19)	(0.39
376300-Mains - Plastic	20401143936	006910	4in Ci Replacement	F0500	Replace cast iron main - CPI / prio	Addition	ISRS-Other	201509	(57.31		0.00148933	(0.60)	(1.02
376300-Majos - Plastic	20401143742	006916	Stst and Woodland C Replacement	F0500	Replace cast fron main - CPt / prio	Addition	ISRS-Other	201509	(606.66		7 0.00148333	(6.30	(10.80
376300-Mains - Plastic	20401143742	006916	S1st and Woodland Ci Replacement	F0500	Replace cost fron main - CPi / prio	Addition	ISRS-Other	201510	(721.08	)	0,00148333	(6.42)	) (12.84
376300-Mains - Plastic	20401143849	CO6918	AOR Replace Cl w/ 1,530tt-4in PE	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(161.71	)	7 0.00148333	(1.68	(2.88
376300-Mains - Plastic	20502143950	006935	Daugherty Avenue Bare Steel Replace	F0572	Muin Replacement - ISRS (SW)	Addition	ISRS-Other	201509	[529.94	1	0.00148333	(5.50	9.43
-376300-Mains - Plastic	20502143950	006935	Daughorty Avenue Bare Steel Replace	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201511	207.00		5 0.00148333	7.40	17.75

Missouri Ces Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016.

Utility Account	MGE Work Order. No.	New Work Order No.	Work Order Description	Funding Prot. No.	Funding Protect Description	FERC Activity	Category	Month	Addition Amount	Months	Depr.Mo. Rate	Accum. Done	Dept Expense
37630D-Mains - Plastic	20502143950	006935	Daugherty Avenue Bare Steel Replace	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201512	(38.76)	4	0.00148133	(0.23)	(0,69
376300-Mains - Plastic	20401143985	006976	4in PBS Replacement James A Ree	F0663	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(73.69)		0.00148333	(0.77)	(1.31
17GSCD-Mains - Plastic	20501143657	006975	Replace Main at Hill and Division C	F0678	Replace bare steel main -sofety re	Addition	ISRS-Other	201509	22,312.78	7	0.00148333	231.58	397.17
376300-Mains - Plastic	20501143657	006975	Replace Main at Hill and Division C	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201510	1,329.43		0.00148333	11.83	23.6G
376300-Mains - Plastic	20501143657	006975	Replace Main at Hill and Division C	F0678	Replace bore steel main - sefety re	Addition	ISRS-Other	201511	(33.53)		0.00148333	(0.25)	(0,60)
376300-Mains - Plastic	20501143657	006975	Replace Main at Hill and Division C	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201512	(33.75)		0.00148333	(0.20)	(0.60)
376300-Mains - Plastic	20806143870	006982	Repl 2in PBS Due to CP Hickory	F0573	Replace bare steel main - safety re	Addition	ISR5-Other	201509	(107.66)		0.00148333	(1.12)	(1.92)
376300-Mains - Plastic	20501143978	006985	Repl 230ft of 2in PE 19th and NH io	F0575	Replace steel & plastic main	Addition	ISRS-Other	201509	(21.87)		0.00148333	(0.23)	(0.39
378000-Mees & Res Station Equipment	20925143982	006990	Rebuild DRS 10 88 and Perry	F0606	Station rebuild & replacement	Addition	15RS-Other	201510	(34.73)		0.0023#333	(0.50)	(0.99)
376300-Mains - Plastic	20030143990	007031	Abandon Pressure System w Isolated	F0598	Replace steel & plastic main	Addition	ISRS-Other	201509	her-94		0.00148333	(1.58)	(2.88
376300-Mains - Plastic	20501144012	007078	6th and Connor Repl 70ft of 4in PBS	F0544	Replace bere steel main - safety re	Addition	ISRS-Other	201512	8,885.71		4 0.00148333	52.72	158.17
376300-Mains - Plastic	20502143980	007080	Repl with 1220ft of Zin PE due to C	F0544	Replace here steel main - safety re	Addition	ISRS-Other	201510	62,096.99		6 0.00145333	552.66	1,105.32
376300+Mains - Plastic	20502143980	007080	Repl with 1220ft of 2in PC due to C	FD544	Replace bare steel main - safety re	Addition	ISRS-Other	201511	37.96		5 0.00148333	0.28	0.68
376300-Mains - Plastic	20502143980	007080	Repl with 1220ft of 2in PE due to C	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201512	123.79	n <sub>tte</sub>	4 0.00148333	0.73	2.20
376100-Mains - Steel	20925143983	007153	Relocate 2in PCS IO DRS 10 BB and P	F0580	Raplace steel & plastic main	Addition	ISRS-Other	201509	(42.17	)	7 0.00148333	(0.44	(0.75
376100-Mains - Steel	20925143983	007153	Relocate 2in PCS IO DRS 10 35 and P	F0580	Replace steel & plastic main	Addition	ISRS-Other	201510	(6.25	)	6 0.00148333	(0,06	(0.11
376300-Mains - Steel	21001143957	007182	Relocate Inlet and Outlet Piping DR	F0504	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(1,046.23		7 0.00148333	(10.86	(18.62

Missourt Oes Energy - MOE 13RS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Hillity Account	MGE Work Order	New Work Order No.	Work Order Description	Funding Prot. No.	Funding Project Description	FERC Activity	Catagory	Menth	Addition Amount	Months	Dept Mo. Rate	Accum. Door	<b>Depr. Ехрапас</b>
76300-Mains - Plastic	21001143957	007182	Relocate Inlet and Outlet Piping DR	F0504	Replace bare steel main - safety re	Addition	ISRS-Other	201509	203,44		0.00148333	2.11	3.62
76300-Mains - Plastic	70502144036	007183	Repl w 225ft of Zin PE 8th and Oeki	F0544	Replace bare steel main - sofety re	Addition	ISRS-Other	201509	(33,63)	7	0.00148333	[0.35)	(0.60
76300-Mains - Plastic	20502144034	007191	Repl w 725ft of 4in PE 13th and Mad	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201510	44,496.85		0.00148333	396.02	792,04
176300-Mains - Plastic	20502544034	007191	Repl w 725ft of 4in PE 13th and Mad	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201511	(505,10)		6.00146333	(3.75)	(8,99
176300-Mains - Plestic 176100-Mains - Stéal	20502144034 21251144040	007191 007197	Repl w 725ft of 4in PE 13th and Mad 2in PCS replacement	F0544 F063G	Replace bare steel main - safety re Replace steel & plastic main	Addition Addition	ISRS-Other	201512 201509	4.07 (22.98)	4	0.00148333 0.00148333	0.02 (0.24)	0,07 (0.41
376300-Mains - Plastic	20501144013	007201	Sth and Gray Repl w 820ft of 4in PE	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201512	91,487.78		0.00148333	542.83	1,628.48
376300-Meins - Plastic	2080G143871	007202	Repl 2in PBS due to CP Rockhill	F0634	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(147,48)		0.00148333	(1,53)	j2.63
376300-Mains - Plastic	20502144035	007206	Repl w 440ft of 4in PE 10th and Mad	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201510	40,516,97		0.00148333	360.60	721.20
376300-Mains - Plastic	20507144035	007206	Repl w 440ft of 4in PE 10th and Med	FD544	Replace bare steel main - safety re	Addition	ISRS-Other	201511	(21.49)		0,00148333	(0.16)	(0.38
376300-Mains - Plastic	20502144035	007206	Repl w 440ft of 4in PE 10th and Mad	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201512	3,648.83		0.00148333	21.65	64.91
37G100-Mains - Steel	20401144041	007310	Glen Arbor and Red Bridge Main Repl	F063.6	Replace steel & plastic main	Addition	ISRS-Other	201509	[54.83	)	7 0.00148333	(0.57)	(0.98
376300-Mains - Plastic	21271143521	507313	POS Replacement	F06G3	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(542 <u>.24</u>	,	7 0.00148333	(5.63	(9.63
376300-Mains - Plastic	21271143521	007313	PBS Replacement	P0663	Replace bare steel main - safety re	Addition	ISRS-Other	201511	{205.55	)	5 0.00148333	(1.52	(3.6)
376300-Mains - Plastic	20401144046	007316	AOR 4(n Cl Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(58.08	)	7 0.00148333	[0.60	(1.0.
376300-Mains - Plastic	20401144045	007317	AOR GIn CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(107.72		7 0.0014833	(1.12)	(2.9
376300-Mains - Plastic	20401144045	007317	AOR Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	(129.21		6 0.00148333	(1,15	(2.3

Missouri Cas Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Entimates for January and February 2016

Utility Account	MGE Work Order	New Work Order No.	Work Order Description	Funding Proj. No.	Funding Project Description	FERC Activity	Catagory	Month	Addition Amount	Months	Depr Mo. Rate	Accum. Deor	Door Expense
17630D-Mains - Pleatic	21251143731	007319	Replace Thin Film with 4in and 2in	F0665	Replace steel & plastic main	Addition	ISRS-Other	201509	(159.16)	- 7	0.00148333	(1,65)	(2.83
976100-Mains - Steel	20806149833	007324	Repl HWY Crossing Due to Desser Cou	F0573	Replace bare steel main - safety re	Addition	ISRS-Other	201509	112,650.74	,	D.00248333	1,169.69	2,005.18
376300-Mains - Plastic	20806143833	007324	Repl HWY Crossing Due to Desser Cou	F0573	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(106,632-89)	. 7	7 0.00148333	(1,107.20)	(1,898.06
376300-Meins - Plastic	20201144057	007327	Replace 2in & 4in PBS Main	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(99.70)		0.00148333	(1.04)	(1.77
376100-Mains - Steel	20323144062	007330	HOUSTONIA GROUNDBED REPLACEMENT	FQSQ3	Rectifier New/Repl ISRS (N)	Addition	ISRS-Other	201509	(27,68)	-	0.00148333	(0.29)	(0.49
376300-Mains - Plastic	20501155072	007396	12th St and Geneva Ave PBS Replacem	F0544	Replace bare steel main - safety ce	Addition	ISRS-Other	201509	(426,50)		7 0.00148333	(4.43)	(7.55
376300-Mains - Plastic	20501155072	007396	12th St and Geneva Ave PBS Replacem	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201510	511,20		0.00148333	4.55	9.10
376300-Mains - Plastic	20501155072	007396	12th St and Geneva Ave PBS Replacem	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201511	11,585,32		5 0.00148333	85.92	206-20
376300-Mains - Plastic	20501155072	007396	12th St and Geneva Ave PBS Replacem	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201512	2,664.35		4 0.00148333	15.81	47.43
376300-Mains - Plastic	20401155084	007474	4in PE Main Relocation	F066S	Replace steet & plastic main	Addition	ISRS-Other	201509	(45.17)		7 0.00148333	(0.47)	(0.80
376300-Mains - Plastic	21001155069	007480	Repl 500ft of 3in & 4in B.S. w/ 4i	FOG78	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(29.92)		7 0.00148333	(0.31)	(0.53
376100-Mains - Steel	20904155108	007499	2in and 4in PBS Replacement with 2	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(31,268,86)	1 5	7 0.00148333	[324.67]	(556.57
376300-Mains - Plastic	20904155108	007499	2in and 4in PBS Replacement with 2i	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	31,119,79		7 0.00148333	323.13	553.91
376300-Mains - Plastic	20201155087	007503	Replace PB\$ main 23rd and Haden and	F0604	Main Repiacement - ISRS (S)	Addition	ISRS-Other	201509	1,469.04		7 0.00148333	15,25	26.1
376300-Mains - Plastic	20201155087	007503	Replace PBS main 23rd and Haden and	F <u>0</u> 604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201510	(36.55	J	6 0.00148333	(0,33	(0.6
376300-Meins - Plastic	20501155075	007506	Repl PBS with 1250ft of PE 12th and	FQ544	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(397.51	)	7 0.0014833;	(4.13	{7.0

Missouri Cas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2015

Hilly Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prof. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Dept Mo. Rate	Accum, Dept	Depr Expense
7630D-Mains - Plastic	20502155074	007508	Walker St PBS Replacement	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(219.28)	7	0.00148333	(2.28)	(3.90)
176300-Mains - Plastic	20201155085	007512	Replace 4in PBS 23rd and Arlington	F0504	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(299.94)		0.00148333	(3.21)	(5.34
976300-Mains - Plastic	20401155102	007512	Gin CI Replacement	F0599	Main Regiscement - ISRS (N)	Addition	ISRS-Other	201509	(4,37)		0.00148333	(0.05)	(0.08
376300-Mains - Plastic	20301155094	007513	Replace 2in PBS Gay and Mitchell	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201510	27,356.82		0.00148333	243.48	486.95
37630D-Mains - Plastic	20301155094	007513	Replace Zin PBS Gay and Mitchell	F0G04	Main Replacement - ISRS (5)	Addition	ISRS-Other	201511	(48,47)		0.00148333	(0.36)	(O.8G
376300-Mains - Plastic	20301155094	007513	Replace 2in PBS Gay and Mitchell	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201512	(60.54)		0.00148333	(0.36)	(1,08
97630D-Mains - Plastic	20904155099	007516	Replace PBS main 130th and 8yers Pa	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	701509	4,396.17		0.00148333	45.65	78,25
376300-Mains - Plastic	20904155099	007516	Replace PBS main 130th and Byars Pa	F0604	Main Regiacement - ISRS (S)	Addition	ISRS-Other	201510	(175.84)	1	0,00148333	(1.56)	(3.13
378000-Meas & Reg Station Equipment	21272155078	007530	Rebuild DRS 607	F0501	Station rebuild & replacement	Addition	ISRS-Other	201509	(30.02)		6.00238333	(0.50)	(0.86
376300-Mains - Plastic	20401155095	007531	AOR - Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	15RS-Other	201509	(325.75)		0.00148333	(5.38)	(5.80
376300-Malins - Pluxtic	20401143855	007532	Cast Iron Replacement Proj Phase 4	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	16,561.45	E	7 p.00148333	171,96	294.71
376300-Meins - Plastic	20401143855	007532	Cast Iron Replacement Proj Phase 4	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	(466.69	2	5 0,00148333	(3.46)	(8.32
376300-Mains - Plastic	20401143855	007532	Cast Iron Replacement Proj Phase 4	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	\$52.79		4 0.00148333	328	2.83
376100-Mains - Steel	21271155077	007571	Main Replacement for DR 607 Inlet a	F0665	Replace steel & plestic main	Addition	ISRS-Other	201509	(61.25		7 0,0014833	(0,63	(1.09
376300-Mains - Plastic	20904155109	007576	Replace Zin PBS White and 148th Ter	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	1.37		7 0.00148333	0.01	0.0:

Missouri Gas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Fundina Prof. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Dopr Mo. Rate	Accum. Door	Dent Expense
376300-Mains - Plastic	21001155065	007591	Repl 255ft of 6in 85 W/ Ain PE.	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(9,205.00)	. 7	0.00148333	(95.58)	[163.85]
									-				
37G300-Mains - Plastic	20505155107	007593	2in PBS Main Replacement	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(64.79)	7	0.00148333	(0.67)	(1.15)
376300-Mains - Plastic	Z1001155066	007597	Repl 182ft of Jin 85 with 2in PE	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(82.51)	7	0,00148333	(0.86)	(1.47)
376300-Mains - Plastic	20301155111	007601	Replace PBS main to eliminate DRS 9	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201510	243,671.01	e	0.00148333	2,168.67	4,337.33
376300-Mains - Plastic	20301155111	007601	Replace PBS main to eliminate DRS 9	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201511	52,13		0.00148333	¢.39	0.93
376300-Mains - Plastic	20301155111	007601	Replace PBS main to eliminate DRS 9	F0004	Main Replacement - ISRS (5)	Addition	ISRS-Other	201512	399.97		0.00148933	2,37	7.12
376300-Mains - Plestic	20501155106	007652	Zin PBS Main Replacement	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201509	3,722.33		0.00148333	38.65	66.26
376300-Mains - Plastic	20501155106	007652	Zin 985 Main Replacement	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201510	15,764.86		0,00148333	140.31	280,61
376300-Mains - Plastic	20501155106	007652	2In PBS Main Replacement	F0S44	Replace barg steel main - safety re	Addition	ISRS-Other	201511	739.56		0.00148333	5.49	13,16
37G300-Mains - Plastic	20501155106	007652	2in PBS Main Replacement	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201512	(464.38)		0.00148333	(2,76)	(8.27
375300-Mains - Plastic	20401155118	007654	AOR 4in CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	3,565.71	- 3	0.00148333	37.02	63.47
376300-Mains - Plastic	20401155118	007654	AOR 4In CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	(11,772,75)		0,00148333	(69.85)	1209.55
376300-Mains - Plastic	20901155097	007672	Replace 2in PBS alley E of Walnut f	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(106.40)		0.00148333	(1.10)	(1.89
376300-Mains - Plastic	20901155097	007672	Replace 2in PBS alley E of Walnut f	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201510	(17,35		0.00148333	(0.15)	(0.31
376300-Mains - Plastic	20801155143	007693	Repl 178ft of 2in Bare Steel Main w	F0573	Replace bare steel main - safety re	Addition	tSRS-Other	201509	(17.66		0.00148333	(0.18	(0.31
376300-Mains - Plastic	20810155146	007706	Repl Main Odell and Missouri	F0592	Replace bare steel main - safety re	Addition	ISRS-Other	201511	208,271,54		5 0.00148333	1,544.68	3,707.23

Missouri Cas Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Proj. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo, Rate	Accum, Depr	Depr Expense
376300-Mains - Plastic	20810155146	007706	Repl Main Odell and Missouri	F0592	Replace bare steel main - safety re	Addition	ISRS-Other	201512	1,596.07		0.00148333	9,47	28.41
376300-Mains - Plastic	21001143861	007789	REPLACE 2151ft of PBS and PCS WITH	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(233.55)	7	0.00148333	(2.43)	(4.16
37G300-Mains - Plastic	21001155067	007790	Repl 165ft of 3in BS w/ 4in PE.	F0678	Replace bare steel main - safety re	Addition	isRs-Other	201509	(19.25)	7	0.00148333	(0.20)	(0.34
37G300-Mains - Plastic	21001155132	007824	Repl 612ft of 4in b/s with 4in PE	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201509	16.76	7	0.00148333	0.17	0.30
376300-Mains - Plastic	20401155219	007826	AOR - 8in Cl Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(115.40)	7	0.00148333	(1.20)	(2.05
376300-Mains - Plastic	20906155221	007828	Replace 2(n pbs main	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	3,196.20	7	0.00148333	33.19	56.89
376300-Mains - Plastic	20906155221	007828	Replace 2in pbs main	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201510	(57.84)		0.00148333	(0.51)	(1.03
376300-Mains - Plastic	20401155181	007861	Cast Iron Replacement project Phase	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	2,614.90	-	0.00148339	27.15	46.55
376300-Mains - Plastic	20401155181	007861	Cast iron Replacement project Phase	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	(16.48)		0.00148333	(0.12)	(0.29
376300-Mains - Plastic	20812155156	007862	2in PBS and 2in PCS Main Replacemen	F0634	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(111.25)		7 0.00148333	(1.16)	(1.98
376300-Mains - Plastic	20401155164	007864	Cast Iron Replacement Proj KC Ph S	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	14,593.09		7 0.00148333	151.52	259.76
376300-Mains - Plastic	20813155154	007865	2in PBS Main Replacement	F0634	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(99.26	,	0.00148333	(1.03)	(1.77
376300-Mains - Plastic	21001155187	007866	Replace 560ft of 4in b/s with 4in P	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201509	214.50			2.23	3.82
376200-Mains - Cast Iron	20401155121	007901	AOR Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(93,114.83		0.00148333	(966.84)	(1,657,44
376300-Mains - Plastic	20401155121	007901	AÓR Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	92,720.58		7 0.00148333		1,650.42
376300-Mains - Plastic	20904155148	007902	PBS Replacement 2inch PE	F0613	Replace bare steel main - safety re	Addition	ISRS-Other	201509	[283.64	).	7 0.00148333	3 (2.95)	(5.05

Missouri Que Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2015

Unility Account	MGE Work Order	New Work Order No.	Work Order Description	Funding Prot. No.	Evnaina Protect Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Accum. Deet	Depr Expense
76300-Mains - Plastic	21001155068	007904	Repl 1395 ft of 4in 85 w/ 4in PE	F0678	Replace bare steel main - sofety re	Addition	ISRS-Other	201509	(247.85)	7	0.00148333	(2.57)	(4.41
	7 8			16-2									
376300-Mains - Plastic	20201155082	007906	Replace PBS Main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201511	\$25,843.25	5	0.00148333	3,900.00	9,359.99
176300-Mains - Plostic	20201155082	007906	Replace PBS Main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201512	42,123.84	4	0,00148333	249.93	749.80
376300-Mains - Plestic	20501155157	007910	3in and 4in PBS Main Replacement	F0572	Main Replacement - ISRS (SW)	Addit(on	ISRS-Other	201512	111,335.89	4	0.00148333	660,59	1,981.77
376300-Mains - Plestic	20910155189	007926	Replace 2in pbs main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	5,173-17	7	0.00148333	53.71	92,08
376100-Mains - Steel	20401155201	007938	Replace 10in pbs main	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	(472.74)	7	0.00148333	(4.91)	[8.41
376100-Mains - Steel	20401155201	007938	Replace 10in pbs main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201511	(14.17)	.5	0.00148333	(0.11)	(0.25
376300-Mains - Plastic	21207155259	007961	3in PBS Main Replacement with 4	F0663	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(5.12)	,	0.00148333	[0.05]	(0.03
376300-Mains - Plestic	20501155247	008129	Zin PCS Main Replacement	F0575	Replace steel & plastic main	Addition	ISRS-Other	201512	228.70		0.00148333	1.36	4.07
376300-Mains - Plastic	20501155278	007141	Repl 2in PBS and PCS with 500ft	F0572	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(108.89)		0.00148333	(1,13)	(1.94
376300-Meins - Plastic	21001155243	008205	Repl 203ft of 2in PBS with 2in PE	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201511	18,830.25		0.00148333	139,66	335,18
376300-Mains - Plastic	21001155243	008205	Rept 203ft of Zin PBS with Zin PE	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201512	1,360.80	-	0.00148333	8,07	24.22
376300-Mains - Plastic	20501155263	008212	Duquesne Rd 3in PCS Main Replacemen	F0575	Replace steel & plastic main	Addition	ISRS-Other	201512	47,010.27		0.00148333	278,93	B36.78
382000 Meter Installations-MGE	20901155299	008214	First Assembly of God 3M Rotary Reb	F0507	Rebuild Meter install 2" & Lg (S)	Addition	ISAS-Other	201509	1,692.13		0.00203333	24.08	41,29
37G100-Mains - Steel	20906155284	008238	Replace 8in PBS Main	F0604	Main Replacement - ISRS (S)	* Addition	ISRS-Other	201510	310,628.02		0.00148333	2,764.58	5,529,17
376100-Mains - Steel	20906155284	008238	Replace 8in PBS Main	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201511	(1,144.54	)	0.001483,33	(a.49)	(20.37
376100-Mains - Steel	20906155284	008238	Replace 8in PBS Main	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201512	454.21		0.00148333	2.69	8.08
378000-Meas & Reg Station Equipment	21271144038	008241	DR 384 RESUILD	F0501	Station rebuild & replacement	Addition	ISRS-Other	201509	(52.85	)	0.00238333	(0.88.0)	(1.51
378000-Mees & Reg Station Equipment	21271144038	008243	DR 384 REBUILD	F0501	Station rebuild & replacement	Addition	ISRS-Other	201509	(8.50	0	7 0.00238533	(0.14)	(0.24
382000 Meter Installations-MGE	20903155313	008244	Price Chopper 3M Rotary Meter Rebui	F0507	Rebuild Meter Install 2" & Lg (S)	Addition	ISRS-Other	201510	1,355.89		0.00203333	16,54	33.08

Missouri Cas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2015

Hillity Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Proi. No.	Funding Protect Coscription	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Accum Door	Depr Expense
82000 Meter installations-MGE	20903155313	008244	Price Chopper 3M Rotery Meter Rebui	F0507	Rebuild Meter Install 2" & Lg (5)	Addition	ISRS-Other	201511	(55.36)		0.00203333	(0.56)	(1.35
82000 Meter Installations-MGE	20903155313	008244	Price Chopper 3M, Rotary Meter Rebui	F0507	Rebuild Meter Install 2" & Lg (S)	Addition	ISRS-Other	201512	3.92	4	0.00203333	0.03	0.20
82000 Meter Installations-MGE	20903155314	008245	Midwest Inn 7M Rotary Meter Rebuild	F0507	Rebuild Meter Install 2" & Lg (S)	Addition	1585-Other	201510	1,793.78	8	0.00203333	21,88	43.77
82000 Meter Installations-MGE	20903155314	008245	Midwest inn 7M Rotary Meter Rebuild	F0507	Rebuild Meter Install 2" & Lg (S)	Addition	ISRS-Other	201511	(142.36)	5	0.00203333	(1.45)	(3.47
182000 Meter Installations-MGE	20903155314	008245	Midwest inn 7M Rotery Meter Rebuild	F0507	Rebuild Meter Install 2" & Lg (5)	Addition	ISRS-Other	201512	(24.24)	4	0.00203333	(0.20)	(0.59
376300-Mains - Plostic	20401155274	008247	din and 6in Cast Iron Repl. 2In PE	F0599	Mein Replacement - ISRS (N)	Addition	ISRS-Other	201509	566.84	7	0.00148333	5.89	10,09
376300-Maine - Plastic	20401155274	908247	4in and Gin Cast Iron Repl. 2in PE	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	(1,681.85)	4	0.00148333	(9.38)	(29.94
37630D-Mains - Plastic	20401155319	008274	AOR - 6(n Cl Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(56.19)	- 7	0.00148333	(0.58)	(1.00
376300-Maine - Plastic	20401155319	008274	AGR - Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	(19.72)	5	0.00148939	(0.15)	(0.35
376300-Mains - Plastic	20401155292	308360	Cast Iron Replacement proj KC Ph7	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	1,253,007.12	6	0.00148333	11,151.74	22,303.48
376300-Mains - Plastic	20401155292	008360	Cast Iron Replacement proj XC Ph7	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	(2,259.41)	5	0.00148333	(16.76)	(40.22
376300-Mains-Plastic	20401155292	008360	Cast iron Replacement proj KC Ph7	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	(614.53)		0.00148333	(3.65)	[10.94
376300-Mains - Plastic	21251155011	008361	Replace Ain PE with 2in PE at 74 an	F0636	Replace steel & plastic main	Addition	ISRS-Other	201512	405.07		0.00148333	2,40	7.21
37G100-Mains - Steel	20401155333	008365	Sinch PCS Replacement	F0665	Replace steel & plastic main	Addition	ISRS-Other	201509	(11.02)	1	0.00148333	(0.11)	(0.20
376300-Mains - Plastic	21272155334	008366	8in PBS Relocation	F0523	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(1,080.31		0.00148333	(11.22)	(19.2)

Missouri Gas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	AGE Work Order No.	New Work Order No.	Work Order Description	Funding Prol. No.	Funding Project Description	FERC Activity	Catagory	Month	Addition Amount	Months	Depr Mo. Rate	Assum, Dept	Dent Expense
176300-Mains - Plestic	20403155301	008389	Cast Iron Replacement project phase	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	914,041.10	0	0.00148333	8,134.95	16,269,90
		A PARTINO				Sea Tarrel							10.0
375300-Mains - Plestic	20401155301	008389	Cast Iron Replacement project phase	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	(176.58)	5	0.00148333	(1.31)	(3,15
								1				4750	
37G300-Majns - Plastic	20401155301	008389	Cast Iron Replacement project phase	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	9,209.37	4	0.00148353	54.64	163.93
376300-Mains - Plastic 376300-Mains - Plastic	20401155172	008390 008390	SIN CI REPLACEMENT	F0500	Replace cast fron main - CPI / prio Replace cast fron main - CPI / prio	Addition Addition	ISRS-Other	201509	3,090.33	,	0.00148333	32,09 18,45	55.01 36.89
376300-Mains - Plastic	20403155172	008390	BIN CI REPLACEMENT	F0500	Replace cast fron main - CPI / prio	Addition	ISRS-Other	201511	213.86	- 6	0.00148333	1.59	3.81
37G3OD-Mains - Plastic	20403155172	008390	BIN CI REPLACEMENT	F0500	Replace cast iron main - CPI / prio	Addition	ISRS-Other	201512	(56.25)		0.00148333	(0.33)	(1.00
376100-Mains - Steel	20401155340	008391	2in PCS Replacement	F0665	Replace steel & plastic main	Addition	ISRS-Other	201509	(7.75)	7	0.00148333	(0.08)	(0,14
376100-Mainz - Steel	21271155342	008392	Zin CS Replacement	F0665	Replace steel & plastic main	Addition	ISRS-Other	201509	(6,38)	7	0.00148339	(0.07)	(0.11
376100-Mains - Steel	21271155342	008392	2in CS Replacement	P0665	Replace steel & plastic main	Addition	ISRS-Other	201510	(0.01)		0.00145333		+
376100-Mains - Steel	20401155343	008393	Jin PCS Replacement	FOGGS	Replace steel & plastic main	Addition	ISRS-Other	201509	(3.70)	7	0.00148333	(0.04)	(0.0)
376100-Mains - Steel	20401155343	008393	3in PCS Replacement	F0665	Replace steel & plastic main	Addition	ISRS-Other	201511	851.17		0.00148333	6.31	15.33
376100-Mains - Steel	20401155343	008393	3in PCS Replacement	F0665	Replace steel & plastic main	Addition	ISRS-Other	201512	(22.36)		0.00148333	(0.13)	(0.46
37G100-Mains - Steel	21271155344	008394	2in PCS Replacement	FOGGS	Replace steel & plastic main	Addition	ISRS-Other	201509	(32.24)	,	0.00148333		(0.5
376300-Mains - Plastic	20401155317	008395	Cast iron Replacement Project Phase	P0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	2,025,509.94		5 0.00148333	7,591.01	18,218.4
376300-Mains - Plastic	20401155317	008395	Cast Iron Replacement Project Phase	F0599	Main Replacement - ISRS (N)	Addition	15RS-Other	201512	(110,737.80)		4 0.00148333	(657.04)	(1,971.1
376100-Mains - Steel	20601155110	008398	Replace 2in Valve due to Leakage 20	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(22.57)	5	0.00148333	(0.23)	(0.4
376300-Mains - Plastic	21207155346	008399	4in PBS Replacement -3rd pty damage	F0613	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(36,25		7 0.00148333		-
376100-Mains - Steel	21258155347	008400	2in PCS and Valve replacement	F0665	Replace steel & plastic main	Addition	ISRS-Other	201509	(32.66	1	0.00148333		(0.5
376300-Mains - Plastic	21001155233	008533	Repl 333ft of 2in and 4in b/s main	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201509	20,308.01	1200	0.00148333		361.4
376300-Mains - Plastic	21001155233	008533	Repl 333ft of 2in and 4in b/s main	F0678	Replace hare steel main - safety re	Addition	ISRS-Other	201510	1,829.70		0.00148333	16.28	32.5

Missouri Cas Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MQE Work Order No.	New Work Order No.	Work Order Description	Funding Proi. No.	Funding Project Description	FERG Activity	Category	Month	Addition Amount	Months	Dept Mo. Rate	Accum. Door	Dent Expense
376300-Mains - Plastic	21001155233	008533	Repl 333ft of 2in and 4in b/s main	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201311	(1,117.00)	5	0.00148333	(8.28)	(19.82)
876300-Mains - Plastic	21001155233	008533	Repl 333ft of 2in and 4in b/s main	F0678	Replace bare steel main - safety re	Addition	ISRS-Other	201512	21,05	4	0.00148333	0,12	0.37
376300-Mains - Plastic	20401155365	008537	AOR - 4in and 6in CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(571.37)		0.00148933	(5.93)	(10.17
37G300-Mains - Plastic	20401155365	008537	AOR - 4in and 5in Cl Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	1,080.43	5	0.00148333	8.01	19.23
376300-Mains - Plastic	20401155365	008537	AOR - 4in and 6in CI Replacement	F0599	Main Replacement -ISRS (N)	Addition	SRS-Other	201512	(32.90)		0.00148333	(0.20)	(0.59
376300-Mains - Plastic	20401155320	008541	AOR - GIn CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	1,620,33	3	0.00148333	16.82	28.84
376300-Mains - Plastic	20401155320	008541	AOR - Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	65.99		0.00148333	0.49	1.17
376300-Mains - Plastic	20502155309	008543	3in and 2in PBS Main Replacement	P0544	Replace bare steel main - safety re	Addition	ISRS-Other	201510	23,262.29		0.00148333	207.03	434.07
376300-Mains - Plestic	20502155309	008543	Sin and 2In PBS Main Replacement	F0544	Replace bare steel main - safety (e	Addition	1SRS-Other	201511	1,110.92		0.00148333	8.24	19.77
376300-Mains - Plastic	20502155309	008543	3in and 2in PBS Main Replacement	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201512	(39.05)	-	0.00148333	(0.23)	j0.7c
376300-Mains - Plastic	20501195264	008546	12th St and Illinois Ave 4in PSS Ma	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201510	155,647.63		0.00148333	1,385.26	2,770.52
376300-Mains - Plastic	20501155264	008546	12th St and Illinois Ave 4in PBS Ma	F0544	Replace bare steel main - safety re	Addition	ISRS-Other	201511	675.11		5 0.00148333	5.01	12.02
37G3D0-Mains - Plastic	20501155264	008546	12th St and Illinois Ave 4in PBS Ma	F0544	Replace bare steel main - safety re	Addition	tSRS-Other	201512	1,214.31		4 0.00148333	7.20	21,61
376300-Mains - Plastic	20401155359	008548	ACR - Bin Cl Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(273.76)		7 0.00148333	(2.84	(4.87
376300-Mains - Plestic	20401155359	008548	AOR - Bin Cl Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	166.38		5 0.00148333	1.23	2.96
376300-Mains - Plastic	20902155308	008549	Replace 2in & 3in PCS/P85	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201511	204,951.25		5 0.00148333	1,520.05	3,648,1
376300-Mains - Plastic	20902155308	008549	Replace 2 in 8, 3 in PCS/PBS	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201512	15,728.26		4 6.00148333	93.32	279.90
37G300-Majns - Plastic	20806155332	008633	2in PBS replacement due to CP and L	F0634	Replace bare steel main - safety re	Addition	ISRS-Other	201509	2,383.79		7 0.00148333	24.75	42.43

Missouri Clas Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Eatimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Quiter No.	Work Order Description	Prot. No.	Eunding Proinct Coscription	FERC Activity	Category	Month	Addition Amount	Months	Dani Mo, Rate	Accum Dept	Depr Expense
876300-Mains - Plestic	20401155356	008635	Cent iron Regiscement Proj Phase 10	E0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	326,099.15		0.00148333	2,418.56	5,804.55
7 D. DODINI (UT) - F. Walle	20401233338	003033	Cast in the method result in the state of th	10333	Main Replacement - Sho (N)	Addition	13A3-Other	201311	326,089.13		0.001483333	2,418.36	9,804.33
376300-Mains - Plestic	20401155356	008635	Cast fron Replacement Proj Phase 10	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	195,269.68		0.00148333	1,158.60	3,475.79
376300-Mains - Plastic	21001155322	008636	Replace 2in PBS/PCS & Gin P	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201510	233,198.40		0.00148333	2,075,46	4,150.92
376300-Mains - Plastic	21001155322	008636	Replace Zin PBS/PCS & Gin P	F0604	Main Replacement -ISRS (S)	Addition	ISRS-Other	201511	(25.83)		0.00148333	(0.19)	(0.46)
376300-Mains - Plastic	21001155322	008636	Replace 2In PBS/PCS & 6in P	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201512	901.12	7	0.00148933	5.35	16.04
376100-Mains - Steel	20923155370	008675	4in PCS Main Replacement	FOGOS	Replace steel & plastic main	Addition	ISRS-Other	201509	(3.61)		0.00148533	(0.04)	(0.06
37G200-Mains - Steel	20923155370	008675	4in PCS Main Replacement	P0605	Replace steel & plastic main	Addition	ISRS-Other	201510	(0.47)		0.00148333	-	(0.01
376300-Mains - Plastic	20201155147	008682	Replace 6in PCS 4in PCS/P8S &	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201511	159,570.86		0.00148333	1,183,48	2,840.35
376300-Mains - Plastic	20201155147	008682	Replace 6In PCS 4In PCS/P8S &	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201512	[4,475.49]		0.00148333	(26.55)	[79.66
376300-Mains - Plastic	20902155383	008731	Replace 4in PBS- 83rd St	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(2,319.34		0.00148333	(13.70)	[23.48
37G300-Mains - Plastic	20902155383	008731	Replace 4in PBS- B3rd St	F0604	Main Replacement - (SRS (S)	Addition	15RS-Other	201512	98.24	-	0.00148333	0.58	1,75
376300-Mains - Plastic	20902155375	008740	Replace 4In PBS- Westridge Rd	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	{2,390.49	)	7 0.00148333	(24,82)	142.55
376300-Mains - Plastic	20902155375	008740	Replace 4in PBS- Westridge Rd	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201512	65.87		0.00148333	0.39	1,17
382000 Meter Installations-MGE	20903155419	008797	Chapel Hill Church 3M Rebuild SLRP	F0507	Rebuild Meter Install 2" & Lg (S)	Addition	ISRS-Other	201510	1,279,42		0.00203333	15.61	31,22
382000 Meter Installations-MGE	20903155419	008797	Chapel Hill Church 3M Rebuild SLRP	F0507	Rebuild Meter Install 2" & Lg (5)	Addition	ISRS-Other	201511	(142.36		5 0.00203333	(1.45)	(3.47
382000 Meter Installations-MGE	20903155419	008797	Chapel Hill Church 3M Rebuild SLRP	F0507	Rebuild Meter Install 2" & Lg (S)	Addition	ISRS-Other	201512	(24.24	)	4 0.00203333	(0.20)	Ja.59
382000 Meter Installations-MGE	20903155417	008798	Winsteads 3M Rebuild SLRP	F0507	Rebuild Meter Install 2" & Lg (S)	Addition	ISRS-Other	201509	2,760.97		0.00203333	39,30	67.37
382000 Meter Installations-MGE	20901155415	008799	RLDS Church 3M Rebuild SLRP	F0507	Rebuild Meter Install 2" & Lg (5)	Addition	ISRS-Other	201510	3,309.62		6 0.00203333	40.38	80.75

Missouri Cas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2018

Hillity Account	MGE Work Order No.	Order No.	Work Order Description	Prol. No.	Funding Protect Description	FERC Activity	Category	Month	Addition. Ameent	Months	Door Mo. Rate	Accum. Depr	Depr Exponer
82000 Meter installations-MGE	20901155415	008799	RLDS Church 3M Rebuild SLRP	F0507	Rebuild Meter Install 2" & Lg (S)	Addition	ISRS-Other	201511	(482,27)		0.00203333	(4.90)	(41.77
agood weter instantions wide	20301133413	004/99	REDS CHUICH SW REBUIRS SCRP	Fusur	wepfild weter meral 5 at 18 (2)	Addition	isro-other	201317	(48gaza)		0.00203333	(4,30)	(11.77)
82000 Meter Installations-MGE	20901155415	008799	RLDS Church 3M Rebuild SLRP	F0507	Rebuild Meter Install 2" & Lg (5)	Addition	ISRS-Other	201512	(36.96)		0.00203333	(0.30)	(0.90
76300-Mains - Plastic	20201255425	008890	Replace Bare Steel-Waldo Ave	F0546	Replace bare steel main - safety re	Addition	ISRS-Other	201509	58,630,49	7	0.00148333	608,78	1,043.62
76300-Mains - Plastic	20201155425	008890	Replace Bare Steel-Waldo Ave	F0546	Replace bare steel main - safety re	Addition	ISRS-Other	201510	219.23		0.00148933	1,95	3.90
176300-Mains - Plastic	20201155425	008890	Replace Bare Steel-Woldo Ave	F0546	Replace bare steel main - safety re	Addition	ISRS-Other	201511	(1,853.50)	-	0.00148333	(13.75)	(32,99
876300-Mains - Plaetic	20201155425	008890	Replace Bare Steel-Waldo Ave	F0546	Replace bare steel main - safety re	Addition	ISRS-Other	201512	127.00	4	0.00148333	0.75	2,26
376300-Mains - Plastic	20902155460	009153	Relocate 4in plus main	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201511	8,429.30		0.00148333	62.52	150.04
376300-Mains - Plastic	20902155460	009133	Relocate 4in pbs main	F0604	Main Replacement - (SRS (S)	Addition	ISRS-Other	201512	12.96		0.00148333	0.08	6.23
376300-Mains - Plastic	20813155491	009136	2in Main Ropiacoment	F0592	Replace bare steel main - safety re	Addition	ISRS-Other	201511	22,925.12		0.00148333	170.03	408.07
376300-Mains - Plastic	20813155491	009136	2in Main Replacement	F0592	Replace bare steel main - safety re	Addition	ISRS-Other	201512	1,097.49		0.00148333	6.51	19.54
376300-Mains - Plastic	20201155497	009227	Replace 4in pbs main	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201510	46,359.87		0.00148333	412,60	825,20
376300-Mains - Plastic	20201155497	009227	Replace 4in pbs main	F0504	Main Replacement - ISRS (S)	Addition	ISRS-Other	201511	10,325.44		0.00148333	76,58	183.79
376300-Mains - Plastic	20201155497	009227	Replace 4in pbs main	F0604	Main Replecement - ISRS (S)	Addition	tSRS-Other	201512	(440.22	)	0.00148333	(2.61)	(7.84
376300-Meins - Plastic	20501155480	009236	Wall Ave 2995' PBS Main Reglacement	F0572	Mein Replacement - ISRS (SW)	Addition	ISRS-Other	201512	170,78 <b>G.3</b> 7		0.00148333	1,013.33	3,039.99
376300-Meins - Plastic	20806155485	009239	Repl PBS with 382 ft 2in Plastic Ma	F0592	Replace bare steel main - safety re	Addition	ISRS-Other	201511	22,355.08		0.00148333	165.80	397.92
376300-Mains - Plastic	20806155485	009239	Repi PBS with 382 ft 2in Plastic Ma	F0592	Replace bare steel main - safety re	Addition	ISRS-Other	201512	1,085.07		0.00148333	G.44	19.31
376300-Mains - Plastic	20401155483	009249	AOR - 8in C. Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	23,951,50		0.00148333	213.17	426,34
376300-Mains - Plastic	20401155483	009249	AOR - Bin Ci Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	(448.62		0.00148333	(3.33)	(7.99
376300-Mains - Plastic	20401155483	009249	AOR - Bin Cl Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	11.11		0.00148333	0.07	0.20
376300-Mains - Plastic	20401155464	009251	AOR - Gin Cl Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	8,281.95	4	0.00148333	73.71	147.42
376300-Mains - Plastic	20401155484	009251	AOR - Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	2,357.86		0.00148333	17.49	41.97
376300-Mains - Plastic	20401155484	009251	AOR - Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	(189.42	)	0.00148333	(1.12)	(3.87
376101-MGE-Mains Steel-Transmission	20903155506	009253	Hydrotost the GV Lateral Transmissi	F0604	Main Replacement - ISRS (S)	Addition	ISRS-Other	201511	767,113,59		5 0.00148333	5,689.41	13,654.59
376101-MGE-Mains Steel-Transmission	20903155506	009253	Hydrotest the GV Lateral Transmissi	F0604	Main Replacement - ISRS (5)	Addition	ISRS-Other	201512	65,637.38		4 0.00148333	389.45	1,168.34
376300-Mains - Plostic	20401155463	009274	Replace 3in PCS, 1.25in PE, 2	F0613	Replace bare steel main - safety re	Addition	ISRS-Other	201510	31,814.07		6 0.00148333	283.14	566.25

Missouri Qea Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Eatimates for January and February 2015

Itlifty Account	MGE Work Order No.	New Work Order No.	Work Order Description	Proj. No.	Funding Protect Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Accum, Dopt	Door Expense
76300-Mains - Plattic	20401155463	009274	Replace 3in PCS, 1.25in PE, 2	F0613	Replace bare Steel main - safety re	Addition	ISRS-Other	201511	25,134.18	5	0.00148333	186.41	447.3
576300-Mains - Plastic	20401155463	009274	Replace 3in PCS, 1.25in PE, 2	F0613	Replace bare steel main - safety re	Addition	ISRS-Other	201512	4,695.83		0.00148333	27.86	83.5
76300-Mains - Plastic	N/A	800036	20th and Malden Lane Relocation		Main Replacement - ISRS (SW)	Addition	ISRS-Other	201512	3,243.54	4	0.00148333	19.25	57.7
s76300-Mains - Plastic	20501132871	003807	20th & Ozark Reloc PCS w 370'-4ln;5	F0664	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201509	(9.61)	7	0.00148333	(0.10)	(0.1
176100-Mains - Steel	21274132678	003876	NE Gath Reloc PCS w 682'-4in PE mai	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201509	(49,41)	7	0.00148333	(0.51)	(0.8
376300-Maine - Plaxtic	20501122022	003999	19th & Malden Reloc PCS/PE w 1965'-	FDGG4	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201509	(219.61)	7	0.00148333	(2.28)	(3.9
376100-Mains - Steel	21001143364	004035	26th & Frederick Reloc PCS w 56'-41	F0617	Street & highway relocates	Addition	Public Improv	201510	5,809.34		0.00148333	51.70	103.4
376100-Mains - Steel	21001143364	004035	26th & Frederick Reloc PCS w 56'-41	F0617	Street & highway relocates	Addition	Public Improv	201511	489.86		0.00148333	3.63	8.7
776100-Mains - Steel	21001143364	004035	26th & Frederick Reloc PCS w 56'-41	P0617	Street & highway relocates	Addition	Public Improv	201512	161.10		0,00148333	0,96	2,8
37G300-Mains - Plastic	20812143354	004134	Main & Elm Reloc PBS w 1895'4In PE	F0545	Street & highway relocates	Addition	Public Improv	201509	(6,60)		0.00148333	(0.07)	(0.1
376100-Mains - Steel	20403132947	004141	Lees Summit. Rd. 20In Relac Proj	F0623	Street & highway relocates.	Addition	Public Improv	201509	623,64		0.00148353	6.48	12,1
.376100-Mains - Steel	20501121966	004161	26th & Schiffendecker Reloc Main WI	F054C	Street & highway relocates - safety	Addition	Public Improv	201509	(25.09		0.00148333	(0.26)	(0,4
376300-Mains - Steel	20501121593	004179	S0th & Indiana Reloc 5962'-Ain PE m	F0GG4	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201509	(0.66		7 0.00148333	(0.01)	(0.0
		148			4-2-5								

Missouri Oas Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prof. No.	Funding Project Description	FERG Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Acoum, Deor	Deer Expense
						15:					_		
378000-Mear & Reg Station Equipment	20401132618	004380	Build DRS 100 LS Rd and GV Lateral	FOS78	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201510	3.65		0.00238333	0.05	0.10
378000-Meas & Reg Station Equipment	20401132618	004380	Bulld DRS 100 L5 Rd and GV Lateral	F0578	Street & Highway Relocates ISRS (5)	Addition	Public Improv	201512	(0.13)	4	0.00238933		3
376300-Maine - Plastic	20308143365	004389	22nd & Shelby Repl PBS w 410'-Zin P	F0S49	Street & highway relocates - safety	Addition	Public improv	201509	(4,65)	7	0.00148333	(0.05)	(0.08)
376100-Mains - Steel	20908143266	004394	291 & Cammercial Reloc CS w 1659'-6	F0578	Street & Highway Relacates ISRS (5)	Addition	Public Improv	201509	(0.17)		g.00148333		
376300-Mains - Plastic	20208143266	004394	291 & Commercial Reloc CS w 16591-6	F0578	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201509	(13,13)	7	0.00148333	(0.24)	(0.23)
376300-Mains - Plastic	20501133062	004450	20th & Wiscontin Reloc 120'-8;1250'	F0664	Street & Hwy Relocator (SRS (SW)	Addition	Public Improv	201509	(1.48)		0.00148333	(0.02)	(50.03)
376100-Mains - Steel	20401132400	004645	Kenses City Street Car Phase 2	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201509	(33,63)	-	7 0.00148333	(0.35)	(0.60
37G300-Mains - Plastic	20401132400	004645	Kansas City Street Car Phase 2	F0547	Street & Highway Relocator ISRS (N)	Addition	Public Improv	201509	(0.91		7 0.00148333	[6.01]	(0.02
376100-Mains - Steel	20401132402	004654	KC Street Car Ph 3 Reloc Ci, PBS w	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201509	(1,166,14		7 0.00148333	(12.11)	(20.76
376300-Maina - Plastic	20401132402	004654	XC Street Car Ph 3 Reloc Cl, PBS W	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201509	(23.19		7 0.00148333	(0.24	(0.41

Missouri Oss Energy - MOE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prot. No.	Funding Protest Onscription	FERC Activity	Catagory	Month	Addition Amount	Months	Denr Mo. Rate	Accum. Depr	Depr Expense
						المراجعة الم							
776100-Mains - Steel	20901232732	004893	Colbern & Unity Way Reloc PBS w 550	F0514	Other relocates	Addition	Public Improv	201509	(3.65)	. 7	0.00148333	(0.04)	(0.06)
37G1DD-Mains - Steel	20307143483	005030	Gth & Main Reloc4in PCS dogleg Sto	F0578	Street & Highway Relocates ISRS (5)	Addition	Public Improv	201509	(23.25)	7	0.00148553	(0.24)	(0.41)
376100-Mains - Steel	20307143483	005030	6th & Main Reloc 4in PCS dogleg Sto	F0578	Street & Highway Relocates ISRS (5)	Addition	Public Improv	201510	(10.17)		0.00148333	(eo.o)	(0,28
376300-Mains - Plastic	20506143552	005251	171 & Pearl Real PBS w 625'-2'n PE	F0664	Street & Husy Relocates ISRS (SW)	Addition	Public Improv	201509	14.80	7	0.00148333	0.15	35.0
376300-Mains - Plastic	20401143309	005270	Blue Pkwy Repi PBS/PE w 2557'-4in;1	F0595	Street & highway relocates	Addition	Public Improv	201509	(594.57)	-	0.00148333	[6.17]	(10.58
37G300-Mains - Plastic	21001143363	005331	Frederick & Kemper Rejoc 20'-Zin PE	F0617	Street & highway relocates	Addition	Rubiic improv	201509	(12.61)		0,00148333	(0.13)	(0.22)
376300-Mains - Plastic	21001143363	005333	Frederick & Kemper Reloc 20'-Zin PE	F0617	Street & highway relocates	Addition	Public Improv	201510	(2.55)		0.00148333	(0.02)	(0.05
976300-Mains - Plastic	20812143611	005492	Hines & Mein Repl PBS/PCS w 5775-2	F0545	Street & highway relocates	Addition	Public Improv	201509	(579.84)		0.00148333	(6.02)	(10.32
376300-Mains - Plastic	21207143502	005515	73rd Crt Reloc PCS w 325'-Gin TF St	F0595	Street & highway relocates	Addition	Public Improv	201509	(94.94)		0,00148333	(0.92)	(1.69
376300-Mains - Plastic	21207143502	005515	73rd Crt Reloc PCS w 325'-Gin TF St	F0595	Street & highway relocates	Addition	Public Improv	201510	(71.45)		0.00148333	(0.64)	(1.27
376300-Mains - Plastic	21205143503	005516	Pleasant Valley Rd Reloc PBSPCS w 1	F0595	Street & highway relocates	Addition	Public Improv	201509	(245.55)		7 0.00148333	(2.55)	(4.37
376300-Mains - Piestic	20501143621	005551	11th & Highview Reloc Pts w 1245'-2	F0546	Street & highway relocates - safety	Addition	Public Improv	201509	9.87		7 0.00148333	0.10	G.18
376300-Mains - Plastic	20501143622	005555	Rolla & Brownell Reloc PBS w 1285'-	F06G4	Street & Hwy Relocates ISRS (SW)	Addition	Public improv	201509	(53,54		7 0.00148333	(0.56	(0.95
376100-Mains - Steel	20307143658	005633	7th & Orange Reloc pcs w 18-Gin CS	F0578	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201509	(1.88	1 =	7 0.00148333	(0.02)	(0.03
376100-Mains - Steel	21274143634	005687	S6th Terr Reloc 20'-2in CS main		Street & Highwey Relocates ISRS (N)	Addition	Public Improv	201509	(6.73		0.00148333		
376300-Mains - Plastic	21207143620	005732	Franklin St Reloc PBS w 1402'-4;70'	F0547	Street & Highway Relocates ISRS (N)	Addition	Public improv	201509	9.05		7 0.00148333		

Missouri Cas Energy - MGE ISRS Work Order Additions Soptember 2015 - December 2015 with Estimates for January and February 2016

Julity Account	MOE Work Order	New Work Order No.	Work Order Description	Funding Prol. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Dept Mo. Rate	Accum. Oppi	Deor Expense
17630C-Mains - Plastic	20501143667	005733	Set & McKinley Reloc PBS w 1215'-21	F0G64	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201509	42,39	7	0.00148333	0.44	0.75
576300-Mains - Steel	20513143661	005787	Pennel & Summit Reloc BS/CS w 485'-	F054G	Street & highway relocates - safety	Addition	Public Improv	201509	(2.50)		0.00148333	(0.03)	(0.04
576300-Mains - Plastic	20513143661	005737	Pennel & Summit Reloc BS/CS w 485'-	FQ54G	Street & highway rejocates - safety	Addition	Public Improv	201509	(20.65)		0.00148553	(0.21)	(0.37
376100-Mains - Steel	21271143554	005772	NE Kelsey Relac PCS/PBS w 100'-4in	F0497	Street & highway relocates - safety	Addition	Public Improv	201509	(71.30		0,00148333	(0.74)	(1.27
376300-Mains - Plastic	21271143554	005772	NE Kelsey Reloc PCS/PBS w 100'-4in	F0497	Street & highway relocates - safety	Addition	Public Improv	201509	(15.63		0.00148333	(010)	(0.28
376300-Mains - Plettic	21213143676	006075	Excelsior Springs Public Improvemen	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201509	(104.98		0.00148333	(2.09)	(1,87
376300-Mains - Plastic	20925143728	006423	Relocate Gin PE MoDOT Walnut to AA	F0578	Street & Highway Relocator ISRS (S)	Addition	Public Improv	201509	4,411.61		7 0,00148333	45.81	78,53
376500-Mains - Plastic	20501143693	006491	Relocate Main Due to Sidewalk Proje	F0664	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201509	(472.53	1	7 0,00148333	(4.91	(8.4)
376100-Mains - Steel	20401143774	006433	Relocate 220'-Bin PBS with Thin Fil	FG497	Street & highway relocates - safety	Addition	Public Improv	201509	(260.48		7 0.00148333	(2.70	(4.64
37G100-Mains - Steel	20901143349	006716	Relocate 4in pbs main	F0549	Street & highway relocates - safety	Addition	Public Improv	201509	(7,29		0.00148333	(0.08	(0,1:
376300-Mains - Plastic	20901143349	006716	Relocate 4in abs main	F0549	Street & highway relocates - safety	Addition	Public Improv	201509	(471.80		7 0.00148333	(4.90	(8.4)
376300-Mains - Plastic	20501143892	005734	Relocate 6in PE Main due to Storm 8	F0664	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201509	(24.84	1	7 0.00148333	(0.26	(0.4
376300-Mains - Plastic	20401143595	006915	Replace BS with Zin and 4in	F0547	Street & Highway Relocator ISRS (N)	Addition	Public Improv	201509	(235.50	2	7 0.00148333	(2.45	(4.1:
376300-Mains - Plastic	20806144003	007171	Relocate Zin Steel Main due to Road	F0545	Street & highway relocates	Addition	Public Improv	201509	(214.54		7 0.00148333	(2.23	) (3.8
376300-Mains - Plastic	20501144049	007326	Relocate Sin PBS Due to Storm Impro	F0664	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201509	(58.55	0	7 0.00148333	(0.61	(1,0
376300-Mains - Plastic	20201155071	007392	Relocate 2in PE for storm 14th and	F0578	Street & Highway Relocates ISRS (S)	Addition	Public improv	201509	(35.39	9)	7 0.0014833	3 (0.37	)

Missouri Gas Energy - MOE 13R3 Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

ZIIIIty Account	MGE Work Order No.	New Work Order No.	Work Order Description	Prot. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Depr Mo. Rate	Accum, Depr	Ocor Excense
76300-Mains - Plastic	20501344063	007507	Relocate 10in PE Main due to Storm	FOGG4	Street & Hwy Relocator ISRS (SW)	Addition	Public Improv	202510	133,020.82		0.00148333	1,183.88	2,3 <i>67.7</i> 7
176300-Mains - Plastic	20501144063	007507	Relocate 10in PE Main due to Storm	F0664	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201511	388.64		0.00148333	2.88	6,92
376300-Mains - Plastic	20501144063	907507	Relocate 10in PE Main due to Starm	F0664	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201512	1,043.11	4	0.00148333	6.19	18,5
376100-Mains - Steel	20928155115	007573	Install two doglegs MoDOT 1353040	FOS78	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201509	1,833.78	7	0.00148333	19.04	32,6
376100-Mains - Steel	20928155115	007573	Install two doglegs MoDOT J353040	F0578	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201510	(4.19		0.00148333	(0.04)	{0.0
376300-Mains - Plastic	71251143812	007574	4in PE Relocation (Relmb)	F0547	Street & Highway Relocates ISRS (N)	Add(tion	Pub  c mprov	201509	(224.14)		0.00148533	(2.33)	(3.9
376300-Mains - Plastic	20904155120	007577	Replace Zin PBS 135th and Parker Pa	F0549	Street & highway relocates - xafety	Addition	Public Improv	201509	(141.42	)	0.00148333	(1.47)	(2.5.
376300-Mains - Plastic	20904155120	007577	Replace 2in P8S 135th and Parker Pa	F0549	Street & highway relocates - safety	Addition	Public Improv	201510	(25.39	) .	0.00148333	[0.23	(0.4
376300-Mains - Plastic	20904155124	007590	Replace main Salmont 137th to 139th	F0578	Street & Highway Relocates ISRS (5)	Addition	Public (mprov	201509	(109.73		7 6,00148333	(1:14)	[1.9
376300-Mains - Plastic	20901155137	007599	Relocate 4in PE MoDQT J4P2233 Black	F0578	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201509	(117.09	)	7 0.00148333	(1.22	(2.0
376300-Mains - Plastic	20501155166	007881	Relocate 4in PE for Storm Improveme	F0664	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201509	(486-37	)	7 0.00148333	(5.05	) (8.6
376300-Mains - Plastic	21240155217	007927	Zin Repi Clark Avenue Bridge Kopi C	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201510	(56.84	)	6 0.00148535	(0.51	) (1.0
376100-Mains - Steel 376100-Mains - Steel	20201155241	007969	Relocate Bin pcs main	F0578	Street & Highway Relocates ISRS (S)  Street & Highway Relocates ISRS (S)	Addition	Public Improv	201509	(104.01		7 0.00148333 6 0.00148333	(0.13	

Missouri Cas Energy - MGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2016

Utility Account	MGE Work Order No.	New Work Order No.	Work Order Description	Funding Prol. No.	Fundina Project Description	FERC Activity	Category	Month	Addition Amount	Months	Dapr Mo. Rate	Accum, Depr	Depr.Expense
376300-Mains - Plastic	20501155329	008310	Relocate 4In PE due to Storm Drain	F0664	Street & Hwy Relocates ISRS (5W)	Addition	Public Improv	201509	(32.04)	7	0.00148333	(65.0)	(0,57)
37G300-Mains - Plastic	21271185315	008362	Relocate 40ft of 4 in PE at Vivion a	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201509	(7.45)	.7	0.00148333	(80.0)	(0.13)
376300-Mains - Plastic	21271155315	008362	Relocate 40ft of 4in PE at Vivion a	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201511	402.03	Š	0.00148333	2,98	7:36
376300-Mains - Plastic	21271155315	008362	Relocate 40ft of 4In PE at Vivion a	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201512	(14.12)	4	0.00148333	(80.0)	(0.25)
378000-Meas & Reg Station Equipment	20901144058	008367	Rebuild DRS 56 Independence and Tow	F0578	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201510	11,000.64	É	3 9.00238333	157.31	314.62
378000-Meas & Reg Station Equipment	209011440SB	008367	Rebuild DRS 58 Independence and Tow	F0578	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201511	(578.46)		0.00236333	(6.89)	(16.54)
376300-Mains - Plastic	20901155368	008674	Manhattan Dr 4in PE Relocatio	F0578	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201509	(0.64)	1 3	7 0.00148333	(0.01)	(0.01)
376300-Mains - Plastic	20901155368	008674	Manhattan Dr 4in PE Relocatio	F0578	Street & Highway Relocates ISR5 (S)	Addition	Public Improv	201512	(0.05)		0.00148333	-	
376300-Mains - Plastic	20501155348	008681	C Street and Harlem PBS/PCS replac	F054G	Street & highway relocates - safety	Addition	Public Improv	201510	79,835.24		0,00148333	710.53	1,421,06
376300-Mains - Plastic	20501155348	208681	C Street and Harlem PBS/PCS replac	F0546	Street & highway relocates - safety	Addition	Public Improv	201511	(3,098,34)		0.00148333	(22,98)	(55.15)
376300-Mains - Plastic	20501155348	008681	C Street and Hariem PBS/PCS replac	F0546		Addition	Public Improv	201512	62.71		0.00148333	0.37	1.11
376300-Mains - Plastic 376300-Mains - Plastic	20908155382	008692	Relocate 2In pcs main Relocate 2In pcs main	F0578 F0578	Street & Highway Relocates (SRS (5) Street & Highway Relocates (SRS (5)	Addition Addition	Public Improv	201509	(31.90		7 0.00148333 0 0.00148333	(0.05)	(0.57
376300-Mains - Piestic	20201155406	008755	2in Main Relocation- 24 Hwy	F0578	Street & Highway Relocates ISRS (S)	Addition	Public improv	201509	(6,36		7 0.00148333	(0.07)	(0,11)
376100-Mains - Steel	71261155422	008790	Ain PCS Relocation	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201509	(8,950.44	)	7 0.00148333	(92.94)	(159.32
37G100-Mains - Steel	21261155422	008790	4in PCS Relocation	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201512	(4,541.42		4 0,00148333	(27,54)	(82.62
976300-Mains - Plastic	20513155372	008791	Carl Junction Addition for R1 HP Ma	F0G64	Street & Hwy Relocates ISRS (SW)	Addition	Public Improv	201510	92,686.08		8 0.00148333	824,90	1,649.81

Missouri Oes Énergy - MGE ISRS Work Order Additions September 2015 - December 2015 with Estimates for January and February 2018

Utility Account	MGE Work Order	New Work Order No.	Work Order Description	Eunding Prot. No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	Months	Dept Mo. Rate	Accum, Dept	Depr Expense
376100-Mains - Steel	20928155427	008804	Relocate Zin pos main	F0578	Street & Highway Relocates ISRS (S)	Addition	Public Improv	201509	(130.99)	. 7	0.00148333	(1.36)	(2.33
376100-Mains - Steel	20401155393	008809	Gin PCs Relocation	F0547	Street & Highway Relocates ISRS (N)	Addition	Public improv	201511	21,076.29	Š	0,00148333	156.32	375.16
376100-Mains - Steel	20401155393	008809	Gin PCS Relocation	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201512	1,881.38	4	0.00148333	11.16	33.49
376300-Mains - Flartic	21215155877	008895	Gas Main Relocation	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201510	107,761.64		0.00148333	959.08	1,918.15
376300-Meins - Plastic	21215155377	008895	Gas Main Relocation	F0547	Street & Highway Relocates ISRS (N)	Addition	Public Improv	201511	(602.32)		0.00148333	(4.47)	(10.72)
376300-Mains - Plastic	21215155377	008895	Gas Main Relocation	F0547	Street & Highway Relocates ISRS (N)	Addition	PublicImprov	201512	(163.37)		0.00148333	(0.97)	(2.91)
376300-Mains - Plastic	20815155412	008899	HWY 65 and HWY J Improvements	F0545	Street & highway relocates	Addition	Public Improv	201509	(3,798.95)	7	0.00148333	(39.45)	(67,62
380200-Services - Plastic & Copper	20324143653	005794	12302 Hwy 135 Repl 2in Svc w 4in PE	F0628	Services - 2" & larger	Addition	SLRP	201509	(1.82)		0.00223333	(0.03)	(0.05
380200-Services - Plastic & Copper	20401143804	006596	BLOUNT-REPLACEMENT SERVICE LINE	F0587	Services - 2" & larger	Addition	SLRP	201509	(137.71)		0,00223333	(2.15)	(3.69
380200-Services - Plastic & Copper	20401143776	006710	2100 CENTRAL AVE-REPL SERVICE LINE	F0587	Services - 2" & larger	Addition	SLRP	201509	(2.40)	-	0.00223333	(0.04)	(0.06
380200-Services - Plastic & Copper	21001143881	006714	Replace 1 1/4 plastic with 2in PE	F0587	Services - 2" & larger	Addition	SLRP	201509	(10.62)		0.00223333	(0.17)	(0.28
380200-Services - Plastic & Copper	21219155239	008130	Repliginch PE Service 1100 Main St	F0587	Services - 2" & larger	Addition	SLRP	201509	5.82	1	0.00223333	0.09	0.16
380200-Services - Plastic & Copper	20401155256	008759	2in Service Replacement	F0631	Services - 2* & larger - safety	Addition	SLRP	201509	1,319.82	100	0.00223333	20.63	35,37
380200-Services - Plastic & Copper	20401155256	008759	2in Service Replacement	F0631	Services - 2" & larger - safety	Addition	SLRP	201512	0.04		0.00223333		-
		L	- Action		The second secon			ant a deltale	12.691.796.48			117,550,76	254,410,62

Missouri Gas Energy - MGE ISRS Work Order Retirements September 2015 - December 2015

Hillity Account	MGE Work Order No.	New Work Order No.	Work Order Description	Proi. No.	Funding Project Description	FERC Activity	Month	Retirement. Amount	Months	Dan Mo. Rate	Accum, Depr	Door Expense
376200-Mains - Cast Iron	20401132881	003789	18th & Locust Repl Cl w 500'-din PE	F0599	Main Replacement - ISRS (N)	Retirement	201509	(60.78)	0	0,00148333	-	(1.08
180200-Services - Plastic & Copper	20401050301	004152	BWO-Repl Svc w/ Pls (North Reg)	F0608	BWO Service Line Repl - ISRS (N)	Retirement	201509	(6,122.29)	0	0.00223333		(164.08
380200-Services - Plastic & Copper	20401050301	004152	BWO-Repl Svc w/ Pls (North Reg)	F0608	BWO Service Line Repl ~ ISRS (N)	Retirement	201510	(17,390.29)	0	0,00223333		(466.06)
180200-Services - Plastic & Copper	20401050301	004152	BWO-Repl Svc w/ Pls (North Reg)	F0G08	BWO Service Line Repl - ISRS (N)	Retirement	201511	(6,141.30)	0			(164.59)
380200-Services - Plastic & Copper	20401050301	004152	BWO-Repl Svc w/ Pls (North Reg)	F0608	BWO Service Line Repl - ISRS (N)	Retirement	201512	(9,975.81)	0	0.00223333		(267.35)
380200-Services - Plastic & Copper	20901050301	004153	BWC-Repl Svc w/ Pls (South Reg)	F0513	BWO Service Line Repl - ISRS (5)	Retirement	201509	(1,607.64)				(43.08)
380200-Services - Plastic & Copper	20901050301	004153	BWO-Repl Svc w/ Pls (South Reg)	F0513	BWO Service Line Repl - ISRS (S)	Retirement	201510	(43,834.11)	Q			(1,174.75
380200-Services - Plastic & Copper	20901050301	004153	BWO-Repl Svc w/ Pls (South Reg)	F0513	BWO Service Line Rept - ISRS (S)	Retirement	201511	(32,837.38)				(880.04)
380200-Services - Plastic & Copper	20901050301	004153	BWO-Repl Svc w/ Pis (South Reg)	FQ513	BWO Service Line Repl - ISRS (S)	Retirement	201512	(30,991.10)	0			(830.56)
380200-Services - Plastic & Copper	20801050301	004501	8WO-Repi Svc w/ Pis (SW Reg)	F0659	BWO Service Line Repl - ISRS (SW)	Retirement	201509	(8,265.47)	- 0			(221.51
380200-Services - Plastic & Copper	20801050301	004501	BWO-Repl Svc w/ Pls (SW Reg)	F0659	BWO Service Line Repl - ISRS (SW)	Retirement	201510	(7,631.17)			•	(204.52
380200-Services - Plastic & Copper	20801050301	004501	BWO-Repl Svc w/ Pis (SW Reg)	F0659	BWO Service Une Repl - ISRS (SW)	Retirement	201511	(8,598,47)	0			(230.44
380200-Services - Plastic & Copper	20801050301	004501	BWO-Repl Svc w/ Pls (SW Reg)	F0G59	BWO Service Line Repl - (SRS (SW)	Retirement	201512	(1,602.71)				(42.93
376100-Mains - Steel	20501143693	006431	Relocate Main Due to Sidewalk Proje	F0664	Street & Hwy Relocates ISRS (SW)	Retirement	201509	(1,315.74)	0		-	(23,42)
380200-Services - Plastic & Copper	20401143804	006596	BLOUNT-REPLACEMENT SERVICE LINE	F0587	Services - 2" & larger	Retirement	201510	(1,115.27)	0			(29.89
376100-Mains - Steel	20401143804	006596	BLOUNT-REPLACEMENT SERVICE LINE	F0587	Services - 2" & larger	Retirement	201510	(1.54)	C			(0.03
376100-Mains - Steel	20806143872	006669	Repl 2in PCS due to CP Main and	F0598	Replace steel & plastic main	Retirement	201509	(1.75.39)				(3.12
376300-Mains - Plastic	21001143907	008800	Repl Goft of 2in PE main with 2inP	F0580	Replace steel & plastic main	Retirement	201509	(1,708.81)				(30.42
376100-Mains - Steel	20806244003	007171	Relocate 2in Steel Main due to Road	F0545	Street & highway relocates	Retirement	201509	(233.30)		CONTRACTOR OF THE PERSON NAMED IN COLUMN 1		(4.15
376100-Mains - Steel	21271143521	007313	PBS Replacement	F0663	Replace bore steel main - safety re	Retirement	201511	(36,930.85)	0			(657.37
376100-Mains - Steel	20301155094	007513	Replace 2in P85 Gav and Mitchell	F0599	Main Replacement - ISRS (S) Main Replacement - ISRS (N)	Retirement	201510	(16,972.75)				(302.11
37G200-Mains - Cast Iron 37G100-Mains - Steel	20401143855 20401143855	007532	Cast Iron Replacement Proj Phase 4  Cast Iron Replacement Proj Phase 4	F0599	Main Replacement - ISRS (N)	Retirement	201511	(1,166,22)		And in concession of the latest section of t		(20.76
376300-Mains - Plastic	20301155111	007532	Replace PBS main to eliminate DRS 9	F0604	Main Replacement - ISRS (S)	Retirement	201510	(21,093.90)				(375.47
376300-Mains - Plastic 376300-Mains - Steel	20301155111	007601	Replace PBS main to eliminate DRS 9	FOGO4	Main Replacement - ISRS (5)	Retirement	201510	(7,597.00)	- 0			(135.23
MAR CANADA	20401155181	007861		F0599	Main Replacement - ISRS (N)	Retirement	201511	(6,939.29)				{123.52
376200-Mains - Cost Iron 376100-Mains - Steel	20401155181	007861	Cast Iron Replacement project Phase  Cast Iron Replacement project Phase	F0S99	Main Replacement - ISRS (N)	Retirement	201511	(127.03)		0.00148333		(2.26
376100-Mains - Steel	21240155217	007927	2in Repi Clark Avenue Bridge Repi O	F0547	Street & Highway Relocates ISRS (N)	Retirement	201511	(429,73)		0.00148333	-	(7.65
382000 Meter Installations-MGE	20903155314	008245	Midwest Inn 7M Rotary Meter Rebuild	F0507	Rebuild Meter Install 2" & Lg (5)	Retirement	201510	(679.23)	-	The second secon		(16.57
376200-Mains - Cast Iron	20401155319	008274	AOR - Gin Ci Replacement	F0599	Main Replacement - ISRS (N)	Retirement	201511	(32.81)				(0.58
376300-Muins - Plastic	21271155315	008362	Relocate 40tt of 4in PE at Vivion a	F0S47	Street & Highway Relocates ISRS (N)	Retirement	201511	(742.44)				(13,22
376100-Mains - Steel	21272155334	008366	8in PBS Relocation	F0613	Replace bare steel main - safety re	Retirement	201509	(3,925.94)			4	(69.88
378000-Meas & Reg Station Equipment	20901144058	008367	Rebuild DRS 58 Independence and Tow	F0578	Street & Highway Relocates ISRS (5)	Retirement	201510	(11,876.14)	-	The second linear second linea		(339.66
376200-Mains - Cast Iron	20401155172	008390	BIN CLREPLACEMENT	F0500	Replace cast iron main - CPI / prio	Retirement	201511	(478.88)				(8.52
376100-Mains - Steel	20401155340	008391	Zin PCS Replacement	FQG6S	Replace stee! & plastic main	Retirement	201509	(23.55)				(0.42
376100-Mains - Steel	20401155343	008393	3in PCS Replacement	F0665	Replace steel & plastic main	Retirement	201509	(9.23)	AND DESCRIPTIONS			(0.16
37G100-Mains - Steel	21207155346	008399	4in 2B5 Replacement -3rd pty damage	F0613	Replace bare steel main - safety re	Retirement	201509	(47.12)		0.00148333		(0.84
376300-tviains - Plastic	20401155365	008537	AOR - 4in and 6in Cl Replacement	F0599	Main Replacement - ISRS (N)	Retirement	201511	(15,464.02)	(	0.00148333		(275.26
376200-Mains - Cast Iron	20401155365	00B537	AOR - 4In and Gin CI Replacement	F0599	Main Replacement - ISRS (N)	Retirement	201513	(1,528.58)	(	0.00148333		[27,21
376200-Mains - Cast Iron	20401155320	D08541	AOR - 6in Cl Replacement	F0599	Main Replacement - ISRS (N)	Retirement	201511	(610.86)	1	0.00148333	1	(10.87
376200-Mains - Cast Iron	20401155359	008548	AOR - 8in CI Replacement	F0599	Main Replacement - ISRS (N)	Retirement	201511	(101.21)		0.00148333		(1.80
376100-Mains - Steel	20806155332	008633	2in PBS replacement due to CP and L	FDG34	Replace bare steel main - safety re	Retirement	201509	(4,746.17)	1	0,001,48333	+	(84.48
380200-Services - Plastic & Copper	N/A	009220	BWO-Abandon Service (North)	F0608	BWO Service Line Repl - ISRS (N)	Retirement	201509	(114,005.17		0.00223333		(3,055.33
380200-Services - Plastic & Copper	N/A	009220	BWO-Abandon Service (North)	F0608	BWO Service Line Repl - ISRS (N)	Retirement	201510	(90,059,69)		0,00223333	*	(2,413.60
380200-Services - Plastic & Copper	N/A	009220	BWO-Abandon Service (North)	F0608	BWO Service Line Repi - ISRS (N)	Retirement	201511	[16,841.67		0.00223333		(451.36
380200-Services - Plassic & Copper	N/A	009220	BWO-Abandon Service (North)	F0608	BWO Service Line Rept - ISRS (N)	Retirement	201512	(24,102.82		0.00223333		(645.95
380200-Services - Plastic & Copper	N/A	009271	BWO-Abandon Service (South Region)	F0513	BWG Service Line Repl - ISRS (S)	Retirement	201509	(4,839.71		0,00223333		(129.70
380200-Services - Plastic & Copper	N/A	009221	BWO-Abandon Service (South Region)	F0513	8WO Service Une Repl - ISRS (S)	Retirement	201510			0.00223333		(864.46
380200-Services - Plastic & Copper	N/A	009221	BWO-Abandon Service (South Region)	F0513	8WO Service Line Repl - ISRS (S)	Retirement	201511	(30,077.06		0,00223333		(806.06
380200-Services - Plastic & Copper	N/A	009221	BWO-Abandon Service (South Region)	F0513	BWO Service Line Repl - ISRS (5)	Retirement	201512	(7,367.28		0.00223333		(197.44
380200-Services - Plastic & Copper	N/A	009222	BWO-Abandon Service (SW Region)	F0659	BWO Service Line Repl - ISRS (SW)	Retirement	201509	(19,129.13	-	0.00223333	an and a second	(53.2.66
380200-Services - Plastic & Copper	N/A	009222	BWO-Abandon Service (SW Region)	FQG59	8WO Service Line Repl - ISRS (SW)	Retirement	201510			0 0,00223333		(345.90
380200-Services - Plastic & Copper	N/A	009222	BWO-Abandon Service (SW Region)	F0659	8WO Service Line Repl - ISRS (SW)	Retirement	201511	18,642.29		D.00223333		(231.6
380200-Services - Plastic & Copper	N/A	009222	BWO-Abandon Service (SW Region)	F0659	IBWO Service Line Repl - ISRS (SW)	Retirement	201512		-	0,00223333		(186.6)
376200-Mains - Cast Iron	20401155483	009249	AOR - 8in Cl Replacement	F0599	Main Replacement - ISRS (N)	Retirement	201511		-	0.00148333	-	(1.17
376100-Mains - Steel	20401155463	009274	Replace 3in PCS, 1.25in PE, 2	F0G13	Replace bare steel main - aniety re	Retirement	201511			0.00148333	-	(58.9)
376300-Mains - Plastic	20401155463	009274	Replace 3in PCS, 1.2Sin PE, 2	F0623	Replace bare steel main - safety re	Retirement	201512			0,00148333		(34.6)
376100-Mains - Steel	20501155128	007602	Gas Main Replacement Due To Leak	F0575	Replace steel & plastic main	Retirement	201509		1	0.00148333	1	(0.15
378000-Mess & Reg Station Equipment	20305155397	008736	Retire DRS G in Sweet Springs	FOGOG	Station rebuild & replacement	Retirement	201510	THE PERSON NAMED IN COLUMN	A COLUMN TO THE OWNER OF THE OWNER	0.00238333		(102.33
378000-Meas & Reg Station Equipment	20201143462	004891	32nd & Norton Retire DRS 82	F0600	Station Rebuild & Repl ISRS (N)	Retirement	201509			0.00238333		(147.5:
378000-Meas & Reg Station Equipment	20324155273	008207	Retire DRS 1 Alley under Water Towe Retire DRS 9 Jefferson and Maguire	F0501	Station rebuild & replacement Station rebuild & replacement	Retirement Retirement	201513	(5,190.78		0 0,00238333 0 0,00238333	-	(148.46
378000-Meas & Reg Station Equipment	20301155114											

378000-Meas & Reg Station Equipment	20305155396	008735	Retire DRS 3 in Sweet Springs	F0606	Station rebuild & replacement	Retirement	201510	(3,356.87)	0 0.00238333		(96.01)
378000-Meas & Reg Station Equipment	20305155398	008732	Retire DRS 7 in Sweet Springs	F0606	Station rebuild & replacement	Retirement	201510	(5,449.03)	0 0.00238333	2111	(155.84)
376200-Mains - Cast Iron	20401155254	008638	4in Cast Iron Abandonment	F0500	Replace cast iron main - CPI / prio	Retirement	201511	[720,43]	0 0.00148333		(12.82)
											-
		111111111111111111111111111111111111111									

Total Retirements [716,119.34]

(18,109.40)

## Missouri Gas Energy Deferred Taxes - Rate Base Reduction ISRS Filing

Federal Tax Rate:	35.0000%
Composite Tax Rate:	38.3886%

2015 Tax Depreciation 2016 Tax Depreciation Total Tax Depreciation		734,931 6,569,782 7,304,713	231	- ,039 ,039	GO-2	015-0270 2,351,132 391,762 2,742,894	G	0-2015-0343 8,471,905 291,202 8,763,106
Book Depreciation		163,955	144	,253	1010	219,072		181,544
Difference between tax and book Depec	\$	7,140,758	\$ 86	,786	\$	2,523,822	\$	8,581,562
Total Deferred Taxes	_\$	2,741,237	\$ 33	,316	\$	968,860	\$	3,294,341

## Missouri Gas Energy ISRS Revenue Requirements Calculation

ISRS Activity:	Total for ISRS Filing		
Gas Utility Plant ProjectsTotal -(RM) RSMo 393.1012:			
Work Orders Placed in Service:			
Replacement Mains, Services and Associated Valves and Regulators	\$	24,696,659	
Deferred Taxes (Previous ISRS)	\$	(4,296,517)	
Accumulated Depreciation (Previous ISRS)	\$	(544,870)	
Deferred Taxes (Current)		(2,741,237)	
Accumulated Depreciation (Current)		(163,954)	
Total ISRS Rate Base		16,950,081	
Pre-tax rate of return from S&A in GR-2014-0007	-	9.75%	
Total Revenue Requirement on Capital		1,652,633	
Depreciation Expense		432,161	
Property Taxes		1,161,687	
Reconciliation of previous ISRS cases	·	323,568	
Current ISRS Revenues	\$	3,570,050	

## Missouri Gas Energy Summary of Plant Additions

Original Cost	Retirements	Accum Depr	Depr Exp
442,808.81		4,026.38	8,090.18
8,220,845.46		64,734.80	146,526.49
597,412.30		4,855.57	10,633.91
		e e	
3,430,729.91		43,934.03	89,160.24
6,344,158.65		28,785.79	115,143,39
5,660,704.28		17,617.70	105,706,44
	(1,813,123.72)		(43,099.34)
24,696,659.41	(1,813,123.72)	163,954.27	432,161.31
	442,808.81 8,220,845.46 597,412.30 - 3,430,729.91 6,344,158.65 5,660,704.28	442,808.81 8,220,845.46 597,412.30 - 3,430,729.91 6,344,158.65 5,660,704.28 (1,813,123.72)	442,808.81 4,026.38 8,220,845.46 64,734.80 597,412.30 4,855.57 - 3,430,729.91 43,934.03 6,344,158.65 28,785.79 5,660,704.28 17,617.70 (1,813,123.72)

ite D	esic	m	
	LT.	5.0	
			ite Design RS Filing

	-	
Total ISRS Rev Requirement	\$	10,253,423
GR-2015-0025 ISRS Rev Req	\$	1,990,295
GO-2015-0270 ISRS Rev Req	\$	2,814,926
GO-2015-0343	\$	1,878,151
Current ISRS Filing	\$	3,570,050

	No. of Customers Note	Customer Charges	Allocation	Ratio To Res Cust Chrq	ISRS Charge	ISRS Revenue
Residential	441,101	\$23.00	\$ 8,955,941	1.0000	\$ 1.51	\$ 8,008,389
Small General Service	60,339	\$34.00	\$ 1,225,099	1.4783	\$ 2.24	\$ 1,619,408
Large General Service	3,082	\$115.40	\$ 62,576	5.0174	\$ 7.59	\$ 280,749
Large Volume	483	\$904.56	\$ 9,807	39.3287	\$ 59.50	\$ 344,877
	505,005		\$ 10,253,423			\$ 10,253,423

Utility Account	New Work Order No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	WO Description	Statute Section	State or Federa Regularment
80200-Services - Plastic & Copper	003816	SLRP - immediate response - company	Addition	Blanket WO	201509	86,708.75	Service/Yard Line Replacement (SLRP): Company Crew. Immediate response - replacement single unprotected steel or copper (Kinese City - Central Region)		- Superior Commission
80200-Services - Plastic & Copper	003816	SLRP - Immediate response - company	Addition	Blanket WO	201510	2,003.40	Service/Yard Line Replacement (SLRP): Company Crew, Immediate response - replacement single unprotected steel or copper (Kenses City - Central Replan)		
80200-Services - Plastic & Copper	003816	SLRP - Immediate response - company	Addition	Blanket WO	201511	(4,137.63)	Service/Yerd Line Replacement (GLRP): Company Grew, Immediate response - replacement single unprotected steel or copper (Kennes City - Central Region)		
80200-Services - Plastic & Copper	003816	SLRP - Immediate response - company	Addition	Blanket WO	201512	(2,953.81)	Service Yard Line Replacement (SLRP): Company Crew. Immediate response -		
dozoo-services - / mane as copper	003826 Total	Ser - Intriguiste (659013t - Company	Audidon	SIGIRE! WO	201311	81,620,71	replacement single unprotected steel or copper (Kameas City - Central Region)	393.1009 (5) (a) (b)	A, B, C, I
180200-Services - Plastic & Copper	003818	SURP - block by block - contract	Addition	Blanket WO	201509	476,619.53	Service/Yest Line Replacement (CLRP): Centract Crew. Block by Block - Planned replacement at all unprotected steel or capper in a strolle block. (Kansas City - Central Region)		
80200-Services - Plastic & Copper	003818	SLRP - block by block - contract	Addition	Blanket WO	201510	499,624.63	Service/Yerd Line Replacement (SLRP): Contract Grew. Block by Block - Planned replacement of all unprofeoled steel or copper in a single block. (Karseas City - Central Region) Service/Yerd Line Replacement (SLRP): Contract Crew. Block by Block - Planned		
80200-Services - Plastic & Copper	003818	SLRP - block by block - contract	Addition	Blanket WO	201511	302,009.45	replacement of all unprotected steel or copper in a whole block. (Kareen City - Central		
80200-Services - Plastic & Copper	003818	SLRP - block by block - contract	Addition	Blanket WO	201512	181,546.04	Service/Yerd Line Replacement (SLRP): Contract Crew. Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Kansas City - Central		
	003818 Total					1,459,799.65		393,1009 (5) (4) (6)	A,B,C,I
			0.000				Cervice/Yerd Line Replacement (DLRP); Contract Crew. Block by Block - Plenned		
380200-Services - Plastic & Copper	003819	SLRP - block by block - contract	Addition	Blanket WO	201509	12,844.81	replacement of all unprotected etent or copper in a single block. (Monett - South Region)		
BB0200-Services - Plastic & Copper	003819	SLRP - block by block - contract	Addition	Blanket WO	201510	8,060.87	Janvise/Yard Line Replacement (SLRP): Contrast Crew. Block by Block - Planned replacement of all unprotected idea or copper in a single block. (Monett - Gauth Region)		
380200-Services - Plastic & Copper	003819	SLRP - black by block - contract	Addition	Blanket WO	201511	(531.73			
380200-Services - Plastic & Copper	003819	SLRP - black by block - contract	Addition	Blanket WO	201512	(211.66	Service/Yard Line Replacement (SLRP): Contract Craw. Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Manet - South Region)		
	003819 Total					20,162.29		393.1009 (5) (a) (b)	A,B,C,I
380200-Services - Plastic & Copper	003823	SLRP - modified block by block - co	Addition	Blanket WO	201509	(267,19	Service/Yerd Line Replacement (SLRP): Company Craw, Modified Block by Dicck - Planned replacement of all unprotected steel or copper in a angle block, (Monett - Bouth Region).		
	003823 Total	1	1		-	(267.19	]	393.1009 (5) (a) (b)	A,8,C,1
382000 Meter Installations-MGE	003825	SLRP - meter & regulator replacemen	Addition	Blanket WO	201509	1,663.60	(exclude regulator) (Lee's Gummt - East Region).		
382000 Meter Installations-MGE	003825	SLRP - meter & regulator replacemen	Addition	Blanket WO	201510	5,681,44			
82000 Meter Installations-MGE	003825	SLRP - meter & regulator replacemen	Addition	Blanket WO	201511	3,390.14			
82000 Meter Installations-MGE	003825	SLRP - meter & regulator replacemen	Addition	Blanket WO	201512	3,711.04	Service/Yerd Line Replacement (SLRP): Company Grew. Rebuild measuregulator setting (exclude regulator) (Les's Summit - East Region).	Control of the control of	
200200.0.1	003825 Total	- Interior	A dahar	ni-de sura	201509	14,446.72		393.1009 (5) (a) (b)	A,B,C,I
380200-Services - Plastic & Copper	003927 003927 Total	Service line locates	Addition	Blanket WO	201209	(0.22	Line Loostes - Service Line Replacements Only (Kenses City - Central Region)	393,1009 (S) (a) (b)	A,B,C,I
880200-Services - Plastic & Copper	003929	SLRP - immediate response - company	Addition	Blanket WO	201509	(65.96	Gervice/Yerd Line Replacement (GLRP): Company Crew. Immediate response- Jeplacement engle utprotested steel or copper (Monatt - South Region)		
	003929 Total					(65.96		393.1009 (5) (a) (b)	A,B,C,I
382000 Meter Installations-MGE	003930	SLRP - meter & regulator replacemen	Addition	Blanket WO	201509	1,485.27	[Service/Yard Line Replacement (SLRP): Contract Crew. Rebuild meter/regulator setting (exclude regulator) (Monett - South Region).		
382000 Meter Installations-MGE	003930	SLRP - meter & regulator replacemen	Addition	Blanket WO	201510	2,135.64	Service/Yerd Line Repletement (SLRP): Contract Crew. Rebuild meter/regulator setting		
382000 Meter Installations-MGE	003930	SLRP - meter & regulator replacemen	Addition	Blanket WO	201511	(713.65	Service/Yerri Line Repletoement (SLRP): Contract Crew. Rebuild meter/regulator setting (Monett - South Region).		
382000 Meter Installations-MGE	003930	SLRP - meter & regulator replacemen	Addition	Blanket WO	201512		Service/Year Line Replacement (SLRP): Contract Crew. Rebuild meter/regulator setting (module regulator) (Monett - South Region).		
	003930 Total					2,862.51		393.1009 (5) (a) (b)	A,8,C,1
382000 Meter Installations-MGE	003931	BWO Mtr/Reg Repl - SLRP ISRS (S)	Addition	Blanket WO	201509	25,739.18	Service/Yerd Line Replacement (SLRP): Company or Contract Crew. Rebuild mater/regulator setting (evolude regulator) - South Region		
382000 Meter Installations-MGE	003931	BWO Mtr/Reg Repl - SLRP ISRS (S)	Addition	Blanket WO	201510		Service/Yerd Line Replacement (SLRP): Company or Contract Crew. Rebuild mater/regulator setting (exclude regulator) - South Region		
382000 Meter Installations-MGE	003931	BWO Mtr/Reg Repl - SLRP ISRS (S)	Addition	Blanket WO	201511	7,336,83	Service/Yard Line Replacement (SLRP): Company or Contract Craw. Rebuild		
382000 Meter Installations-MGE	003931	BWO Mtr/Reg Repl - SLRP ISRS (S)	Addition	Blanket WO	201512		Bervion/Pend Line Replacement (SLRP): Company or Contract Crew. Rebuild meter/regulator satting (exclude regulator) - South Region		
SOLOGO MICOCI (HOMEROCHO)15-14(OC	003931 Total		Audition	Diamet WO	LULDAL	51,976,08		393.1009 (5) (a) (b)	A,8,C,1
			1				Service/Yard Line Replacement (SLRP): Company Crew. Modified Block by Block - Planned replacement of all unprotected staat or copper in a single block: (Kanesa Cty -		
380200-Services - Plastic & Copper	003932	SLRP - modified block by block - co	Addition	Blanket WO	201509	18,371,14	Central Region)		
380200-Services - Plastic & Copper	003932	SLRP - modified block by block - co	Addition	Blanket WO	201510	7,149.34	Service/Yerd Line Replacement (SLRP): Company Crew. Modified Dlack by Block - Planned replacement of all unprotected steel or copper in a sargle block. (Kances Chy - Contral Replace)		

Utility Account	New Work Order No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	WO Description	Statute Section	State or Federal Regul rement
180200-Services - Plastic & Copper	003932	SURP - modified block by block - co	Addition	Blanket WO	201511	15,672.74	Servica/Yard Lina Replacement (SURP); Company Craw, Modified Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Kansas City + Central Region)		3,000
					5.00		Service/Yard Line Replacement (SLRP): Company Crew, Modified Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Kanase City -		
80200-Services - Plastic & Copper	003932	SLRP - modified block by block - co	Addition	Blanket WO	201512	11,319.90	Central Region)	Contract to the same	4004
- mary special	003932 Total			- Company is the company of the comp	-	52,513.12	Service/Yard Line Replacement (SLRP): Company Crew, Service/yard line replacement -	393.1009 (5) (a) (b)	A,B,C,1
80200-Services - Plastic & Copper	003935	SLRP - materials - company crews	Addition	Blanket WO	201509	5,691.02	Material Charges Only (Kansas City - Monett - South Region)		
11.700.000	003935 Total					5,591.02	Service/Yerd Line Replacement (SLRP): Contract Craw, Immediate response -	393.1009 (5) (a) (b)	A,8,C,1
80200-Services - Plastic & Copper	003937	SLRP - Immediate response - contrac	Addition	Blanket WO	201509	(3.64)	replacement single unprotected steel or copper (Joplin - South Region)		
	003937 Total					(3.64)		393.1009 (5) (a) (b)	A,B,C,1
attended in a constant	The state of the s	Like and the best of the con-	Leganor	erono rese	Total .	2 000 46	Service/Yard Line Replacement (SLRP): Contract Craw, Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Jopen - South Region)		
80200-Services - Plastic & Copper	003972	SLRP - block by block - contract	Addition	Blanket WO	201509	3,671.65			
	242422	Control Control Control	1		46.46	. 1170	Service/Yerd Line Repletement (SLRP): Contract Crew, Block by Block - Planned repletement of all unprotected sizes or copper in a single block. (Japin - South Region)		
80200-Services - Plastic & Copper	003972	SLRP - block by block - contract	Addition	Slanket WO	201510	94.65			
Manage & L. L. M.	003972	CORP. No all porters de la companie	130000	nie-Carttin	201511	(7.057.00)	Service/Yard Line Replacement (SLRP): Contract Crew, Blook by Block - Planned replacement of all unprotected steel or copper in a single block. (Jophn - South Region)		
80200-Services - Plastic & Copper	003972	SLRP - block by block - contract	Addition	Blanket WO	201511	(3,957,00)	the product of the pr		
annon a sudere Blank B Course	003972	SLRP - block by block - contract	Addition	Blanket WO	201512	113.40	Service/Yerd Line Replacement (SLRP): Contract Craw, Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Joplin - South Region)		
80200-Services - Plastic & Copper	003972 Total		Audibou	Bialities wo	201344	[77.30]		393.1009 (5) (a) (b)	A,B,C,I
Service of the servic			Townson Villa				Service/Yend Line Replacement (GLRP): Company or Contract Crew. Rebuild		
82000 Meter Installations-MGE	003974	BWO Mtr/Reg Repl - SLRP ISRS (N)	Addition	Blanket WO	201509	95,286.61	mater/regulator setting (emiliais regulator) - North Region Service/Yerd Une Replacement (SURP): Company or Contract Craw. Rebuild		
82000 Meter Installations-MGE	003974	BWO Mtr/Reg Repl - SLRP ISRS (N)	Addition	Blanket WO	201510	114,443.57	meter/regulator setting (exclude regulator) - North Region		
82000 Meter Installations-MGE	003974	BWO Mtr/Reg Repi - SLRP ISRS (N)	Addition	Blanket WO	201511	41,749.98	Service/Yerd Line Replacement (BLRP): Company or Contract Crew. Rebuild mater/regulator setting (exclude regulator) - North Region		
92000 Harter facts librians MAGE	003974	BWO Mtr/Reg Repl - SLRP ISRS (N)	Addition	Blanket WO	201512	10,846.49	Service/Yard Line Replacement (OLRP): Company or Contract Crave. Rebuild		
82000 Meter Installations-MGE	003974 Total		Addition	diamet wo	201312	262,326.65		393.1009 (5) (a) (b)	A,B,C,I
	10000					202/22	Service/Yeru Line Replacement (SLRP): Company Cray. Modified Block by Block -		4.404.44
380200-Services - Plastic & Copper	003975	SLRP - modified block by block - co	Addition	Blanket WO	201509	1.17	Planned replacement of all unprotected steel or copper in a single block, (Joplin - Couth Region)		
	003975 Total					1.17		393.1009 (5) (a) (b)	A,B,C,1
							Service/verd Line Replacement (SLRP): Company Cray. Modified Block by Dlock - Planned replacement of all unprotected steel or copper in a single block. (Loc's Summit -		
380200-Services - Plastic & Copper	003976	SLRP - modified black by black - co	Addition	Blanket WO	201509	(30.66	East Region)	TO PAGE AND THE	
	003976 Total					(30.66		393,1009 (5) (5) (6)	A,8,C,1
	10 140 - 1				100		Service/rerd Line Replacement (SLRP): Company Crew. Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Less Summitt - East		
380200-Services - Plastic & Copper	003979	SLRP - block by block - company cre-	Addition	Blanket WO	201509	14.49	Region)	222 CARA (417 VIII)	46.47
var.	D03979 Tota				-	14.49	Service/Yerd Line Replacement (SLRP): Contract Crew, Dlock by Block - Planned	393,1009 (5) (a) (b)	A,B,C,I
and a section of the section of the section	121000	and the second second	2.0000000				rapingament of all unprotected steel or copper in a single block. (Lee's Gummit - East		
380200-Services - Plastic & Copper	004146	SLRP - block by block - contract	Addition	Blanket WO	201509	6,963.76	Region)  Service/Yerd Line Replacement (SLRP): Contract Crew. Black by Block - Planned		
contact of widers Minute D. Connect	CD4146	CLOS Mark No. 14 - 40 - 14 - 14	Addition	Mantes 11/0	201510	22 022 22	replacement of all unprotected steel or copper in a simple block. (Lea's Summit - East		
380200-Services - Plastic & Copper	004146	SLRP - block by block - contract	Addition	Blanket WO	201510	37,933.22	[Region] Service/Yard Line Replacement (SLRP): Contrast Crew, Block by Block - Planned		
380200-Services - Plastic & Copper	004146	SLRP - block by block - contract	Addition	Blanket WO	201511	2,265.09	Implement of all unprotected steel or copper in a single block. (Lee's Summs - East		
Sabzut-Services - Plastic & Copper	004240	SERV - DIDEK BY BIDEK - CONTRACT	Addiction	DIMITALE TVO	201311	2,205.05	Service/Yard Line Replecement (GLRP): Contract Craw, Block by Block - Planted		
380200-Services - Plastic & Copper	004146	SLRP - block by block - contract	Addition	Blanket WO	201512	1,874.81	replacement of sill unprotected steet or copper in a single block. (Les's Cummit - East Region)		
SOUZOF-SELVICES - PRESCIE OF CODDES	004146 Tota		Addition	Diameter 440	101512	49,036.88		393.1009 (5) (a) (b)	A.B.C.I
			1 3 200	Bl1 - 1970	201509		Service/Yerri Line Replacement (SLRP): Contract Craw, Service/yerd line replacement-		
380200-Services - Plastic & Copper	004148 004148 Tota	SLRP - materials - contract	Addition	Blanket WO	201203	693.68	Misterial Charges Only (Jopkin - Bouth Region)	393.1009 (5) (a) (b)	A,8,C,1
764 00.	Time Adu				-		Service/Varvi Line Replacement (St.RP): Contract Crew. Immediate response -	333.2003 (3) (6) (6)	11,0,0,1
380200-Services - Plastic & Copper	004150	SLRP - Immediate response - contrac	Addition	Blanket WO	201509	8,988.74	replacement single unprotected steet or copper (Kanses City - Central Region)  Gervice/Yard Line Replacement (CLRP): Contract Crow. Immediate response -		
380200-Services - Plastic & Copper	004150	SLRP - immediate response - contrac	Addition	Blanket WO	201511	(2,481.06	replacement single unprotected steel or copper (Kansas City - Central Region)		
380200-Services - Plastic & Copper	004150	SLRP - Immediate response - contrac	Addition	Blanket WO	201512	1,090,44	Service/Yerd Line Replacement (SLRP): Contract Crew, Immediate response -		
3,250,57	004150 Tota					7,598.12		393.1009 (5) (a) (b)	A,B,C,I
380200-Services - Plastic & Copper	004152	BWO Service Line Repl - ISRS (N)	Addition	Slanket WO	201509	-	Replace service lines with plastic - North Region		
380200-Services - Plastic & Copper	004152	BWO Service Line Repl - ISRS (N)	Addition	Blanket WO	201510	-	Replace service lines with plastic - North Region		
380200-Services - Plastic & Copper	004152	BWO Service Une Repl - ISRS (N)	Addition	Blanket WO	201511	74,543.80			
380200-Services - Plastic & Copper	004152	BWO Service Line Repl - ISRS (N)	Addition	Blanket WO	201512	43,679.82 506,449.01	Replace service lines with plastic - North Region	393.1009 (5) (a) (b)	A,B,C,I
380200-Services - Plastic & Copper	004152 Tota 004153	BWO Service Une Repl - ISRS (S)	Addition	Blanket WO	201509	-	Replace service lines with plastic - South Region	222,1002 (2) (4) (5)	Pipieli
SOUSON-SELVICES - LISSUE & CODDEL	004129	POWN O DELAICE THE REDI - 1949 (2)	Addition	DIMINES AND	201303	37,073,34	Luchano notatre wate All handle a resolut staffers		

Utility Account	Order No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	WO Description	Statute Section	State or Feder Requirement
80200-Services - Plastic & Copper	004153	BWO Service Line Repl - ISRS (S)	Addition	Blanket WO	201510	86,584.93	Replace service lines with plastic - South Region	(m)	
30200-Services - Plastic & Copper	004153	BWO Service Une Ropi - ISRS (S)	Addition	Blanket WO	201511	71,033.92	Replace service lines with plastic - Couth Region		
0200-Services - Plastic & Copper	004153	BWO Service Line Repl - ISRS (S)	Addition	Blanket WO	201512		Replace service lines with plastic - South Region		
	004153 Total		1			256,290.33		393,1009 (5) (a) (b)	A,B,C,I
80200-Services - Plastic & Copper	004279	SLRP - materials - contract	Addition	Blanket WO	201509	(8.00)	Service/Yard Line Replacement (SLRP): Contract Crew, Service/yard line replacement - Material Charges Only (Kanass Crly - Central Region)		
80200-Services - Plastic & Copper	004279	SLRP - materials - contract	Addition	Blanket WO	201512	117.00	Service/Yard Line Replacement (SLRP): Contract Crew. Bervice/yard line replacement -		
80200-Services - Plastic & Copper	004279 Total	SERP - materials - contract	Addition	Bidnker WU	201542	109.00	Meterial Charges Only (Kansas City - Central Region)	393,1009 (5) (a) (b)	A,B,C,1
						- Tellings	Service/Yerd Line Replacement (GLRP); Company Crew. Rebuild meter/regulator setting	393,1003 (3) (4) (6)	A,D,L,
82000 Meter Installations-MGE	004282	SLRP - meter & regulator replacemen	Addition	Blanket WO	201509	1,732.15	(exclude regulator) (Kanese City - Central Ragion).		
82000 Meter Installations-MGE	004282	SLRP - meter & regulator replacemen	Add\tion	Blanket WO	201510	2,789.65		**	
82000 Meter installations-MGE	004282	SLRP - meter & regulator replacemen	Addition	Blanket WO	201511	4,583.70	Service/Yard Line Replacement (SLRP): Company Graw. Rebuild metar/regulator setting (exclude regulator) (Kanses City - Central Replan).	r.	
DOOD IN COLUMN DESCRIPTION	20.4222		200000	BU ST A LOCAL	204542		Service/Yard Line Replacement (GLRP): Company Craw. Rebuild metar/regulator setting	in a	
82000 Meter Installations-MIGE	004282	SLRP - meter & regulator replacemen	Addition	Blanket WO	201512	2,888.71		neg	1861
	004282 Total		-		+	11,994.21	] [Garvica/Yard Line Replacement (SLRP): Contract Crew, Garvice/yard line replacement -	393.1009 (5) (a) (b)	A,B,C,1
80200-Services - Plastic & Copper	004287	SLRP - materials - contract	Addition	Blanket WO	201509	52,023.10	Material Charges Only (Lee's Summit - East Region)		
80200-Services - Plastic & Copper	004287	SLRP - materials - contract	Addition	Blanket WO	201510	5 498 95	Service/Yard Line Replacement (SLRP): Contract Crew, Service/Yard line replacement - Meterial Charges Only (Lee's Summit - East Region)		
	7						Service/Yard Line Replacement (SLRP): Contract Crew. Service/yard line replacement -		
80200-Services - Plastic & Copper	004287	SLRP - materials - contract	Addition	Blanket WO	201511	157.70	Material Charges Only (Lea's Summit - East Region)		
B0200-Services - Plastic & Copper	004287	SLRP - materials - contract	Addition	Blanket WO	201512	3,499.35	Service/Yard Line Replecement (SLRP): Contract Crew. Service/yard line replecement - Material Charges Only (Lea's Summit - East Region)		
	004287 Total			-	1 1	61,179.10	Constitution of the consti	393.1009 (5) (a) (b)	A,B,C,I
80200-Services - Plastic & Copper	004288	Replace existing protected steel, p	Addition	Blanket WO	201509	6,028,23	Replacement and/or removal of entating protected steel or plastic (Joplin - South Region)		
80200-Services - Plastic & Copper	004288	Replace existing protected steel, p	Addition	Blanket WO	201511	(556.42	Replacement and/or removal of enating protected steel or plastic (Joplin - South Region)		
80200-Services - Plastic & Copper	004288	Replace existing protected steel, p	Addition	Blanket WO	201512	574.13	Replacement and/or removal of existing protected steel or plastic (Joplin - South Region)		
euzuo-services - Plasue & Copper	004288 Total	Replace existing protected steel, p	Audition	DIATIRET WO	201512	6,045.94		393.1009 (5) (a) (b)	A.B.C.I
	DOMESTI DEST		-		-	6,043.34		232.7003 [3] [8] [8]	M20,C1
BODON Consider Discolo 2 Comme	004407	FIRE Class to Class and account and	Addison	Plantitio	201500	0 555 57	Elervice/Yard Line Replacement (SLRP): Company Craw. Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Moneti - South Region)		
80200-Services - Plastic & Copper	004407	SLRP - block by block - company cre	Addition	Slanket WO	201509	8,665,57			
	10000	COR AN	2.1100	B1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	202544	1000 00	Service/Yard Line Replacement (SLRP): Company Crew, Block by Block - Planned proplecement of all unprotected steel or copper in a single block. (Monett - South Region)		
80200-Services - Plastic & Copper	004407	SLRP - block by block - company cre	Addition	Blanket WO	20151.1	(603.81			
	1000000	Auto attendant of the statements	1	au Taiscop i	Section 1	70.5	Service/Yend Line Replacement (SLRP): Company Crev. Block by Block - Planned replacement of all unprotected steel or copper in a single block. (Monett - South Region)		
80200-Services - Plastic & Copper	004407	SLRP - block by block - company cre	Addition	Blanket WO	201512	42.61	A CONTRACTOR OF THE PROPERTY O		-2000
	004407 Total					8,104.37	Service/Yard Line Replacement (SLRP): Contract Crew, Immediate imagenae -	393.1009 (5) (a) (b)	A,B,C,I
80200-Services - Plastic & Copper	004413	SLRP - immediate response - contrac	Addition	Blanket WO	201509	(4,12	replacement single unprotected steel or copper (Monett - South Region)		
	004413 Total					(4.12		393,1009 (5) (a) (b)	A,B,C,I
80200-Services - Plastic & Copper	004414	SLRP - immediate response - contrac	Addition	Blanket WO	201509	5 750 43	Service/Yard Line Replacement (2LRP): Contract Crew. Immediate response - replacement single unprotected steel or copper. (Les's Summit - East Region)		
			1 2 5 600 100 1				Service/Yard Line Replacement (SLRP): Confract Crew, Immediate response -		
180200-Services - Plastic & Copper	004414	SLRP - immediate response - contrac	Addition	Blanket WO	201510	20,233.86	replacement single unprotected steel or copper (Lea's Summit - East Region)		
80200-Services - Plastic & Copper	004414	SLRP - Immediate response - contrac	Addition	Blanket WO	201511	55,930.49	Service/Yard Line Replecement (SLRP): Contract Crew, Immediate response - replacement single unprotected steel or copper (Lee's Summit - Sest Region)		
380200-Services - Plastic & Copper	004414	SLRP - Immediate response - contrac	Addition	Blanket WO	201512	8,754.10	Service/Yerd Line Replacement (SLRP): Contract Crew. Immediate response -		
BUZOU-Services - Plastic & Coppet	004414 Total	SERP - Immediate response - contrac	Addition	DIBINET WO	201312	90,668.88		393,1009 (5) (a) (b)	A,B,C,I
180200-Services - Plastic & Copper	004416	Replace existing protected steel, p	Addition	Blanket WO	201509	(863.66		393,1005 (3) (4)	A,B,C,I
880200-Services - Plastic & Copper	D04416	Replace existing protected steel, p	Addition	Blanket WO	201510		Replacement and/or removal of enesting protected steel or plastic (St. Joseph)		
80200-Services - Plastic & Copper	004416	Replace existing protected steel, p	Addition	Blanket WO	201511		Replacement and/or removal of existing protected steel or pleatic (St. Joseph)		
80200-Services - Plastic & Copper	004416	Replace existing protected steel, p	Addition	Blanket WO	201512	462.84			
55555 52(4)465 (10556 6 65526)	004416 Total		Tabbition	Old I ALL TO	202322	(266.44		393.1009 (5) (a) (b)	A,B,C,I
80200-Services - Plastic & Copper	004492	SLRP - modified block by block - co	Addition	Blanket WO	201509	287.68		and a second	
80200-Services - Plastic & Copper	004492	SLRP - modified black by block - co	Addition	Blanket WO	201510	1,555.33			
180200-Services - Plastic & Copper	004492	SLRP - modified block by block - co	Addition	Blanket WO	201511		Project Type:B		
80200-Services - Plastic & Copper	004492	SLRP - modified block by block - co	Addition	Blanket WO	201512	-	Project Type:B		
The state of the s	004492 Total					1,788.82		393.1009 (5) (a) (b)	A,B,C,I
82000 Meter Installations-MGE	004498	SLRP - meter & regulator replacemen	Addition	Blanket WO	201509	76.04	Service/Yerd Line Replacement (SLRP): Company Crew, Rebuild meter/regulator setting (exclude regulator) (Jopin - South Region).	•	
382000 Meter Installations-MGE	004498	SLRP - meter & regulator replacemen	Addition	Blanket WO	201510	4 7	Service/rard Line Replacement (CLRP): Company Crew. Rebuild meler/regulator settin (exclude regulator) (Jopiin - South Region).	2	
882000 Meter Installations-MGE	004498	SLRP - meter & regulator replacemen	Addition	Blanket WO	201511	356.57	[Service/Yard Line Replacement (SLRP); Company Crew. Rebuild meter/regulator setting	9	
					-		Service/Yard Line Replacement (SLRP); Company Crew. Rebuild meter/regulator setting	g	
182000 Moter Installations-MGE	004498	SLRP - meter & regulator replacemen	Addition	Blanket WO	201512	199,22	(exclude regulator) (Jopkin - South Region).		

Utility Account	New Work Order No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	WO Description	Statute Section	State or Federa Requirement
	004498 Total					970.39		393.1009 (5) (a) (b)	A,B,C,I
80200-Services - Plastic & Copper	004499	SLRP - materials - company crows	Addition	Blanket WO	201509	(0.44)	Service/Yard Line Replacement (SLRP): Company Crew. Service/yard line replacement - Material Charges Only (Joplin - South Region)		
	004499 Total					(0.44)		393.1009 (S) (a) (b)	A,B,C,I
80200-Services - Plastic & Copper	004501	BWO Service Line Repl - ISRS (SW)	Addition	Blanket WO	201509	44,471.17	Replace service lines with plastic - Southwest Region		
80200-Services - Plastic & Copper	004501	BWO Service Line Repl - ISRS (SW)	Addition	Blanket WO	201510	62,720.88	Replace service thes with plastic - Southwest Region		
80200-Services - Plastic & Copper	004501	BWO Service Line Repl - ISRS (SW)	Addition	Slanket WO	201511	76,101.35	Replace service thes with plantic - Southwest Region		
80200-Services - Plastic & Copper	004501	BWO Service Line Repl - ISRS (SW)	Addition	Blanket WO	201512	39,275.64	Replace service lines with plastic - Southwest Region	No. 2 Aug Learn	
1.000	004501 Total	1 Transmission - Tran		- The state of the		222,569.04		393.1009 (5) (a) (b)	A,B,C,1
80200-Services - Plastic & Copper	004598	SLRP - immediate response - company	Addition	Blanket WO	201509	(48.36)	Service/Yerd Line Replacement (SLRP): Company Craw. Immediate response - (replacement single unprotected steel or copper (Lec's Summit - Sast Region)		
	004598 Total					[48.36]		393.1009 (5) (a) (b)	A,B,C,1
80200-Services - Plastic & Copper	004599	SLRP - modified black by black - co	Addition	Blanket WO	201509	(162.83)	Service/Yard Line Replacement (SLRP): Contract Crew. Modified Block by Block – Planned replacement of unprotected steel or copper. (Kansas City - Central Region)		
and the second	004S99 Total					(162.83)		393.1009 (5) (a) (b)	A,B,C,I
							Service/Yard Line Replecement (SLRP); Contract Crew, Modified Block by Block -		
80200-Services - Plastic & Copper	004600	SLRP - modified block by block - co	Addition	Blanket WO	201509	(147.61)	Planned replacement of unprotected steel or copper (Jophn - South Region)		
				-			Service/Yerd Line Replacement (SLRP): Contract Crew. Modified Block by Block -		
80200-Services - Plastic & Copper	004600	SLRP - modified block by block - co	Addition	Blanket WO	201510	2,021.93	Planned replacement of unprotected steel or copper (Jopan - South Region)		
80200-Services - Plastic & Copper	004600	SLRP - modified block by block - co	Addition	Blanket WO	201511	5,437.93	Service/Yard Line Replacement (SLRP); Contract Crew, Modified Block by Block - Planned replacement of unprotected steel or Copper (Joplin - South Region)		
					17-7-3		Service/Yard Line Replacement (GLRP): Contract Crew. Modified Block by Block -		
80200-Services - Plastic & Copper	004600	SLRP - modified black by block - co	Addition	Blanket WO	201512	782.20	Planned replacement of unprotected steel or capper (Jopin - South Region)		
	004600 Total		7			8,094,45		393.1009 (5) (a) (b)	A,B,C,I
80200-Services - Plastic & Copper	004601	SLRP - modified block by block - co	Addition	Blanket WO	201509	(0.50)	Service/Yard Line Replacement (SLRP); Contract Crew, Modified Block by Block - Planned replacement of unprotected steel or copper (St. Joseph)		
COLOR DEL VILLE - I HANG IX COPPE	004601 Total	DEN - HIDGERES DIOCK DY DIOCK - CD	- NODICOTI	Old Fisher Fred	201303	(0.50	Construction of the Constr	393.1009 (5) (a) (b)	A.B.C.I
							Service/Yerd Line Replacement (SLRP): Company or Contract Crew, Rebuild	222:7202 (2) (1) (0)	Arcton
82000 Meter Installations-MGE	004602	BWO Mtr/Reg Repl - SLRP ISRS (SW)	Addition	Blanket WO	201509	1,387.35	meter/regulator setting (exclude regulator) Southwest Region. Service/Yard Line Replacement (SLRP): Company or Contract Crew. Rebuild		
82000 Meter installations-MGE	004602	BWO Mtr/Reg Repl - SLRP ISRS (SW)	Addition	Blanket WO	201510	2,613.58	melar/regulator setting (exclude regulator) Courtivest Region,		
382000 Meter Installations-MGE	004602	BWO Mtr/Reg Repl - SLRP ISRS (SW)	Addition	Blanket WO	201511	2,306.05	Genvice/Yerd Line Replacement (SLRP); Company or Contract Crevy, Rebuild meter/regulator setting (exclude regulator) Southwest Region.		
THE STATE OF THE S				1000			Service/Yerd Line Replacement (SLRP): Company of Contract Crew. Rebuild		
882000 Meter Installations-MGE	004602	BWO Mtr/Reg Repl - SLRP ISRS (SW)	Addition	Blanket WO	201512	665.55		170 0 35 400 1000	46.27
	004602 Total					6,972.53	Service/Yers Line Repleasment (SLRP); Company Crew. Service/yers line replacement.	393,1009 (5) (a) (b)	A,B,C,I
180200-Services - Plastic & Copper	004609	SURP - materials - company crews	Addition	Blanket WO	201509	6,653.93	Material Charges Only (Lee's Summit - East Region)		
380200-Services - Plastic & Copper	004609	SLRP - materials - company crews	Addition	Blanket WO	201510	7,230.07	[Service/Yerd Line Replacement (SLRP): Company Craw, Service/yerd line replacement		
			1				Service/Yard Line Replacement (SLRP): Company Crew. Service/yard line replacement		
180200-Services - Plastic & Copper	004609	SLRP - materials - company crews	Addition	Blanket WO	201511	4,541.69	Material Charges Only (Lee's Summit - Cast Region)		
380200-Services - Plastic & Copper	004609	SLRP - materials - company crews	Addition	Blanket WO	201512	{179.92	Service/Yard Line Replacement (SLRP): Company Crow. Service/yard line replacement.  Misterial Charges Only (Les's Summit - East Region)	State of the second	
	004609 Total					18,245.77		393.1009 (5) (a) (b)	A,B,C,(
76300-Mains - Plastic	007052	Main Replacement - ISRS (N)	Addition	Blanket WO	201510	180,392.52	For short replacements of main done on emergency basis - North Region		
76300-Mains - Plastic	007052	Main Replacement - ISRS (N)	Addition	Blanket WO	201511	1,506.80			
76300-Mains - Plastic	007052	Main Replacement - ISRS (N)	Addition	Blanket WO	201512	745.37		article of the state of the state of	m Avir
75000	007052 Total				100000	182,644.69	and the first property of the control of the contro	393.1009 (5) (a) (b)	A,8,C
176300-Mains - Plastic	007053	Main Replacement - ISRS [5]	Addition	Slanket WO	201510	20,238,01	그리아 가는 그 아이들이 아니는 아이들이 아니는 아니는 아이들이 아이들이 가는 것이 되었다. 그리아 아이들이 살아 있다.		
176300-Mains - Plastic	007053	Main Replacement - ISRS (S)	Addition	Blanket WO	201511		For short replacements of main done on emergency basis - Court Region		
76300-Mains - Plastic	007053 007053 Total	Main Replacement - ISRS (S)	Addition	Blanket WO	201512	5,017.27 25,348.41		393.1009 (5) (a) (b)	A,B,C
376300-Mains - Plastic	007054	Main Replacement - ISRS (S)	Addition	Blanket WO	201510	7.119.41		222-7002 [5] [4] [0]	WOOL
376300-Mains - Plastic	007054	Main Replacement - ISRS (S)	Addition	Blanket WO	201511	150.00	그리다 그리지 않는데 가게 하는 사람이 모든 사람들이 모든데 가지 모든데 그리다 하나 무슨데 되었다면 하나 모든데 하나 되었다.		
376300-Mains - Plastic	007054	Main Replacement - ISRS (S)	Addition	Blanket WO	201512	239.18	프레크 중에 대통하는 사람들이 하는 사람들이 되었다. 그 사람들이 되었다면 하는 것이 되었다면 하는 것이 없었다. 그 없는 것이 없는 것이다.		
	007054 Total	The state of the s				7,508.59		393.1009 (5) (a) (b)	A,B,C
380200-Services - Plastic & Copper	009217	BWQ Service Une Repl - ISRS (N)	Addition	Blanket WO	201509	861.58	Approved by: Joe Hampton on 00/01/2015, Replace main on Main St, Perker St, Bridge	51571.000.000	136.3
The state of the s		100			272003	002.30			
380200-Services - Plastic & Copper	009217	BWO Service Line Repl - ISRS (N)	Addition	Blanket WO	201510	7,069.77	Approved by: Joe Hampton on 06/01/2015, Replace main on Main St, Parker St, Bridge St, Patrick St, and the alleyway between Main St and Ray St with 2" PE, (ISRS)		
payeon-services - master or nobbet	009217 Total		Addition	Dianket WO	201510	7,069.77	그 무게들으면서 개발하다 보면 아이스에는 이러스에게 되어 가는 이 아이스 그리고 어떻게 되었다고 아이를 했다.	393.1009 (S) (a) (b)	A,B,C,I
376200-Mains - Cast Iron	003969	BWO Ci Joint Encapsulation ISRS (N)	Addition	Encapsulation	201509	140,588.53		222,7003 (2) (*) (0)	ارسارهاردم
376200-Mains - Cast Iron	003969	BWO Cl Joint Encapsulation ISRS (N)	Addition	Encapsulation	201510		Project Type:3		
376200-Mains - Cast Iron	003969	IBWO Ci Joint Encapsulation ISRS (N)	Addition	Encapsulation	201511		Project Type:0		
S. DERN SERVICE - PRINT HOST	000000	Tosse or south tripping control (342)	Mudicion	THE PARISON OF	LOSSA	7+0,330,03	E infant (State)		

Utility Account	New Work Order No.	Funding Project Description	FERC Activity	Category	Month	Addition	WO Description	Statute Section	State or Federal Requirement
376200-Mains - Cast Iron	003969	BWO CI Joint Encapsulation ISRS (N)	Addition	Encapsulation	201512	151,371.11	Project Type B		
TO THE STATE OF TH	003959 Total					597,412.30		393.1009 (5) (a) (b)	A,B,C,I
							Approved by: Gary Williams on 01/03/2014, Replace 500 test of 4" Ci (work order unknown) with 500'-4" PS due to two cest iron breaks being within 500 feet of each other.		
376100-Mains - Steel	003789	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	266.08	See be-in procedure. Tis-over B services.		
			1000000				Approved by: Cary Williams on 01/03/2014, Replace 500 feet of 4" Ct (work under unknown) with 500"-4" PE due to two cast iron breaks being within 500 feet of each other.		
376100-Mains - Steel	003789	Main Replacement - ISRS (N)	Addition	ISRS-Other	201510	480.08	See te-in procedure. Tis-over 8 services.		
							Approved by: Gary Williams on 01/03/2014, Replace 500 feet of 4" Ct (work order unknown) with 500"-4" PE due to two cast fron breaks being within 500 feet of each other.		
376100-Mains - Steel	003789	Main Replacement - ISRS (N)	Addition	ISRS-Other	201511	172.78	Sea tie-in procedure. Tie-over d nervices.		
			7.00				Approved by Cary Williams on 01/03/2014, Replace 500 feet of 4° Ct (work order junknown) with 500-4° PE due to two cast fron breaks being within 500 feet of each other.		
376100-Mains - Steel	003789	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512	(95,118.85)	See tie-in procedure, Tie-over it services.		
ALCOHOLD DESCRIPTION	Contract of	and the second second					Approved by: Gary Williams on 01/03/2014, Replace 500 feet of 4" CI (work order junknown) with 500"-4" PE due to two cast ron breaks being within 500 feet of each other		
376300-Mains - Plastic	003789	Main Replacement - ISRS (N)	Addition	ISRS-Other	201512		See tie-in procedure: Tie-over 8 services.	77. G7779.	75.Z.r.)
	003789 Total					899.15	I also to have the former of the former	393.1009 (5) (a) (b)	A.B,C,D,I
376300-Mains – Plastic	003808	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(29.95)	Approved by: Stave Lindacy on 03/18/2014, "MCDOT Fermit Required Abundion 1636/." 37 PIGS (VMEN NOICH), 633" –49 PIGS (VMEN NOICH), 435" –27 PIGS (VMEN NOICH), 435" –47 PIGS (VMEN NOICH), 435" –47 PIGS (VMEN NOICH), 435" –48 P		
	003808 Total					(19.95)		393.1009 (5) (a) (b)	A,B,C
376300-Mains - Plastic	003874	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(108.81			
	003874 Total					(108.81		393.1009 (5) (a) (b)	A,B,C,O,
378000-Meas & Reg Station Equipment	004003 004003 Total	Station Rebuild & Repl ISRS (N)	Addition	ISRS-Other	201509	(1,455.90 (1,455.90	Approved by: Rob Hatik on 07/02/2013, Relacujal reg station 250 at 107th and Nehmes (Emirel) to 10th Rever Road in the past; This is in conjunction with the 20nch replacement project WOst 13-2022, Iniet 16th PCG system 0-16020, MCP 250 PBIO, MAOP 280 PBIO, TEST 830 PBIO, Coultst 16th PCG system 2-014, MOP 185 PBIO, MAOP 250 PBIO, TEST 830 PBIO, This DR3 will utilize senting valves and regulations. This will include arrow/ing all facellins at ensiting Mayfair distation and cleanup.include building and footings.	393.1009 (5) (a) (b)	A,8
	004003 1003				-	(1,433,30		232/1002 (2) (9) (0)	A, G
376100-Mains - Steel	004064	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	2.47	Approved by: Cellen Shoemister on 10/00/2013. Abandon 16' - 2' PBS (M/OE' NONE) and 49' - 3' PBS (M/OE' NONE) and 49' - 3' PBS (M/OE' NONE) and 10' PBS (M/OE' NONE) and the place as the 20' - 4' Thinfilm, in order to replace base is tall, outlet, and control line piping and install remote intel and audit visites to BDR of 10'-00'. Novel to be completed in on optimization with WOE' 13-000E, Project Location. Wincomain Ave and Montana Pt, that Pressure System: C-1, MOP': 50 paig', MOAP': 85 paig', MOAP': 85 paig', Design (Test) paig', Cuttler Pressure System: C-1, MOP': 50 paig', MOAP': 85 paig', Test's 100 paig'; 1048'.		
376300-Mains - Plastle	004064	Main Replacement - ISRS (SW)	Addition	iSRS-Other	201509	ć.49			
	004064 Total			,		2.96		393.1009 (5) (a) (b)	A,B,C
376300-Mains - Plastic	004081	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201509	(29.22	Approved by Casina Bhomakker on Dr. 103.014, Replace 157 of 41 PCQ, 407 of 57 PCI. 310" of 2" PCID, 10" of 4" PCI. 3" of 2" PCI, and 4" of 5" PC with 500" of 4" PCI and 310" of 2 PCI due to corresion and PCIS holistion lessues, Project Location (15) ct; between 150" of 15" of 15		
	004081 Total					(29,22		393.1009 (5) (a) (b)	A,B,C

Utility Account	New Work Order No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	WO Description	Statute Section	State or Federal Regularment
(76100-Mains - Steel	004126	Reculfier New/Repl ISRS (N)	Addition	ISRS-Other	201509	(12 93)	Approved by: Ransy Spector on 11/08/2013, This work order is necessary to replace the existing ground had and notifier originally installed on work order in necessary to replace the existing ground had an expected in the provided of the provided in provided in a privitie segment exception (will have 55 th 60 monoton spaced at 15 intervals in a privitie segment exception will be provided. Whe described with the provided in the contraction will be defined in by contraction and MCC service and perform Salamoing and arguintaments. This register is designed to protect approximately 5.034 of 27 PCS and 6.576 of 27 PDS mein. Calculated current dismand is 0.03 ample.		
, 0100-1418/15 Dect/	004126 Total	recurrer receip negri iono (c)	Piddicion)	(SIG-Other	201303	(12.93)		393.1009 (5) (a), (b)	A, 8, E
							Approved by: Steve Helcomb on 10/07/2013, Rebuild DRS 356 due to complications		63695
78000-Meas & Reg Station Equipment	004133	Station Rebuild & Repl ISRS (N)	Addition	ISRS-Other	201509	(1.88)	arising during Hydro Test. Construct 1-10" run Utilizing existing regulators, and 1-0" run for bypeas.		
	004133 Total					(1.88)		393.1009 (5) (a) (b)	A,B
76300-Mains - Plastic	004198	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(0.31)	Approved by: Slave Holcomb on 01/20/2014, Replace 1225 - 2º PD3 (AVO#s), 10/101, 10/2089, 327 - PD3 (AVO#s), 55840, Space 126, 368 - 2º PC3 (AVO#s 158407) and 6 - 2º PC PC0 (AVO#s 158407) and 6 - 2º PC and 1202 - 4º PC to clear one (f) active 81 Law (Law No. 13-140) and 13-140 pc and 1202 - 2º PC3 (AVO#s), 10/101, 10		
	004198 Yotal					(0.31)		393.1009 (5) (a) (b)	A,B,C
							Approved by: Stave Underly on 11/18/2013, 10/85, Replace and abandon a total of 14/44 of cast from man in Jacobs 0308 & 0000 with 100/76 of PC. This work will be part of the Cast from Papicament Program as mandelined by the Misecout Public Genvice Commission for Calendar year 2014, New main will be into the C-175 KCLD pressure trystam. New main to operate at 50 page (MPC). Be part MAOP. Text at Parelline 100 page for a design MAOP = 3.0 page, Diselling main to be replaced has an MAOP = 1.10 page. Set MAOP = 3.0 page, As service repulsation with Parel to be schaped, Set actionated sheet (This work order number; size and footige of main to be refered. 67 bere steel centroles are to be replaced, Replacement baseline stay for the commission of the commission of the set of th		
376300-Mains - Plastic	004221 004221 Total	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	24.18	has no non-particular life cas as more more received to the Addition and	393.1009 (5) (a) (b)	A,B,C
376300-Mains - Plastic	004248	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509		Approved by: Reigh Janes on 03/14/2014, We have dual mains on 24 Hwy believen Cogan and Alan Rd. The main on the south adds is 0° PBS and only service five outstorners. The 15804 and 15005 E US Highway 24 over to the 8° PCS on the hoth cide of 24 Hwy (one will be short disk) and matel 152° of 4° PC main, Main to absender; 152° - 6° PBS (WOB A5422A); 167° - 6° PBS (WOB 4622B); and 180° - 4° PBC (WOB A5423B).		7,92
	004248 Total			January Committee of the Committee of th		(5.05)		393.1009 (5) (a) (b)	A,B,C
376100-Mains - Steel	004271	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	(1,22)	Approved by: Cary Williams on 12/02/2013, AOR, Replace 40*-6in Ct with Bin PE. 13* of Ct was exposed at 2551 Chelses. Tile-over two services and replace one service (2553 Chelses), Retire 35'-oin Ct, B30PB8; 5'-6in Ct, B10P103.		
	004272 Total	The state of the s	332,551	TOTAL DATE	1,000	(1.22)		393.1009 (5) (a) (b)	A,B,C
376100-Məins - Steel	004315	Restifier New/Repi (SRS (N)	Addition	ISRS-Other	201509	(2.72)	Approved by: Rendy Speciar on 11/12/2012, This work order to necessary to retire existing Recitine; LOSQS and ground bed installed in work order 64-6270. The eristing courted output is ensufficient to supply current resetted and hastory of ground bed reasonable in working the provided of the supply current resetted and hastory of ground bed with a 15-3-56-604; is inchanging indicaping ground bed is depicted. The new ground bed will be 15-3-56-604; or OCCEPTION of the STATE of the S		
	004315 Total					(2.72		393.1009 (5) (a), (b)	A, B, E
376300-Mains - Plastic	004364	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509		Approved by: Reigh Janes on 00/11/2014, Replace and abendon 752" - 2" plos main (Unknown) by installing 730" - 2" pa main due to leakage under pevernent. (IGRC)		100
	004364 Total				+	(11.98		393.1009 (5) (a) (b)	A,8,C
376200-Mains - Steel	004374	Main Replacement - ISRS (5)	Addition	ISRS-Other	201509	23:43	Approved by, Ken Thomas on 00/12/2013, Main to abandon: DSC of 4s PBC from well  NONE, 960 of 4s PBC from well  SONE, 961 of 4s PBC from well  SONE, 962 of 4s PBC from well  SONE, 962 of 5s from well  SONE, 962 of 4s PBC and  SONE 962 of 9s from well  SONE, 962 of		
376100-Mains - Steel	004374	Main Replacement - ISRS (5)	Addition	ISRS-Other	202510	(400.00	Approved by: Ken Tromus on 00/12/2013, Main to abendon; 20° of ath PBS from wold NONE, DeS of all PBS from well ASSIDE, 7° of all PBS on well ASSIDE, 7° of all PBS on well ASSIDE, 7° on well ASSIDE of all PBS on 15° of all PBS		
21010Culvigiu2 + 20061	004374 Total		Addition	iono-umer	201210	(376.57	A STATE OF THE STA	393.1009 (5) (a) (b)	A,B,C
- Joseph - Joseph	1 204374 1008	J				(3/6,3/		sasatons fat for fol	CAP/C

Utility Account	New Work Order No.	Funding Project Description	FERC Activity	Category	Month	Addition Amount	WO Description	Statute Section	State or Federal Regularment
376100-Mains - Steel	004382	Roctifier New/Ropi ISRS (N)	Addition	ISRS-Other	201509	4.65	Approved by: Randy Spector on 11/09/2013, This work order in incressing to replace the existing ground bed and restlier originally inhalled on work order 79/0034. The ground was the face of the control		
376 TOO-Mains - 2ree:	004382 Yotal		Addition	isis-ome	201303	4,65		393,1009 (5) (a), (b)	A, B, E
							Approvide by: State Lindsey on 11/20/2013. Replace and elemino 210' -11/4" pile finition of the Christopen in 1925, 120' -2" pile main (no 3100s in 1951), 100' -4" pile main (no 3100s in 1951), 100' -4" pile main (no 320 pile 1950), 100' -4" pile main (no 320' pile 1950), 100' -4" pile main (no 320' pile 1950), 100' -4" pile main (no 140), 80' pile main (no 140),		
376100-Mains - Steel	004396 004396 Total	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	94.48	24	393,1009 (5) (a) (b)	A,B,C
376100-Mains - Steel	004430 004430 Yotal	Rectifier New/Repl ISRS (N)	Addition	ISRS-Other	201509	5,25 5.15		393.1009 (S) (a), (b)	A, B, E
	004430 Total					5.15		393.1009 (5) (8), (6)	A, B, E
376300-Mains - Piastic	004458	Main Replacement - ISRS (SW)	Addition	i\$R\$-Other	201509	17,217,01	Approved by: Stein Holpsomb on 02/05/014, Reglaca 103** 2* PCE, (WOffe Name 4, 1720089, 972** 2* PBS (WOffe Name), 972** 3* PBS (Woffe Name), 972** 4* PBS (Woffe Name), 972** 4* PBS (Woffe Name), 973** 4* PBS (Woffe Name), 973** 4* PBS (Woffe Name), 973** 5* PBS 2* SSE** 4* PBS (Woffe Name), 973** 5* PBS 2* SSE** 5* PBS 2* SSE** 4* PBS (Woffe Name), 973** 5* PBS 2* SSE** 5* PBS 2		
376300-Mains - Plastic	004458	Main Ropiacoment - ISRS (SW)	Addition	ISRS-Other	201510	9,218.3	Approved by: Clave Holosomia on 02/28/2014, Replace 10X1-X** PCG (WOd** None & 7/20080), 6772-X** PSG (WOd** None), 3772-37* PSG (WOd** None, 805442, a 041605), 2011-47* PSG (WOd** None, 805442, a 041605), 2011-47* PSG (WOd** None), 972-47* PSG (WOd** None, 805442, a 041605), 2011-47* PSG (WOd** None), 972-97* PSG (WOd** None),	•	
376300-Mains - Piastic	004458	Main Replacement - ISRS (SW)	Addition	ISRS-Other	201511	6,654.1	Approved by: Gleve Holizomb on G2/20/2014, Replace 193*-2" PGS (WOR's North & 17/20/20), 9772-3" PGS (WOR's		

April	Utility Account	New Work Order No.	Funding Project Description	FERC Activity	Catagory	Month	Addition Amount	WO Description	Statute Section	State or Federal Regulrement
276300-Mains - Plastic   Oxid-St Total   Oxi								720089, 1972 - 2º PSB, (MOR None), 1772 - 12º RSB, (MOR's None, 035042), 8 ArtifatS), 2011-49 PCB, (WOR 6855402) & 4*PCP, (MOR 947505), with 13052 - 19° B. 5809 - 4*P Guide to healings leavies. There have been 20 repatied teaks on the main to be replaced and 4 #3 active teaks (fleat #8 1.24/202), (1-0.15), (1-0.10), 2 1-0.2000), on the main to be replaced. The project will be obenying the pressure from the C-2 to the C-1 System in the series. Pressure Test Information is included in the very corter packet. There are 5 services that vib be tested prior to pressure without Project Location 17 BSI blackward. Main 31 and Walt Ave, Wall Ave N of 12th 51. Pressure System: C-2, MOP: 1.5 PSIG. MADP: 1.5 PSIG. Design 58 PSIG. Test: 100 POID. Pres PEF Force 53 302.4.		
Approach   Company   Com	376300-Mains - Plastic		Main Replacement - ISRS (SW).	Addition	ISRS-Other	201512			JEST MAN WITH THE CO.	123
2004/14 Total   2004/14 Tota								Approved by Galen Shoemaker on 00/00/2013, Replace fuses que lo unqualified parament making fuses. Primacurus sett pay for all material, time and equipment due to this work as they go along. Crear yell indicate on map where they have related diseas. Project Location: Theils and Cover, Pressum Gydens. 0-2001; MOP: 83 away. MADP.	393-1009 (5) (3) (6)	A,B,C
Approvale by Real-Residue (1971). A period (1971). A period (1971). A period (1971). The section (1971) of the period (1971). The section (1971) of the period (1971). The section (1971) of the period (1971) of the perio	376100-Mains - Steel			Addition	ISRS-Other	201509		The state of the s	393,1009 (5) (a) (b)	A.B.C
Addition ISRS-Other 2015/09 (25.12)  Addition IS	376300-Mains - Steel			Addition	iSRS-Other	201509		Approved by: Rob Hinck on 08/21/2013, Abenden 356 - 2n PBS (AVOIrs. Mone, A4070, 46134), 27 - 2n PBG (AVOIrs. 08-0004, 70-4439), 31 - 2n PB (AVOIr ADIO), 57 - 3n PBG (AVOIR ADIO), 57 - 50 - 60 - 60 - 60 - 60 - 60 - 60 - 60	333,1403 (5) (4)	770,2
5007, 21 - 7 PGS WORK BOUND, 180 - 9 PGS WORK BOUND, 501 TOP, 170 - 170 PG WORK BOUND, 501 TOP, 170 PG PG WORK BOUND, 501 PG, 170 PG PG WORK BOUND, 501 PG		004SS9 Total					(37.67		393.1009 (5) (a) (b)	A,8,C
Approved by: Raiph -tenne on GX202013. Replace main with a history of leistage and a System del St said on Leinrighton between Eith and Walnut with 607 - 48 page (P. 2021).  376 100-Mains - Steel  Main Replacement - ISRS (S)  Addition  ISRS-Other  2.37  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 48 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 48 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 48 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 48 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 48 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 48 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 49 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 49 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 49 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 49 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 49 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replace 17 (April 12), 807 - 49 page (P. 2011).  Approved by: Elsew Lindsay on D481/2014, Acodemical Main Replacement. Replacem	376300-Mains - Plastic			Addition	ISRS-Other	201509		5507), 211 - 27 PCG (MOR: 820441), 9807 - 47 PBG (MOR: NONE), 63-1167), 7- 67 PCG (MOR: PA)-444(3), and 1207 - 67 PBG (MOR: NONE) and replace with 2607 - 27 PC, 11682 - 67 PC, and 107 - 87 Thirliffer to clear one (1) sother #5 Leavi (Leak No. 09-0153) due 5020131. There are 23 resparse leaks on this ment, Project Location; Leifferson and Daugharty, Pressure Dystem. C-2, MOP: 1.5 pag; MAOP: 1.5 paig; Design 59 paig; Test: 100 pag; (1875 554 757). Recpand for introduction invalue 6-5-15 per Cindy Pack; - AMM;	1	ARC
2.37  Approved by: Clave Lindsay on 04/01/2014, Accelerated Main Replacement: Replace 17.430 at PSI3, a 250 of PCG, and 11.40 at PC main with 22.007 - 2* PC and 400 - 4* PC. After this wood route is consistent with first 12 clinics in gratients. ORDR 40 at PCC main with 22.007 - 2* PC and 400 - 4* PC. After this wood route is consistent with first 12 clinics in gratients. ORDR 40 at PCC main with 22.007 - 2* PC and 400 - 4* PC. After this wood route is consistent of PCG and 11.40 at PCG and 12.40 at PCG 400 - 4* PCG AND VIOLENTIA AND PCG 400 - 4* PCG AND PCG AND VIOLENTIA AND PCG AND P	376100-Mains - Steel			Addition	ISRS-Other	201509		Approved by: Raiph Jenes on 03/20/2013, Replace main with a history of lenkings and a 5 year ool #3 leak on Lenngton between Ellin and Walnot with 800 * 48-quot; PE, 200 * Zequot; PE, and 270 * 1-1/48-quot; PE, Main Is replace: 430 * 48-quot; PSS (WOR 105); 031 * 38-quot; PSS (WOR 031-331); 200 * 28-quot; PSS (WOR 105); 600 * 48-quot;	395.1003 (3) (4) (9)	A, D, C
17.430° of PSIS, 8,250° of PCS, and 1,40° of PC main with 22,000° -2° PC and 30° -4° PC. After this work order in this work order in this work order in their 2 district rag statistics—0488*4 64 did Retring and 330° (or VICE 14-340). This work will salve fatter and 20° of PSIS 140° of 150° of 1		004619 Tota	The same of the sa				2.37		393.1009 (5) (a) (b)	A,B,C
810,250; 100 - 4m PCS - W/OB 87146, 31 - 4m PC - W/OB 87146; 31 - 4m PC - W/OB 87146; 31 - 4m PC - W/OB 87146; 31 - 4m PC - W/OB 90,007; 51 - 4m PC								17.430 et PAS, 9,255 of PCS, and 1,140 of PC main veh 22,200 - 2° PE and 340 - 4° PCS. And this work order is complete we will raile 2 oldinic fing station. — PCS# 46 et 2 Statistic fing station. — PCS# 40 et 2 Statistic fing statistic—— PCS# 40 et 2 Statistic fing statistic—— PCS# 40 et 2 Statistic fing statistic—— PCS# 40 et 2 Statistic fing statistic final		
376300-Mains - Plastic 004888 Main Replacement - ISRS (S) Addition ISRS-Other 201509 (436.66) (436.66) (436.66) (436.66) (436.66)	376300-Mains - Plastic	45 1000		Addition	ISRS-Other	201509			000 4000 (0) (-) (1)	

			FERC Activity	Category	Month	Amount	WO Description	Statute Section	Requiremen
876300-Mains - Plastic	004889	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509	(103.02)	Approved by: Save Lindsey on DA01/2014. This work order is being written as part of time accelerated math replacement program, We will replace all PBC and PCC from within the C-027 pressure system with 7,977 of 27 PCF. This will allow us to rather the SDRC mind itself the special system of 100 of 33 bits mind like Ridge Blay letter on WOR 14-3450 and DR6 1344 at 90th and Sterling fattler on WOR 14-357), C-027: MDP = MADP = 2 paig., C-500: MDP = 30 paig., MAQP = 44 paig. All services on existing plastic them been choiced for indequate pressure text. There are 11 that will be cut off, pressure letters, CFV installated and 5 that there warps each stilling replaced, pressure trained, CFV installated prior to typing ortol the C-500 pressure system. All existing PC (minh has an adequate pressure text for this pressure increase. Mint to betrades; CFV or 27 PBG (MOS ASST), 1001-12 PBG (MOS ASST), 1001-17 PBG (MOS ASST), 7001-4 PBG (MOS ASST), 1001-4 PBG (MOS		
235200 Major Niewie	00400		adlass	ions only a	201740	(22) 62	Approved by Slava Unitiesy on 64/01/2014. This work order is being written as part of the possiented intell replacement, program, Viel will replace at PDS and PDS man within the C-G27 present system with 77/07 or 27 PE. This will allow us to return the two DDS that the C-G27 present system will replace at PDS and PDS at 30 Min and Stur Ridge by direction the two DDS distail and the program of the C-S00 Min and Stur Ridge Styld represent W08 14-25(9) and CDR 104 at 40th and Sterning (staffs on W08 14-34/57), CG27-MOP * AAGOP ~ 2 peg. C-S00 MOP * 30 peg. MACP * 44 peg., All services on vesting black have been character for elegated pressure test and There are in that will be not off pressure service test. There are in that will be not off pressure intelligent pressure test. (EPV installed print by thing off the C-D00 pressure services. All entire pressure tests, (EPV installed print by thing off the C-D00 pressure services. All entire pressure tests, (EPV installed print by 1181 * + PDS (MOR A-ADD), 100 * - 4* PDG (MOR A-ADD		
376300-Mains - Plastic	004889 004889 Total	Main Replacement - ISRS (S)	Addition	ISRS-Other	201510	(321.09		393,1009 (5] (a) (b)	A,B,C
376300-Mains - Plastic	004949 004949 Total	Main Replacement - ISRS (S)	Addition	ISRS-Other	201509		Approved by, Reigh James on 04.04.72014, Replace and sounder 447 - T pite main (unknown 1920 such adder), 749 - T pite main (unknown 1051 such corest, 507 - T pite main (unknown 1552 such adder) and 50 - T pe entitle (so T0-14.05) by jimsälling 1,325 - T pe man. Valual inspection of this main during resert sets investigations wattern to implementar, (1073)	393.1009 (5) (a) (b)	A.A.C
THE STATE OF THE S	90-13-13 (1002)					10.55	Approved by: Kever Dreskell on 04/07/2014, Replace 3th and 3th PBS due to leak. Lay	220,7002 (2) (2) (2)	na/c
376100-Mains - Steel	004973	Replace bare steel main - safety re	Addition	ISRS-Other	201509	(3.83	10"-Sin thin film and 14"-2in thin film. Work dane by MOE crew.Original JO 7740C & 2740B, year 1949		
	004973 Total					(3.83		393.1009 (5) (a) (b)	A,8,C
376300-Mains - Plastic	004986	Main Replacement - ISRS (N)	Addition	ISRS-Other	201509	126.05	Approved by: Sleve Holoomb on 04/15/2014, ISRS. Replace and abandon a total of 20,000 of oast you main in Sector 0006 with 21,013 of PE. This work will be part of the Cast Inon Replacement Program as mandated by the Missouri Public Services (Commission for Calendar year 2014, New main will like into the C-175 KCLE pressure eyation. New main to openist as 150 paig IAOP. The art of PMOP. The 16 paig IAOP and the Application of the Commission		
STORES WHILE - I MAKE	004986 Total	The state of the s	House	and which	202303	[26.05		393,1009 (S) (a) (b)	A,B,C
376300-Mains - Plastic	005008	Replace bare steet main - safety re	Addition	ISRS-Other	201509	(330.94	Approved by: Sleve Holcamb on 64/14/2014, "MODOT PERMIT REQUIRED" Abendon 1322 - 2" PBS (WOR's: 3088, 18679, 20534, 32-6519), 305 - 4" PBS (WOR's: 3088, 18679, 20534, 32-6519), 305 - 4" PBS (WOR's: 25-6535), 305-3097, and 1007 - 2" PEC (WOR's: 25-6535), 305-3097, and 1007 - 2" PEC (WOR's: 25-6578) and 1949less with 10567 - 2" PEC and 3007 - 4" PEC learn net (1) solid "SLess (Leak No. 1747) and 1949less with 19567 - 2" PEC and 3007 - 4" PEC learn net (1) solid "SLess (Leak No. 1747) and 1949less with 1949 - 1007 - 305 and 1949 - 1007 - 305 and 1949 - 1007 - 305 and 1949 - 1007		
	005008 Total					(330.94		393.1009 (5) (a) (b)	A,B,C