

**BEFORE THE PUBLIC SERVICE COMMISSION
OF THE STATE OF MISSOURI**

In the Matter of an Investigation into)	
The City of New Florence, Missouri's)	
Compliance with the Commission's)	<u>File No. GS-2017-0324</u>
Rules Regarding Natural Gas Safety)	
Found at 4 CSR 240-40.030)	

PROGRESS REPORT

COMES NOW the Staff of the Missouri Public Service Commission, by and through counsel, and in response to the Commission's March 29, 2019 *Order Directing Staff to File Progress Report* (Order), states as follows:

1. The Commission's Order directing Staff to file a progress report no later than June 30, 2019 was issued the same day, March 29, 2019, when Staff filed its fourth progress report in this matter. Staff also filed progress reports on December 28, 2018, June 29, 2018, and December 29, 2017.

2. The Commission opened this investigation docket on June 28, 2017, in response to a Motion to Open Case filed by Staff on June 6, 2017, in which Staff requested the Commission open an investigation into the City of New Florence's (City) compliance with the Commission's gas safety rules.

3. As described in the attached Progress Report Memorandum, page 10, Section C. Current Progress and Status Report, Staff has continued to work with the City regarding its compliance with Commission Rule 4 CSR 240-40.030. The City has made progress toward achieving compliance since Staff's March 29, 2019 progress report; however, there are still some outstanding compliance concerns that the City is working with Staff to resolve. Staff met with the City on June 19, 2019, to discuss, among other

things, the remaining unresolved items from the February 12, 2019 inspection and revisions to the O&M and Emergency Response Plan. Staff understands that the City intends to complete its required actions by the end of June, at which time the City will send a written response to Staff regarding the actions it has completed. Therefore, Staff recommends that the Commission keep this docket open. Staff proposes to provide an additional progress report, or pursue other actions as appropriate, no later than September 30, 2019.

WHEREFORE, Staff submits the attached Progress Report pursuant to the Commission's March 29, 2019 Order, and requests the Commission issue an order directing Staff to file an additional progress report or other filing as appropriate no later than September 30, 2019.

Respectfully submitted,

/s/ Robert S. Berlin

Robert S. Berlin
Deputy Staff Counsel
Missouri Bar No. 51709

Attorney for the Staff of the
Missouri Public Service Commission
P. O. Box 360
Jefferson City, MO 65102
(573) 526-7779 (Telephone)
(573) 751-9285 (Fax)
bob.berlin@psc.mo.gov

CERTIFICATE OF SERVICE

I hereby certify that copies of the foregoing have been mailed, hand-delivered, transmitted by facsimile or electronically served to all counsel of record this 28th day of June, 2019.

/s/ Robert S. Berlin

MEMORANDUM

TO: Missouri Public Service Commission Official Case File
Case No. GS-2017-0324, City of New Florence, Missouri

FROM: Safety Engineering Department
Evan P. Neuner, Technical Specialist II
Jason Dickneite, Utility Engineering Specialist II
Daniel Fitzpatrick, Utility Engineering Specialist III
Brian J. Buchanan, Technical Specialist II
Clinton L. Foster, Utility Engineering Specialist II
Kathleen A. McNelis, PE, Utility Regulatory Engineering Manager

<u>/s/ Kathleen A. McNelis, PE 06/28/2019</u> Commission Staff Division / Date	<u>/s/ Robert S. Berlin 06/28/2019</u> Staff Counsel's Office / Date
--	--

SUBJECT: Staff's Progress Report in the Matter of an Investigation into the City of New Florence, Missouri's Compliance with the Commission's Rules Regarding Natural Gas Safety Found at 4 CSR 240-40.030

DATE: June 28, 2019

On June 6, 2017, the Commission's Staff filed a Motion to open a case to investigate the City of New Florence's compliance with the Commission's rules regarding natural gas safety found at 4 CSR 240-40.030 and to assist Staff in conducting more formal discovery, including but not limited to the issuance of subpoenas, pursuant to the Commission's rules of practice and procedures.¹ The Commission ordered Staff to undertake an investigation of the City of New Florence's compliance with the Commission's rules regarding gas safety.

As discussed more fully in this progress report, the City has made progress towards achieving compliance since Staff's March 29, 2019 progress report. Staff recommends that the Commission keep the case open. Staff intends to continue monitoring for compliance and proposes to provide an additional progress report, or take other action as necessary, no later than September 30, 2019.

A. Background

The Commission has the authority to require each gas utility, including municipal gas systems, to operate its system in a manner that promotes and safeguards the health and safety of

¹ See 4 CSR 240-2.090 and 4 CSR 240-2.100.

its employees, customers and the public.² A municipality that owns any gas plant is subject to the provisions of Section 386.572, RSMo, for violations of natural gas safety laws, rules or orders.³

The City of New Florence, Missouri, owns and operates a municipal gas system under Section 386.310 RSMo, and is subject to the provisions of Section 386.572, RSMo.

The Commission's Safety Engineering Department Staff (Staff) performs routine inspections of the operators of pipelines that are jurisdictional to the Commission to determine compliance with the Commission pipeline safety rules. A number of different types of inspections are performed at routine intervals, including but not limited to natural gas pipeline safety Standard Records and Field inspections⁴, Operations and Maintenance and Emergency Response Plan inspections⁵, Public Awareness Plan and Effectiveness Evaluation inspections⁶, Operator Qualification Program inspections⁷, and Distribution Integrity Management inspections⁸.

² Missouri Revised Statutes Section 386.310.

³ Missouri Revised Statutes Section 386.572.

⁴ Standard Records and Field inspections focus on an operator's actions to comply with the requirements of the operating and maintenance (O&M) provisions of 4 CSR 240-40.030. Staff reviews the operator's compliance with operating and maintenance provisions of 4 CSR 240.030, including but not limited to: (1)(H), (4)(CC), (4)(DD), (4)(EE), (5)(D), (6)(H), (8)(O), (8)(P), (8)(Q), (9)(F), (9)(I), (9)(J), (9)(Q), (9)(K), (9)(L), (9)(M), (9)(N), (9)(U), (9)(V), (10)(D), (10)(E), (10)(F), (10)(G), (10)(J), (11), (12)(C), (12)(D), (12)(H), (12)(I), (12)(J), (12)(K), (12)(M), (12)(N), (12)(N), (12)(N), (12)(O), (12)(P), (12)(S), (13)(C), (13)(D), (13)(L), (13)(M), (13)(N), (13)(R), (13)(S), (13)(T), (13)(U), (13)(V), (13)(W), (13)(X), (13)(Y), (13)(Z), (13)(BB), and (14). Additionally, some of the provisions of 4 CSR 240-40.080 are included in the Standard Records and Field inspections. Staff's goal is to perform Standard Records and Field inspections of each pipeline operator at a frequency of once every two years, with a maximum interval between inspections of 5 years.

⁵ Operations and Maintenance and Emergency Response Plan inspections focus on an operator's plans and procedures for compliance with the operating and maintenance and emergency response provisions of 4 CSR 240-40.030(12)(C) and (12)(J). Staff performs Operations and Maintenance and Emergency Response Plan inspections of each pipeline operator at a maximum interval between inspections of 5 years.

⁶ Public Awareness Plan and Effectiveness Evaluation inspections focus on an operator's plans, procedures and actions for compliance with the public awareness provisions of 4 CSR 240-40.030(12)(K). Staff performs Public Awareness Plan and Effectiveness Evaluation inspections of each pipeline operator at a maximum interval between inspections of 5 years.

⁷ Operator Qualification Program inspections focus on an operator's plans, procedures and actions for compliance with the operator qualification provisions of 4 CSR 240-40.030(12)(D). Staff performs Operator Qualification Program inspections of each pipeline operators at a maximum interval between inspections of 5 years.

⁸ Distribution Integrity Management inspections focus on an operator's plans, procedures and actions for compliance with the distribution integrity management program provisions of 4 CSR 240-40.030(17). Staff performs Distribution Integrity Management inspections of each pipeline operator at a maximum interval between inspections of 5 years.

On July 6, 2016, Staff conducted a natural gas pipeline safety Standard Records and Field inspection of the New Florence municipal gas system. On July 8, 2016, Staff provided an inspection summary letter to the City of New Florence (the “City”) which listed and explained twelve (12) Areas of Probable Violation (“APVs”)⁹ and three (3) Areas of Concern (“ACs”)¹⁰ which Staff found during its July 6, 2016 inspection. The letter requested a response from the City within 20 days describing actions taken or scheduled as a result thereof.

The City provided an update of its progress on July 21, 2016, and a partial response to Staff’s inspection summary providing satisfactory responses to three (3) of the twelve (12) APVs, and one (1) of the three (3) ACs on December 14, 2016.

Staff sent a follow-up letter to the City dated February 6, 2017, requesting a response by February 26, 2017, and met with City personnel on February 23, 2017, to discuss the status of the items contained in the follow-up letter. During this meeting, Staff agreed to allow the City until March 8, 2017 to respond. Having received no response from the City by March 8, 2017, Staff contacted the City and agreed to allow the City until April 1, 2018 to respond to the letter dated February 6, 2017. Having still not received a response from the City, Staff Counsel sent a letter to the City dated May 5, 2017, requesting a response within ten days to the items contained in Staff’s February 6, 2017 follow-up letter. Not receiving a response, Staff filed a motion to open this case. On June 28, 2017, the Commission opened case number GS-2017-0324.

Staff Witness Kathleen A. McNelis, PE

B. History of the Investigation

On June 28, 2017, the Commission opened case number GS-2017-0324. This is the fifth progress report filed since the investigation case was opened.

⁹ Staff defines APV as follows: An Area of Probable Violation (APV) means that based on our inspection findings, there has been a probable violation of either a pipeline safety regulation (4 CSR 240-40.020, .030 or 0.080) or a document provision that is included by reference in the pipeline safety regulations (e.g. American Petroleum Institute’s (API) Recommended Practice (RP) 1162 (incorporated by reference in 49 CFR 192.7 and adopted in subsection 4 CSR 240-40.030(1)(D)).

¹⁰ Staff defines Area of Concern as: An Area of Concern means that while no area of probable violation (see definition of Area of Probable Violation) was found, there are issues that the operator should address to either prevent an area of probable violation in the future, or to improve its safety program.

1. First Progress Report:

On December 29, 2017, Staff filed a progress report discussing the City's progress towards completing the twelve remaining APVs and three remaining ACs from the July 6, 2016, Standard Records and Field inspection. At the time of the December 29, 2017 filing, the City had satisfactorily addressed all of the ACs and all except one of the APVs.

Additionally, during the interim between opening the case on June 28, 2017, and the December 29, 2017 progress report, Staff conducted two additional routine inspections:

- A Public Awareness Plan (PAP) and Public Awareness Effectiveness Evaluation (PAPEE)¹¹ inspection was conducted on September 11, 2017, which resulted in Staff sending an inspection summary to the City on September 12, 2017 listing the actions necessary to meet the regulatory requirements.
- A Distribution Integrity Management Program (DIMP) inspection was conducted on October 30, 2017. In order to comply with the Distribution Integrity Management Program (DIMP) requirements specified in 4 CSR 240-40.030(17), a distribution pipeline operator must among other things re-evaluate threats and risks on its entire pipeline at least every five years¹². The City's initial DIMP evaluation of threats and risks was provided with its initial DIMP Plan, dated August 2, 2011. The City of New Florence had not conducted the required re-evaluation at the time of Staff's inspection. Staff sent an inspection summary to the City on November 7, 2017, stating among other things that the City must perform a complete program re-evaluation as required by 4 CSR 240-40.030(17)(D)6. and provide a copy of the results to Staff. Staff requested a response within 60 days, which would have been January 6, 2018, after the date of the December 29, 2017 progress report.

¹¹ The regulatory requirements are in 4 CSR 240-40.030(12)(K).

¹² 4 CSR 240-40.030(17)(D)6.

- An Operator Qualification (OQ) Program inspection was conducted on October 31, 2017. Staff sent an inspection summary to the City on November 6, 2017. Staff requested a response within 30 days; however, no response was received by the time of the December 29, 2017 progress report.

2. Second Progress Report:

On June 29, 2018, Staff filed a progress report discussing the City's progress towards completing the twelve remaining APVs and three remaining ACs from the July 6, 2016, Standard Records and Field inspection, and the unresolved inspection items from the DIMP and OQ inspections.

- With respect to the Standard Records and Field inspection, the City had made progress but had not fully complied with the requirements of the remaining APV of 4 CSR 240-40.030(12)(D), which prescribes the minimum qualifications for person performing each covered task¹³ that an operator performs on its pipelines.
- With respect to the PAP and PAPEE inspection, the City had made progress, but had not yet completed all of the required effectiveness evaluations. Natural gas pipeline operators in Missouri are required to follow the requirements outlined in 4 CSR 240-40.030(12)(K). 4 CSR 240-40.030(12)(K)2. requires that the operator must follow the general program recommendations, including baseline and supplemental requirements of the American Petroleum Institute (API) Recommended Practice (RP) 1162. One of the requirements in the API RP 1162 is to conduct periodic PAP effectiveness evaluations at a frequency of no more than 4 years apart. The City had made progress towards completion of this task, but had not yet completed all of the required effectiveness evaluations.

¹³ 4 CSR 240-40.030(12)(D)1. B. defines a covered task as an activity, identified by the operator that is 1. Performed on a pipeline facility, 2. Is an operations, maintenance or emergency-response task, 3. Is performed as a requirement of this rule and 4. Affects the operations or integrity of the pipeline.

Staff provided the City with details on the remaining requirements, in a letter dated May 11, 2018 and discussed the letter with the City during Staff's June 14, 2018 on-site follow-up with the City.

- With respect to the DIMP inspection, the City provided a revised DIMP plan to Staff on June 11, 2018. Staff reviewed the plan and found that it did not satisfy all of the requirements of 4 CSR 240-40.030(17)(D). Staff met with the City on June 14, 2018 to discuss the required amendments. Staff sent a follow-up letter to the City describing the required amendments on June 21, 2018, and requested the City to provide a revised plan by July 30, 2018.
- With respect to the OQ inspection, the City did not provide a response. Staff provided the City with the details on the remaining requirements in a letter dated May 11, 2018 and discussed them with the City during Staff's June 14, 2018 on-site follow-up with the City.

3. Third Progress Report:

On December 28, 2018, Staff filed a progress report addressing certain changes in City personnel who are involved with operation of the natural gas system, and the City's progress on unresolved inspection items.

With respect to personnel changes:

On August 7, 2018, the Mayor of the City of New Florence (City) informed Staff that the City Superintendent had been replaced. The Mayor stated the new City Superintendent would be in contact with Staff regarding the unresolved inspection items.

On August 17, 2018, Staff contacted the new City Superintendent by telephone to set up a meeting. It was agreed that Staff would visit either August 22, or 23, 2018. During the phone call, the City Superintendent mentioned that the City had some turnover with its mayor. On August 20, 2018, Staff called the City Superintendent to confirm the meeting the following week. The City Superintendent informed Staff he planned to terminate his employment with the City effective sometime during the same week.

On August 21, 2018, Staff was informed by the City Clerk that the City Superintendent had terminated his employment with the City. Staff was informed that the City of Hermann would be operating the natural gas system for the City of New Florence.

In the past, the City of New Florence retained the City of Hermann as a contractor to perform certain covered tasks on the City of New Florence's natural gas system, including certain tasks that the New Florence City Superintendent was not qualified to perform. Apart from this work, the City of Hermann operates natural gas systems in the cities of Hermann and Middletown, Missouri, and provides natural gas to the City of New Florence. There were no unresolved findings as the result of Staff's most recent Standard Records and Field Inspection, and Operator Qualification Program Inspection conducted with the City of Hermann.

Staff contacted the new Mayor Pro Tempore of the City of New Florence on August 21, 2018. The Mayor Pro Tempore stated that the City of New Florence intended to contact the City of Hermann to let it know of the situation in the City so that it will be prepared to respond in the event of an emergency.

On September 13, 2018, Staff contacted the City of New Florence City Clerk to inquire about the status of the operation of the City's natural gas system. The City Clerk informed Staff that a new City Superintendent was in the City's employ, but was not yet prepared to take over the City's natural gas system. The City stated that the City of Hermann had been retained for any emergency work necessary on the system.

On November 1, 2018, Staff met with the City of New Florence's new City Superintendent. Staff discussed operator qualification requirements for natural gas operators in the State of Missouri. Staff also informed the City Superintendent that the City was due for a Standard Records and Field inspection, and that someone from Staff would be in contact to set up a date for the inspection.

With respect to unresolved inspection items:

- The remaining APV from the July 6, 2016 Standard Records and Field inspection pertained to the qualification of the City's former superintendent to perform specific covered tasks on the pipeline. Since that individual was no longer employed by the City, Staff no longer found this issue relevant to this investigation. Staff stated that it planned to address any new or continuing issues with the new City Superintendent. Staff then scheduled a Standard Records and Field inspection of the City of New Florence for January 2, 2019, with the new City Superintendent.
- No additional progress was made by the City on its PAP and PAPEE inspection findings. Staff intended to renew its efforts to ensure compliance with the requirements of 4 CSR 240-40.030(12)(K) following the January Standard Records and Field inspection.
- No additional progress was made by the City on its DIMP inspection findings. Staff intended to renew its efforts to ensure compliance with the requirements of 4 CSR 240-40.030(17) following the January Standard Records and Field inspection.
- No additional progress was made by the City on its OQ inspection findings. Staff intended to renew its efforts to ensure compliance with the requirements of 4 CSR 240-40.030(12)(D) following the January Standard Records and Field inspection.

Additionally, during the interim period between opening the June 29, 2018 and December 28, 2018 Progress Reports, Staff conducted one additional routine inspection. Staff conducted an Operations and Maintenance (O&M) and Emergency Response Plan inspection on December 18, 2018 with the New City Superintendent.

4. Fourth Progress Report:

On March 29, 2019, Staff filed a progress report addressing the City's progress on unresolved inspection items:

- A Standard Records and Field inspection was conducted on February 12, 2019. An inspection summary letter was provided to the City on February 25, 2019 describing 15 APVs and one AC. Staff requested a response from the City within 30 days of the February 25, 2019 letter, indicating any actions that have been taken or will be scheduled as a result of the Staff's comments. The City sent a response dated March 11, 2019 to Staff's inspection summary. At the time of the fourth progress report filing, Staff had not yet completed its review of the City's response.
- An inspection of the City's O&M and Emergency Response program plan was conducted December 18, 2018. Staff provided the City with an inspection summary letter on January 3, 2019, describing the revisions the City needed to make to achieve compliance with the requirements of 4 CSR 240-40.030(12)(C) and (12)(J). Staff requested a response within 30 days indicating any actions that have been taken or will be scheduled as a result of the inspection and an estimated schedule for completion of scheduled actions. The City sent a response to Staff's inspection summary dated March 11, 2019. The response indicated that the City was working on revisions to the O&M and Emergency Response Plan and would provide a copy of it to Staff when revisions were completed.
- The City had completed some but not all actions identified by Staff's September 11, 2017 PAP and PAPEE inspection to comply with the requirements of 4 CSR 240-40.030(12)(K). Staff met with the City on March 11, 2019, to discuss the actions required to satisfy the requirements of 4 CSR 240-40.030(12)(K). The City stated that it planned to begin taking

actions to complete compliance during March 2019, and anticipated completion by the end of April 2019.

- The City had not made any progress towards addressing deficiencies noted in Staff's November 6, 2017 inspection summary for the October 31, 2017 OQ inspection. Staff met with the City on March 11, 2019, to discuss the actions required to satisfy the requirements of 4 CSR 240-40.030(12)(D). Staff requested that the City provide a written response to its November 6, 2017 letter outlining a plan to address remaining items from the inspection.
- The City had not made any additional progress towards addressing the deficiencies noted in Staff's November 7, 2017 inspection summary for the DIMP inspection conducted on October 30, 2017. Staff met with the City on March 11, 2019, to discuss the actions required to satisfy the requirements of 4 CSR 240-40.030(17). Staff requested that the City provide a written response to its July 30, 2018, letter outlining a plan to address remaining items from the inspection.

Staff Witness Clinton L. Foster, and

Staff Witness Kathleen A. McNelis, PE

C. Current Progress and Status Report

The City's progress and current status with respect to each unresolved inspection is described below.

1. Standard Records and Field Inspection

After reviewing the City's March 11, 2019 response to Staff's inspection summary letter, Staff found that the City's reply as it pertained to 11 of the APVs (APV numbered 1, 3, 5, 7, 8, 9, 10, 12, 13, 14, and 15 in the inspection summary) was satisfactory as written on the condition that the proposed actions are completed as scheduled and the proposed procedures are implemented. The reply as it pertained to 4 of the APVs (numbered 2, 4, 6, and 11) and AC 1 required further discussion. Staff provided a follow-up letter dated April 1, 2019, which provided

additional comments describing the actions required for compliance with the five unresolved inspection items.

Staff requested that the City review the additional comments attached to its April 1, 2019 follow-up letter and respond to Staff within 20 days of the date of the letter, describing any actions that have been taken or will be scheduled as a result of the attached comments.

Staff has not yet received a response from the City regarding the unresolved items from the February 12, 2019 inspection.

Staff met with the City on June 19, 2019 to discuss the remaining unresolved items from the February 12, 2019 inspection. The City provided documentation that it had successfully resolved three of the four APVs and the one AC. Staff and the City discussed the one remaining APV. Staff understands that the City intends to take action to complete required actions by the end of June. The City will then send a written response to Staff with completion information.

Staff Witness Jason Dickneite, and

Staff Witness Evan P. Neuner

2. Operations and Maintenance and Emergency Response Plan Inspection

As indicated in the fourth progress report, the City sent a response to Staff's inspection summary dated March 11, 2019. The response indicated that the City was working on revisions to the O&M and Emergency Response Plan and would provide a copy to Staff when revisions are completed.

Staff has not yet received a response from the City regarding the unresolved items from the January 3, 2019 inspection.

Staff had a meeting the City on June 19, 2019, to discuss revisions to the O&M and Emergency Response Plan. During this meeting, the City stated that it is still working on unresolved items and stated the plan will be completed by September 30, 2019.

Staff Witness Daniel Fitzpatrick

3. Public Awareness Plan and Effectiveness Evaluation Inspection

A Public Awareness Plan (PAP) and Public Awareness Plan Effectiveness Evaluation (PAPEE)¹⁴ inspection was conducted on September 11, 2017, and an inspection summary was sent to the City on September 12, 2017. The City has completed some but not all actions required by 4 CSR 240-40.030(12)(K).

Staff met with the City on March 11, 2019, to discuss the actions required to satisfy the requirements of 4 CSR 240-40.030(12)(K). The City stated that it planned to begin taking actions to complete compliance during March, 2019, and anticipated completion by the end of April 2019.

On May 30, 2019, the City indicated that it intended to take additional actions to comply with outstanding requirements in the next few weeks. As of the June 19, 2019 visit by Staff, the City had completed the Emergency and Public Officials survey's and an effectiveness evaluation based on the survey results. To date the City has completed the effectiveness evaluations of its public awareness messages to three of the four stakeholder groups: Affected Public, Emergency Officials and Public Officials. The City still needs to complete the effectiveness evaluation of its public awareness messages to Excavators. The City stated this would be completed by the end of June.

Staff Witness Brian J. Buchanan

4. Operator Qualification Program Inspection

An Operator Qualification (OQ) program inspection was conducted on October 31, 2017. An inspection summary was sent to the City on November 6, 2017. Staff requested a response within 30 days, and has not yet received a response.

Staff met with the City on March 11, 2019, to discuss the actions required to satisfy the requirements of 4 CSR 240-40.030(12)(D). As of the March 11, 2019 meeting, the City had made none of the required plan amendments as requested in Staff's inspection summary sent to

¹⁴ Regulatory requirements are in 4 CSR 240-40.030(12)(K).

the City on November 6, 2017. Staff requested that the City provide a written response to its November 6, 2017 letter outlining a plan to address remaining items from the inspection.

Staff has not yet received a response.

Staff met with the City on June 19, 2019, to discuss the progress on the OQ Program Inspection. The City has placed priority on completion of the O&M and Emergency Response Plan. The City stated that it would address the inspection items related to the OQ Program following its completion of revisions to the O&M and Emergency Response Plan.

Staff Witness Clinton L. Foster

5. Distribution Integrity Management Program Inspection

A DIMP inspection was conducted on October 30, 2017. An inspection summary was sent to the City on November 7, 2017. The City provided a revised distribution integrity management program plan on June 11, 2018. The revised plan does not satisfy all of the requirements of 4 CSR 240-40.030(17)(D). Staff met with the City on June 14, 2018, to discuss the required amendments. A follow-up letter was sent detailing these requirements on June 21, 2018, and requested a revised plan by July 30, 2018. The City did not provide a response.

Staff met with the City on March 11, 2019, to discuss the actions required to satisfy the requirements of 4 CSR 240-40.030(17). Staff requested that the City provide a written response to its July 30, 2018, letter outlining a plan to address remaining items from the inspection.

Staff has not yet received a response.

Staff met with the City on June 19, 2019, to discuss the progress on the Distribution Integrity Management Program Inspection. The City has placed priority on completion of the O&M and Emergency Response Plan. The City stated that it would address inspection items related to its DIMP program following its completion of revisions to the O&M and Emergency Response Plan.


Staff Witness Kathleen A. McNelis, PE


D. Conclusions and Recommendations

Provided that the City of New Florence continues to use only qualified individuals to operate its natural gas system, Staff's opinion is that there are no immediate safety concerns regarding unqualified operation of a gas system. However, it is imperative that the City of New Florence continue to take actions necessary to come into full compliance with the Commission's natural gas pipeline safety regulations.

Due to the City's personnel changes (See Section B History of the Investigation, Part 3. Third Progress Report), in August 2018, the City's current Superintendent was not a party to Staff's previous investigations. The City has made progress towards achieving compliance since Staff's previous progress report.

Staff recommends that the Commission keep the case open. Staff intends to continue monitoring for compliance and proposes to provide an additional progress report, or take other action as necessary, no later than September 30, 2019.





DIANNA L. VAUGHT
Notary Public - Notary Seal
State of Missouri
Commissioned for Cole County
My Commission Expires: June 28, 2019
Commission Number: 15207377

