One Ameren Plaza 1901 Chouteau Avenue PO Box 66149 St. Louis, MO 63166-6149 314.621.3222

314.554.2237 314.554.4014 (fax) JJCOOK@AMEREN.COM

September 14, 2000

VIA FEDERAL EXPRESS



Mr. Dale Hardy Roberts Secretary/Chief Regulatory Law Judge Missouri Public Service Commission P. O. Box 360 Jefferson City, MO 65102

Re: MPSC Case No. EC-2000-63

Dear Mr. Roberts:

Enclosed for filing on behalf of Union Electric Company, d/b/a AmerenUE, in the above matter, please find an original and eight (8) copies of its **Final Response** to Commission Ordered Status Report.

Kindly acknowledge receipt of this filing by stamping a copy of the enclosed letter and returning it to me in the enclosed self-addressed envelope.

Very truly yours,

∕Jamés J. Cook

Managing Associate General Counsel

JJC/db

Enclosures

cc: Ms. Shelly Register

Parties on Attached Service List

13077

BEFORE THE PUBLIC SERVICE COMMISSION STATE OF MISSOURI

Frank E. Dilley, et al.,

Complainants,

v.

Union Electric Company,
d/b/a AmerenUE

Respondent

Service Company,
Case No. EC-2000-63

UNION ELECTRIC COMPANY'S FINAL RESPONSE

Comes now Union Electric Company ("Union Electric," "UE" or "the Company") in further response to the Commission's directives in this matter.

By letter dated June 19, 2000, the Company submitted its "Third Response to Commission Ordered Status Report of Current and Planned Projects for the Spring of 2000." In that filing, the Company reported that all projects in this area have been completed and that it would provide a final report to the Commission by September 15, 2000.

On June 19, 2000, the Commission filed its Order Directing Filing of Company's status report showing the performance of its Brumley area distribution system during the summer season. This report "shall note the time, date, duration, and cause of every service outage in the area served by the Brumley Substation between July 1, 2000, and September 1, 2000."

Attached hereto is Attachment 1, an updated version of the status report previously submitted to the Commission. This report includes the information requested in the Commission's July 19th Order.

WHEREFORE, Union Electric Company hereby submits the attached report for consideration by the Commission.

Dated: September 14, 2000

Respectfully submitted,

AmerenUE

Bv:

James J. Cook, MBE #22697

Ameren Services Company

One Ameren Plaza

1901 Chouteau Avenue

P. O. Box 66149 (MC 1310)

St. Louis, MO 63166-6149

314-554-2237

314-554-4014 (fax)

jjcook@ameren.com

September 13, 2000

Brumley Substation Area Update July 1 –September 1, 2000

This report is divided as follows:

- A. Projected peak loading on feeders 129-051 and 129-052 for the summer of 2000;
- B. Actual peak loads on feeders 129-051 and 129-052 for the period of 7/1/00 through 9/1/00 and the feeder peaks from summer 1999;
- C. Extended Outage History for feeders 129-051 and 129-052 for the period 7/1/00 through 9/1/00;
- D. Comments on specific outages experienced during the 7/1/00 through 9/1/00 time period;
- E. Ongoing area projects.

A. Project loading on feeders 129-051 and 129-052 for the summer of 2000;

The projected peak loadings (in amperes) for the two circuits were as follows:

Feeder	Phase A	Phase B	Phase C	
129-051	157	145	199	
129-052	77	83	33	

These predictions indicate the projected loads for the Brumley Substation distribution feeders after the completion of all planned phase cuts and feeder diversions. All such projects were completed prior to the summer 2000 peak. Note that the Feeder 129-051 Phase A projections have been modified from the June 19,2000 Update.

B. Actual peak loads on feeders 129-051 and 129-052 for the period of 7/1/00 through 9/1/00;

Feeder	Phase A	Phase B	Phase C	
129-051	126	120	166	
129-052	84	72	20	

The peak occurred at 6 p.m. on Thursday, August 31, 2000. The maximum ambient temperature as measured at Bagnell Dam was 103 degrees Fahrenheit.

The peak loads on the same feeders during the summer of 1999 occurred on Thursday, July 29 at approximately the same time of 6p.m. The maximum ambient temperature as measured at Bagnell Dam was 102 degrees Fahrenheit.

Feeder	Phase A	Phase B	Phase C	
129-051	212	128	180	
129-052	20	90	48	

C. Extended Outage History for feeders 129-051 and 129-052 for the period 7/1/00 through 9/1/00

REVIEW OF PRIOR ORDERS FROM 07/01/00 TO 09/01/00 FEEDER 129051 EXTENDED OUTAGES

DATE	TIME DIST	SUB	FEEDER	KV	TP CAUSE	$\mathbf{W}\mathbf{H}$	IR/	MIN	CUST	ORDER NO
07/15/00	08:10 LAKE	BRUM	129-051	12	DO TREES	T	4	40	38	001970135
	08:10 LAKE	BRUM	129-051	12	GO TREES	T	2	50	13	001970310
07/17/00	07:01 LAKE	BRUM	129-051	12	TO OH PROB	T	4	54	1	001992124
	07:11 LAKE	BRUM	129-051	12	TO OH PROB	T	4	44	1	001992132
07/30/00	16:12 LAKE	BRUM	129-051	12	TO OH PROB	С	4	48	1	002120294
07/31/00	12:59 LAKE	BRUM	129-051	12	TO OH PROB	C	5	31	1	002131723
08/07/00	05:48 LAKE	BRUM	129-051	12	TO OH PROB	Τ .	4	42	1	002201142
08/18/00	11:26 LAKE	BRUM	129-051	12	DO TREES	C	4	49	23	002315640
	16:15 LAKE	BRUM	129-051	12	GO TREES	C	2	55	6	002317031

REVIEW OF PRIOR ORDERS FROM 07/01/00 TO 09/01/00 FEEDER 129051 EXTENDED OUTAGES

DATE	TIME DIST	SUB	FEEDER K	ζV	TP CAUSE	W 3	HR/N	MIN	CUST	ORDER NO
08/31/00	00:25 LAKE	BRUM	1 129-051	12	MO PRE-ARN	NG (0 0	00	1	002440043
	08:25 LAKE	BRUM	I 129-051	12	TO UNKNOV	VN (1	35	1	002441316

TOTAL for Feeder 129-051

87

REVIEW OF PRIOR ORDERS FROM 07/01/00 TO 09/01/00 FEEDER 129052 EXTENDED OUTAGES

DATE	TIME DIST	SUB	FEEDER	KV	TP CAUSE	W	HR/MI	N CUST	ORDER NO
07/11/00	21:57 LAKE	BRUN	1 129-052	12	DO UNKNOW	n R	15 03	3 18	001933526
08/06/00	20:10 LAKE	BRUN	1 129-052	12	DO UNKNOW	N C	2 30	38	002190896
08/08/00) 14:13 LAKE	BRUN	1 129-052	12	DO TREES	С	3 3	7 38	002214339
08/18/00) 14:38 LAKE	BRUN	1 129-052	12	DO UNKNOW	N C	1 52	2 9	002316597
08/27/00	07:26 LAKE	BRUN	129-052	12	TO OTHER	T	1 34	1	002400371

TOTAL for Feeder 129-052

104

Legend on extended outage order summaries

TP Order Types DO Device Outage GO Grouped Outage MO Momentary Outage TO Transformer Outage W Weather Codes

C Calm

- R Rain
- T Thunderstorms

D. Comments on specific outages experienced during the 7/1/00 through 9/1/00 time period;

Sub Transmission (34,500 volt) outages

On Wednesday, August 30, 2000 at 4:47 p.m., a crossarm supporting the 34kv subtransmission circuit that supplies the Brumley Substation and Equiline (Shell) Customer Substation broke. One of the phases of the 34,500-volt sub transmission made contact with feeder 129-051 phase C. Some customers supplied from the distribution system experienced a momentary outage and a temporary overvoltage condition. The Equiline (Shell) Customer Substation experienced a 9 hour and 10 minute outage.

Distribution (12,470 volt) outages

Momentary outages of the distribution system are not documented.

There were three recorded extended outages to customers located on Feeder 129-051 Phase A. All three were transformer outages to individual customers. These outages occurred on 7/17/00 (Order 001992124), on 7/31/00 (Order 002131723) and on 8/7/00 (Order 002201142).

E. Ongoing area projects

Forty-three poles located on Highway C were recommended for replacement. Those poles have been scheduled to be replaced no latter than December 31, 2001;

Keethtown Distribution Substation is scheduled to be placed in service during the summer of 2001. This will be a 1.5-mva substation to be located on Highway U. The substation will provide up to 70 amperes per phase of relief for feeders 129 051 Phase C and 129-052 Phase B. Feeder reliability in this area will also be increased due to the resulting shorter feeder lengths.

CERTIFICATE OF SERVICE

MPSC Case No. EC-2000-63

I hereby certify that a copy of the foregoing was served via first-class, U.S. mail, postage prepaid, on this 14th day of September, 2000, on the following parties of record:

Office of the Public Counsel	General Counsel
P. O. Box 7800	Missouri Public Service Commission
Jefferson City, MO 65102	P. O. Box 360
	Jefferson City, MO 65102
Mr. Frank E. Dilley	Ms. Stephanie F. Myers
312 Highway C	509 Highway C
Ulman, MO 65083	Ulman, MO 65083
Mr. Dustin Myers	Mr. James A. Pankey
509 Highway C	356 Highway C
Ulman, MO 65083	Ulman, MO 65083
Mr. Quentin Lupardus	Mr. Steve Byrd
P. O. Box 385	P. O. Box 403
Ulman, MO 65083	Ulman, MO 65083
Mr. Donald D. Patterson	Mr. William W. Patterson
P. O. Box 363	199 Hwy C
349 Highway C	Tuscumbia, MO 65082
Ulman, MO 65083	, i
Mr. Joseph Alieksaites	Ms. Mildred Alieksaites
217 County Side Road	9 Jackson Cemetery Road
Ulman, MO 65083	Ulman, MO 65083
James & Rita Jefferies	David & Brenda Haley
#31 Timber Trails Drive	216 Patterson Loop
Brumley, MO 65017	Ulman, MO 65083
Paul & Rebecca Young	Ruby Otto
Ulman, MO 65083	69 Timber Trails Drive
	Brumley, MO 65017
Ms. Sharon K. Abbott	Mr. Robert J. Sparrow
21 Opal Drive	26 Howell Loop
Ulman, MO 65083	Ulman, MO 65083
Ms. Pauline Hensley	Mr. Douglas Zeigenbein
217 Howell Loop	324 Brushy Fork Road
Ulman, MO 65083	Ulman, MO 65083
Mr. Paul Patterson	Mr. Jimmy Myers
147 Redbird Lane	373 Highway C
Ulman, MO 65083	Ulman, MO 65083
Mr. Eddie Reed	Kenneth & Marilyn Carico
158 Hawken Cemetery Road	141 Highway JJ
Ulman, MO 65083	Ulman, MO 65083
Mr. Lloyd E. Reed	Mr. Randolph E. Shipp
154 Hawken Cemetery Road	264 Highway JJ
Ulman, MO 65083	Ulman, MO 65083

Deitra Brouk	James M. Myers
147 Dog Creek School Road	361 Highway C
Ulman, MO 65083	Ulman, MO 65083
Ms. Tammy Byrd	Ms. Georgette A. Patterson
P. O. Box 403	Box 396
Ulman, MO 65083	Ulman, MO 65083
Mr. Steven D. Patterson	Mr. Marshall E. Humphreys, III
107 Sand Rock Road	109 Redbird Lane
Ulman, MO 65083	Ulman, MO 65083
Buster McGowin	James & Melissa Carico
#47 Highway JJ	823 Pea Ridge Road
Ulman, MO 65083	Brumley, MO 65017
Mr. Lonnie Jeffries	Mr. John J. Williams, II
#3 Timber Trails Drive	154 Keyes School Road
Brumley, MO 65017	Ulman, MO 65083
Joann Jefferies	Ms. Myna McGowin
22 County Side Road	#47 Highway JJ
Ulman, MO 65083-9603	Ulman, MO 65083
James Aleksaites	Ms. Betty J. Drace
436 Highway C	326 Highway C
Ulman, MO 65083	Ulman, MO 65083
Lucretia Drace	Mr. Gene S. Bax
326 Highway C	P. O. Box 386
Ulman, MO 65083	Ulman, MO 65083
Mr. Donald Hibler	Mr. Herbert Nixdorf
156 Ulman Ridge Road	332 Highway C
Tuscumbia, MO 65082	Ulman, MO 65083
Ms. Linda Sue Nixdorf	
328 Highway C	
Ulman, MO 65083	

James J. Cook