

Order: TGCR 100000511102 REPAIR SHOP HEATERS

REPAIR SHOP HEATERS
THIS WORK ORDER IS A RESULT OF THE NERC BUILDING HEATERS CHECK PM.
2 HEATERS IN SHOP NEED ATTENTION:
NW CORNER BY COMPRESSOR
WEST WALL SOUTH END
Info for work order provided by R.Lewis. 10/12/2025
Adjusted thermostats and heaters started and heated properly. Perhaps it was not cool enough on the 12th? 10/26/2025 ROL

Sys.Status: CLSD JBFI NMAT PRC SETC RCOM

HeaderData Operations Components Costs Partner Objects Additional Data Location Planning Control Enhancement

Person responsible

PlannerGrp: 020 / : 5165 LU Empire Thermal
Mn.wk.ctr: THERMAL / : 5165 Empire Thermal Riverton
Person respons.:
Notifctn: 100000919976
Costs: 0.00 USD
PMActType: 014 Repair
SystCond.:
Address:

Dates

Bsc start: 10/14/2025 05:40 Priority: 3 30 Days
Basic fin.: 11/26/2025 05:40 Revision:

Reference object

Func. Loc.: GN-T-RIVR-BOPL-STRU Structures & Improvements
Equipment: 21027150 Maintenance Building

Notification is completed -> can only be displayed View Details

Save Cancel