

Order: TGCR 0000522134

STG BUILDING HEATER 1001

STG BUILDING HEATER 1001

UNIT TRIPPED MAIN BREAKER. STARTER / CONTACTORS BAD. REPLACED WITH SOLID STATE. 11/5/2025 AB

Sys.Status: CLSD JBFI NMAT PRC SETC

RCOM

HeaderData Operations Components Costs Partner Objects Additional Data Location Planning Control Enhancement

Person responsible

PlannerGrp: 020 / : 5165 LU Empire Thermal

Notifctr: 100000935562

Mn.wk.ct: THERMAL / : 5165 Empire Thermal Riverton

Costs: 0.00 USD

Person respons.: [Empty field]

PMActType: 014 Repair

SystCond.: [Empty field]

Address: [Empty field]

Dates

Bsc start: 11/05/2025 12:55

Priority: 3 30 Days

Basic fin.: 12/22/2025 12:55

Revision: [Empty field]

Reference object

Func. Loc.: GN-T-RIVR-PB03-ST01-... Structures

Equipment: 21025542 UNIT HEATER