

APPENDIX B: Figures




Figure 1: General location of the June 26, 2023 natural gas incident at the Craig-Hurt Funeral Home garage in Mountain Grove, Missouri, Map View (**Source:** Google Maps; text box and arrow added by Staff)




Figure 2: Approximate location of the June 26, 2023 natural gas incident at the Craig-Hurt Funeral Home garage in Mountain Grove, Missouri and the approximate location of damage to Summit's 2-inch diameter plastic natural gas main, Map View (**Source:** Google Maps; text boxes and arrows added by Staff)



Figure 3: Satellite view showing the approximate location of the June 26, 2023 natural gas incident at the Craig-Hurt Funeral Home garage in Mountain Grove, Missouri, and the approximate location of damage to Summit's 2-inch diameter plastic natural gas main, Map View (**Source:** Google Maps; text boxes and arrows added by Staff)



Figure 4: Photograph of Summit's 2-inch diameter plastic natural gas main and tracer wire that was damaged by A&A Cable (contractor working for MasTec) on June 26, 2023 during a directional bore operation. The damage location occurred just south of W 4th Street in an alley between N Maple Avenue and N Main Avenue in Mountain Grove, Missouri. (Source: Summit Photograph)



Figure 5: Photograph of Summit's 2-inch diameter plastic natural gas main that was damaged by A&A Cable

on June 26, 2023 in Mountain Grove, Missouri. (Source SNGMO)



Figure 6: Photograph showing view of Summit’s 2-inch diameter plastic natural gas main, exposed where the damage occurred. “DAMAGE” cones were placed above the located natural gas main, and a “MARK” cone was placed above locate lines painted on the ground. (Source: SNGMO)



Figure 7: Photograph of SNGMO locating its' natural gas main following the incident to verify the accuracy of previously painted locate lines at the location of the incident. (Source: SNGMO)